

Dell™ PowerConnect™  
7024/7048/7024P/7048P/7024F/7048R/  
7048R-RA/8024/8024F/M6220/M6348/M8024/M8024-k

# PowerConnect 5.1.12.2 Firmware Release Notes



**Date: Dec 2017**  
**System Firmware Version 5.1.12.2**

**Information in this document is subject to change without notice.**

**© 2003 – 2017 Dell Inc. All rights reserved.**

Reproduction in any manner whatsoever without the written permission of Dell Inc. is strictly forbidden.

Trademarks used in this text: Dell, the DELL logo and PowerConnect are trademarks of Dell Inc; Intel and Pentium are registered trademarks and Celeron is a trademark of Intel Corporation; Microsoft and Windows are registered trademarks of Microsoft Corporation.

Other trademarks and trade names may be used in this document to refer to either the entity claiming the marks and names or their products. Dell Inc. disclaims any proprietary interest in trademarks and trade names other than its own. All rights reserved. This document may not, in whole or in part, be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form without the prior written consent of Dell. Dell reserves the right to make changes without further notice to any products or specifications referred to herein to improve reliability, functionality or design.

Reproduction, adaptation or translation without prior written permission is prohibited, except as allowed under the copyright laws.

## *Table of Contents*

<b>Introduction</b>	<b>1</b>
<b>Global Support</b>	<b>1</b>
<b>Firmware Specifications</b>	<b>1</b>
<b>Firmware Upgrade</b>	<b>2</b>
<b>Firmware Downgrade</b>	<b>3</b>
<b>Boot Code Downgrade</b>	<b>3</b>
<b>Hardware Supported</b>	<b>3</b>
<b>Support Matrix</b>	<b>4</b>
<b>Supported Firmware Functionality</b>	<b>5</b>
<b>Added Functionality in this Release</b>	<b>6</b>
<b>Changed Functionality in this Release</b>	<b>14</b>
<b>Issues Resolved</b>	<b>22</b>
<b>CLI Reference Guide Updates</b>	<b>68</b>
<b>User's Configuration Guide Updates</b>	<b>74</b>
<b>Known Issues</b>	<b>78</b>
<b>Known Restrictions and Limitations</b>	<b>89</b>
<b>System – 5.0.1.3</b>	<b>91</b>
<b>System – 5.0.0.4</b>	<b>91</b>
<b>Management – 4.2.1.3</b>	<b>92</b>
<b>Layer 2 – 4.2.0.4</b>	<b>93</b>
<b>Layer 3 – 4.2.0.4</b>	<b>94</b>
<b>Management – 4.2.0.4</b>	<b>95</b>
<b>Data Center – 4.2.0.4</b>	<b>95</b>
<b>End of Release Notes</b>	<b>96</b>

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Introduction

This document provides specific information for the Dell PowerConnect 7024/7048/7024P/7048P/7024F/7048R/7048R-RA/8024/8024F/M6220/M6348/M8024/M8024-k switches firmware version 5.1.12.2.

It is recommended that this release note be thoroughly reviewed prior to installing or upgrading of this product.

## Global Support

For information regarding the latest available firmware, release note revisions, or additional assistance, please visit [support.dell.com](http://support.dell.com).


## Firmware Specifications


### Firmware Version


Firmware Image Name	Version Number	Release Date
PCM6220v5.1.12.2.stk	5.1.12.2	December 2017
PC7000_M6348v5.1.12.2.stk	5.1.12.2	December 2017
PC8024v5.1.12.2.stk	5.1.12.2	December 2017
PCM8024v5.1.12.2.stk	5.1.12.2	December 2017
PCM8024kv5.1.12.2.stk	5.1.12.2	December 2017


Version Numbering Convention					
Version number	Description				
PowerConnect Series	5	1	12	2	Four part version number
				ℓ	Denotes the build number.
			ℓ		Denotes an ad hoc release of the product software.
		ℓ			Denotes a scheduled maintenance release of the product software.
	ℓ				Denotes a major version number.


## Firmware Upgrade

 **NOTE:** Administrators upgrading PowerConnect 7024/7048/7024P/7048P/7024F/7048R/7048R-RA/8024/8024F/M6220/M6348/M8024/M8024k switches from 2.x.x.x or 3.x.x.x or 4.x.x.x or 5.x.x.x versions of firmware MUST follow the instructions documented in the [Upgrading PowerConnect Switches from Version 2.x.x.x or 3.x.x.x or 4.x.x.x or 5.x.x.x to 5.1.12.2 Firmware](#) procedure. Failure to follow the procedures described in that document when upgrading firmware may result in an inoperable switch!

 **NOTE:** After upgrading the switch firmware version to 5.1.12.2, the CPLD (Complex Programmable Logic Device) code update is required on M8024-k and PC8024/PC8024F switches via serial console if switch is running with the older CPLD version. The latest CPLD version available for M8024k and PC8024/PC8024F switch is Version 6. Administrators upgrading PowerConnect 8024/8024F/M8024k switches MUST follow the CPLD update instructions documented in the [Upgrading PowerConnect Switches from Version 2.x.x.x or 3.x.x.x or 4.x.x.x or 5.x.x.x to 5.1.12.2 Firmware](#) procedure.

 **NOTE:** Dell PowerConnect 8132/8164/8132F/8164F switches are no longer supported on the future 5.x.x.x releases. The last 5.x.x.x firmware version supported for PC8100 series switches is 5.1.4.5. The firmware support for PowerConnect 8132/8164/8132F/8164F switches are migrated to the 6.x.x.x releases which includes fixes from 5.x.x.x releases. The latest 6.x.x.x firmware version available for PC8100 series is 6.3.2.4. N4000 Series and PC8100 Series shares the same 6.x.x.x firmware image (N4000v6.3.2.4.stk).

 **NOTE:** OMNM (Open Manage Network Manager) v6.0 SP1 supports firmware management of PowerConnect 7024/7048/7024P/7048P/7024F/7048R/7048R-RA/8024/8024F/M6220/M6348/M8024/M8024-k to deploy the firmware version 4.1.x.x or later. OMNM v6.0 SP1 supports PowerConnect 8132/8164/8132F/8164F to deploy the firmware version 5.0.0.4 or later.

 **NOTE:** Occasionally, there may be changes made to CLI commands and CLI parameters to fix issues and to provide additional features. Occasionally, these CLI changes can cause configuration mismatches if downgrading from the new firmware back to an older version. When considering a firmware upgrade it is recommended that the current configuration, before upgrade, be retrieved from the switch. This provides a copy of the original running configuration that can be used for restoration if a mismatch in configuration results because of a downgrade from the new version.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Firmware Downgrade

Downgrading from 5.1.12.2 to an earlier release is supported on most PowerConnect series switches; however, migration of configuration information from a later release to an earlier release is not supported. The existing configuration may or may not work with the earlier version of firmware, therefore, it is best to be physically present at the switch site and to be prepared to access the switch over the serial port if necessary when downgrading firmware.

Auto-downgrade of a stack is enabled by default. To avoid accidentally downgrading a stack, be sure to disable auto-downgrade (CLI command: no boot auto-copy-sw allow-downgrade).

Recent versions of the PowerConnect M8024-K modular switches have hardware changes that require firmware version 4.1.0.19 or higher. PowerConnect M8024-K with a new PPID label cannot be downgraded to the firmware version below 4.1.0.19. If a downgrade is attempted, the firmware activation procedure will detect that earlier firmware version is not compatible with the switch hardware and abort the activation procedure. Any PowerConnect M8024-K with the old PPID label can accept any version of the switch firmware.

MODEL	OLD PPID	NEW PPID
M8024K	2F07F A00	2F07F A01
	57821 A00	57821 A01

## Boot Code Downgrade

Never downgrade the boot code! The 5.1.12.2 boot code supports all earlier versions of firmware and never needs downgrading.

## Hardware Supported

- Dell PowerConnect M6220 Ethernet Switch
- Dell PowerConnect M6348 Ethernet Switch
- Dell PowerConnect 7024 Ethernet Switch
- Dell PowerConnect 7048 Ethernet Switch
- Dell PowerConnect 7024P Ethernet Switch
- Dell PowerConnect 7048P Ethernet Switch
- Dell PowerConnect 7024F Ethernet Switch
- Dell PowerConnect 7048R Ethernet Switch
- Dell PowerConnect 7048R-RA Ethernet Switch
- Dell PowerConnect 8024 Ethernet Switch
- Dell PowerConnect 8024F Ethernet Switch
- Dell PowerConnect M8024 Ethernet Switch
- Dell PowerConnect M8024-k Ethernet Switch
- Dell PowerConnect 8132 Ethernet Switch – Not supported. Migrated to 6.x.x.x firmware
- Dell PowerConnect 8164 Ethernet Switch – Not supported. Migrated to 6.x.x.x firmware
- Dell PowerConnect 8132F Ethernet Switch – Not supported. Migrated to 6.x.x.x firmware
- Dell PowerConnect 8164F Ethernet Switch – Not supported. Migrated to 6.x.x.x firmware

## Support Matrix

Since not all functionality is supported on all switches, the following matrix identifies the major differences among the PowerConnect switch models. A check mark indicates support for the feature. All other features listed in the release notes are supported on all switches.

Feature/Switch	Priority Flow Control	DCBx	ETS	PoE+	iSCSI Optimization	USB	grEEEn Ethernet	Hot Swap Cards	WRED
Dell PowerConnect M6220 Ethernet Switch									
Dell PowerConnect M6348 Ethernet Switch					✓				✓
Dell PowerConnect 7024 Ethernet Switch					✓	✓	✓	✓	✓
Dell PowerConnect 7048 Ethernet Switch					✓	✓	✓	✓	✓
Dell PowerConnect 7024P Ethernet Switch				✓	✓	✓	✓	✓	✓
Dell PowerConnect 7048P Ethernet Switch				✓	✓	✓	✓	✓	✓
Dell PowerConnect 7024F Ethernet Switch					✓	✓	✓	✓	✓
Dell PowerConnect 7048R Ethernet Switch					✓	✓	✓	✓	✓
Dell PowerConnect 7048R-RA Ethernet Switch					✓	✓	✓	✓	✓
Dell PowerConnect 8024 Ethernet Switch	✓	✓			✓				✓
Dell PowerConnect 8024F Ethernet Switch	✓	✓			✓				✓
Dell PowerConnect M8024 Ethernet Switch					✓				✓
Dell PowerConnect M8024-k Ethernet Switch	✓	✓			✓				✓
Dell PowerConnect 8132 Ethernet Switch	✓	✓	✓		✓	✓	✓	✓	✓
Dell PowerConnect 8164 Ethernet Switch	✓	✓	✓		✓	✓	✓	✓	✓
Dell PowerConnect 8132F/8164F Ethernet Switch	✓	✓	✓		✓	✓	✓	✓	✓

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## **Supported Firmware Functionality**

For more details regarding all the supported firmware features and functionality, please refer to the Dell PowerConnect Series CLI Reference Guide and the Dell PowerConnect Series User's Configuration Guide.

## Added Functionality in this Release

This section contains a list of features added in this release that are new for at least one switch listed in the **Hardware Supported** section above.

### Release 5.1.12.2

- No Added Functionality in this Release

### Release 5.1.11.1

- No Added Functionality in this Release

### Release 5.1.10.1

- No Added Functionality in this Release

### Release 5.1.9.4

- No Added Functionality in this Release

### Release 5.1.9.3

- No Added Functionality in this Release

### Release 5.1.8.2

- No Added Functionality in this Release

### Release 5.1.7.5

- No Added Functionality in this Release

### Release 5.1.6.3

- No Added Functionality in this Release

### Release 5.1.5.1

- No Added Functionality in this Release

### Release 5.1.4.5

- No Added Functionality in this Release

### Release 5.1.3.7

- No Added Functionality in this Release

### Release 5.1.2.3

- Added “show system stack-ports stack-path” CLI command.



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA

## Release Notes

- Added additional outputs to the "show tech-support" CLI command:

show interfaces counters errors  
show power inline (PoE only)  
show power inline firmware-version (PoE only)  
show switch stack-port counters  
show lldp remote-device all  
show interfaces advertise  
show interfaces media-type  
show interfaces advanced firmware  
show nsf  
show slot  
show process cpu  
show iscsi sessions  
show ethernet cfm errors  
show fiber-ports optical-transceiver

### Release 5.1.1.7

- No Added Functionality in this Release

### Release 5.1.0.1

- IGMP Snooping Improvements
- IP Multicast Enhancements
- Support for B1 CPU – only on PC8100 series
- New Browser Support
  - Mozilla Firefox 14
  - Internet Explorer 9
  - Google Chrome 21
- Static Route Maximum Increased to 512 (for all switches except for M6220 series)
- USB Auto-configuration expanded for multiple MAC Address support
- Ability to reset stack port counters
- Increased Maximum number of dot1x clients per port to 24
- Commands to remove signed certificates/Keys
- Support for Additional transceivers/optics

### Release 5.0.1.3

- Added PoE DC Disconnect HW support – on PC7000 series

## **Release 5.0.0.4**

- Added Native EEE Support for the PC8100 10GBaseT Ports
- 802.1Qaz (ETS) – on 8100 series
- Support for 40 Gig (QSFP+) interfaces
- Support for Bootcode upgrade from pre-4.x image to 5.x image without manual system reset.
- Local Preference for LAG
- Private VLAN
- CLI output filtering
- Routing Improvements for OSPF
- UDLD
- Administrative Profiles
- AAA Authorization
- TACACS+ Accounting
- Stacking over QSFP+ ports
- QSFP+ diagnostics
- sFlow Support on Port Channels

## **Release 4.2.2.3**

- No Added Functionality in this Release

## **Release 4.2.1.3**

- No Added Functionality in this Release

## **Release 4.2.0.4**

- DCBx on M8024-k/8024/8024F
- FIP Snooping Bridge on M8024-k/8024/8024F
- Add EEE Support for the PC7000 10GBaseT Ports
- GUI EEE Power Savings Charts
- RP Failover Performance Improvement
- Flexible Dynamic LAG Limits
- CLI Help Usability Improvements
- Ability to Show Static Route Entries
- CMC XML Support
- Stacking Over Ethernet Ports
- Change Dell EqualLogic iSCSI Auto Detect to default
- Add CLI Macro (Port Profile) for Dell Compellent Storage Equipment
- Provide Dell EqualLogic DCBx TLV Auto Detect and Configuration on M8024-k/8024/8024F

## **Release 4.1.1.9**

- No Added Functionality in this Release

## **Release 4.1.0.19**

- Media-type CLI command

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA

## Release Notes

Added new command "media-type" to configure an interface to select the specified media on a combo port. It is recommended the administrators select the specific media type for the particular type of network connection they expect to use. Users may observe a single port flap when the media type is changed from RJ45 to auto-select RJ45 and only the corresponding SFP port is enabled. Refer to the CLI Reference Guide Updates section below for the complete syntax.

### Release 4.1.0.6

#### ➤ IPv4-Only Mode Optimization

PowerConnect switches allocate the maximum sizes for routing tables (and others, as applicable) for both IPv4 and IPv6. Switch Performance Optimization allows the operator to optimize the allocation of switch silicon tables for either IPv4 only or mixed IPv4/IPv6 operation. The template specified limits are enforced by routing components when routes are being learned. When IPv4 only mode is selected, the following capabilities are disabled:

- DHCPv6 relay
- DHCPv6 server
- IPv6 routing/forwarding
- OSPFv3
- IPv6 Neighbor Discovery
- Configured v6-over-v4 tunnels
- Automatic (6to4) tunnels
- IPv6 Multicast

A reboot is required when changing to or from IPv4 mode.

#### ➤ Auto-Install

USB based auto-install is an easy way to quickly bring up a switch with a known configuration. Network based auto-install is useful in rolling out a configuration or firmware update to a group of switches or in maintaining a central repository of switch configurations and firmware where the switches always obtain their firmware and configuration from a central server.

The following clarifications are helpful in understanding the processing steps in auto-install:

- Always power on the switch that is desired to be the stack master first
- Auto-install never proceeds if a startup-config file is present on the (master) switch
- USB auto-install is attempted first. Network auto-install only proceeds if USB auto-install fails.
- If there are multiple .setup files present on the USB flash device, the powerconnect.setup file is selected
- If a valid .setup file is not found on the USB flash device, the single .text file is used
- If multiple .text files are present, the powerconnect.text file is used.

Network based auto-install utilizes information obtained from a DHCP server. Refer to the documentation for a discussion of the DHCP options used by Auto-Install.

When auto-install downloads a firmware image to switch memory, it compares the version to the current switch image. If different, the image in memory is copied to the switch backup image and activation of the image is attempted. If activation succeeds, the switch is rebooted and auto-install then attempts configuration file download.

Auto-install configuration files are executed as a script. For more details on Auto-Install, refer to the User's Guide.

#### ➤ Link Local Protocol Filtering

Link Local Protocol Filtering blocks Cisco link local protocols from being flooded in the network. By default, PowerConnect switches process and respond to Cisco CDP packets. However, in networks where this capability is not

desirable or other Cisco proprietary packets are flooded over the network, the administrator can disable flooding of Cisco link local protocols. The following table identifies the matching criteria for filtering Cisco proprietary packets:

Rule Type	Rule Purpose	Blocked Destination MAC Address	Ether Type
Blockcdp	Used to block CDP PDU's	N/A	0x2000
Blockvtp	Used to block VTP PDU's	N/A	0x2003
Blockdtp	Used to block DTP PDU's	N/A	0x2004
Blockudld	Used to block UDLD PDU's	N/A	0x0111
Blockpagp	Used to block PAGP PDU's	N/A	0x0104
Blocksstp	Used to block SSTP PDU's	N/A	0x010b
Blockall	Used to block all defined Protocol Filtering PDU's	01:00:0C:CC:CC:C0	N/A

#### ➤ DHCP Server

The PowerConnect Series switches support a simple DHCP server capability for domains that do not wish to deploy a redundant DHCP address assignment solution or who have need of a temporary solution while (re)deploying their DHCP server solution.

In configuring DHCP scopes, be aware that the DHCP pool address and netmask must exactly match a VLAN address and netmask assignment for DHCP addresses to be served over that VLAN.

Only a single manual IP address can be assigned to a pool. The address must have a netmask of 32.

#### ➤ GMRP

The GARP Multicast Registration Protocol provides a mechanism that allows networking devices to dynamically register (and de-register) Group membership information with the MAC networking devices attached to the same segment, and for that information to be disseminated across all networking devices in the bridged LAN that support Extended Filtering Services. The PowerConnect Series switches support GMRP as specified in IEEE 802.1Q 1998.

#### ➤ WRED

Weighted Random Early Drop is supported on certain PowerConnect series switches. Refer to the table at the beginning of this section for further information. CoS queue configuration involves the following hardware port queue configuration parameters:

- scheduler type: strict vs. weighted
- minimum guaranteed bandwidth
- maximum allowed bandwidth (i.e. shaping)
- queue management type: tail drop vs. WRED
- tail drop parameters: threshold
- WRED parameters: minimum threshold, maximum threshold, drop probability

Tail drop and WRED parameters are specified individually for each supported drop precedence level.

In addition, the following are specified on a per-interface basis:

- queue management type: tail drop vs. WRED (only if per-queue configuration is not supported)
- WRED decay exponent

Switch administrators should remember to configure ingress ports as trusted or un-trusted. By default ingress ports trust dot1p values.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA

## Release Notes

### ➤ Stack Firmware Synchronization

Stack firmware synchronization updates all stack members to the active firmware version on the master switch. Stack firmware synchronization is enabled by default. Stack firmware downgrade is enabled by default.

### ➤ Multicast VLAN Registration

Multicast VLAN Registration provides a method of coalescing multicast traffic requested by users on multiple VLANs onto a single VLAN when carried over the network.

MVR does not require that either source or receiver ports utilize VLAN tagging.

Network planners are reminded that multicast groups in the 224.0.0.x range are reserved for multicast control plane traffic. Network planners should select multicast groups in another range for normal multicast traffic, e.g. 239.0.1.x

### ➤ iSCSI Optimization

iSCSI Optimization automatically configures ports for use with the iSCSI protocol and tracks iSCSI sessions on the PowerConnect 7000 and 8000 Series switches as well as the PCM6348. Dell EqualLogic arrays are automatically detected and configuration of Dell EqualLogic connected ports is performed automatically.

Administrators are advised that the configuration performed by enabling iSCSI optimization is not automatically reversed on disabling the feature. The administrator will need to manually remove the configuration settings when migrating Dell EqualLogic servers or iSCSI initiator ports to other ports or switches.

Detection of Dell EqualLogic arrays is keyed on receipt of the mandatory System Description TLV in the LLDP packet. Disabling LLDP will effectively disable Dell EqualLogic array detection.

Dell EqualLogic arrays are required to be upgraded to firmware 5.0.2 or later in order to use the iSCSI Optimization feature.

### ➤ LLDP

Administrators should ensure that LLDP-MED is enabled in order to operate EEE. Disabling LLDP or LLDP-MED will effectively disable EEE, IEEE 802.3at PoE+ high power negotiation and Dell EqualLogic array detection in the iSCSI Optimization feature.

### ➤ Connectivity Fault Management

Connectivity Fault Management performs Metro Ethernet maintenance functions. Dell PowerConnect CFM supports the following functions defined in IEEE 802.1ag Draft 8.1:

- Path discovery (link trace messages)
- Fault detection (continuity check message)
- Fault verification and isolation (loopback and link trace messages)
- Fault notification (alarm indication signal or SNMP trap).

### ➤ Management IP Address Conflict Detection

Management IP address conflict detection actively looks for duplicate IP address assignment and logs conflicts. Only the last identified IPv4 address conflict is retained for display by a show command. Administrators may examine the in- memory logs or the output from a SYSLOG server to identify the historical IP address conflicts. If console logging is enabled for traps, a message will appear on the console indicating that an address conflict has occurred.

### ➤ Email Alerting

Email alerting allows administrators to be notified via email regarding system events. Multiple email addresses can be configured. The system will attempt to resolve mail servers specified with a FQDN immediately and, if successful, store the mail-server as an IP address. If a new IP address is subsequently assigned to the mail server, the operator will need to re-assign the email address on the switch.

Only the Mail User Agent functionality of RFC 4409 is implemented. The PowerConnect switch does not implement SMTP server functionality.

➤ **802.1X Monitor Mode**

Monitor mode is a special debug mode that assists network administrators in configuring 802.1X authenticators. Users attempting to authenticate using the authenticator are always granted access when monitor mode is enabled. All interactions with the supplicant and the authentication server are logged.

Administrators are cautioned against enabling monitor mode in a deployed network where 802.1X users may gain access to sensitive network resources.

➤ **Time Controlled ACLs**

Time controlled ACLs allow administrators to apply ACLs based on the time of day. Both periodic and absolute time periods may be configured.

Administrators are cautioned that invalid (overlapping) periodic entries within a time range will prevent the time range from being applied. Administrators are advised to test their periodic entries and validate that they become active as expected before deploying the time ranges in a production network. Administrators can check if a time range is active by using the *show time-range* command.

It is recommended to enable ACL logging to ensure notice of ACL activation and de-activation.

➤ **SNTP over IPv6**

SNTP operates over IPv4 and IPv6 and may be configured using IPv4 or IPv6 addresses or DNS.

➤ **Strong Passwords**

The strong passwords feature allows administrators to specify that local switch passwords meet certain characteristics considered to enhance network security.

Administrators are advised that the minimum character classes configuration must be enabled (value equal to 1 or greater) along with enabling the strong password feature before the other minimum character class configurations are enforced. These character class configurations are:

- Minimum number of uppercase letters.
- Minimum number of lowercase letters.
- Minimum number of numeric characters.
- Minimum number of special characters

The password strength restrictions do not apply to users configured for the internal authentication server.

➤ **Switch Auditing**

Switch auditing enhances network security by logging sensitive administrative actions. Switch auditing logs the following actions:

- Successful login
- Unsuccessful attempt to login
- Logout out from the switch
- Timed out logout from the switch
- Download file to the switch
- Upload file from the switch
- Remove file from the flash
- File changes on the flash
- Clear configuration
- Add or remove user
- Change user access level

Use of a SYSLOG server for monitoring network events is highly recommended.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## ➤ Authentication

The PowerConnect switches support authentication via a number of methods. The methods are specified in named lists. Lists may be assigned to the enable and login access methods. The supported authentication methods are:

- Enable
- Line
- RADIUS
- TACACS
- IAS
- Local
- None

Methods are attempted in the order specified in the authentication list. If the authentication method rejects authentication, the user login is rejected. If an authentication method fails, e.g. unable to contact the authentication server, the next method in the list is attempted. The IAS, local and none methods can never fail so, if specified, must be last in the list.

The 802.1X authentication list cannot be named and only supports the RADIUS, IAS, or none authentication methods. The 802.1X authentication can only have a single method.

## ➤ Internal Authentication Server

The PowerConnect Series switches support 802.1X authentication of network users from an internal authentication database. IAS users are given access to network resources. IAS is not a valid method for login or enable authentication.

The IAS database can be downloaded to the switch using the “ias-users” target in the copy command. The ias-users file takes the form of a configuration script, as follows:

```
configure
aaa ias-user username client-1
password my-password1
exit
aaa ias-user username client-2
password aa5c6c251fe374d5e306c62496c3bcf6 encrypted
exit
aaa ias-user username 1f3ccb1157
password 1f3ccb1157
exit
```

IAS users may also be configured via the web interface.

## ➤ DNS Client

The PowerConnect Series switches support name resolution via an embedded DNS client. When a DNS name is specified, it is attempted to be resolved against the configured DNS servers immediately. The PowerConnect switches will store the resolved IP address. If the IP address of the host resolved via DNS changes, the administrator will need to update the configured IP address, either via DNS or manually.

If the switch is configured to obtain an address via DHCP, DNS server information received from the DHCP server is used to populate the DNS client configuration.

## ➤ Port Profiles (CLI Macros)

The PowerConnect series of switches provides a convenient way to save and share common configurations through the use of CLI macros. A CLI macro is a set of commands having a unique name. When a CLI macro is applied, the CLI commands contained within the macro are executed and added to the running configuration. When the macro is applied to an interface, the existing interface configurations are not lost; the new commands are added to the interface and are saved in the running configuration.

A CLI macro may have keywords (variables) which are replaced by values provided when the macro is applied (up to 3 keywords per macro). Macros can be applied to specific interfaces, a range of interfaces, or the global configuration.

Administrators may add their own macros or utilize the built-in macros.

Administrators are cautioned to ensure that a macro does not change command modes (e.g., change from interface configuration mode to global configuration mode).

The software includes 6 built-in macros:

- profile-global - the global configuration used to enable RSTP and loop guard.
- profile-desktop - the interface configuration for increased network security and reliability when connecting a desktop device, such as a PC, to a switch port.
- profile-phone - the interface configuration used when connecting a desktop device such as a PC with an IP phone to a switch port.
- profile-switch - the interface configuration used when connecting an access switch and a distribution switch or between access switches.
- profile-router - the interface configuration used when connecting the switch and a WAN router.
- profile-wireless- the interface configuration used when connecting the switch and a wireless access point.

Built-in macros may not be deleted or altered by the operator.

## Changed Functionality in this Release

This section contains commentary on significant differences from previous releases of firmware on PowerConnect switches, e.g. the 8132/8164/8132F/8164F/7024/7048/7024P/7048P/7024F/7048R/7048R-RA/M6348/M6220/M8024/8024/8024F/M8024-k switches. Dell PowerConnect series switches closely conform to networking industry standard operational capabilities and administrative interfaces. The differences below should be studied carefully as attempting to configure or operate the PowerConnect switches in the same manner as for previous releases of firmware for PowerConnect 8132/8164/8132F/8164F/7024/7048/7024P/7048P/7024F/7048R/7048R-RA/M6348/M6220/M8024/8024/8024F/M8024-k switches may lead to unexpected results.

### Release 5.1.12.2

- No Changed Functionality in this Release

### Release 5.1.11.1

- No Changed Functionality in this Release

### Release 5.1.10.1

- No Changed Functionality in this Release

### Release 5.1.9.4

- No Changed Functionality in this Release

### Release 5.1.9.3

- No Changed Functionality in this Release

### Release 5.1.8.2

- No Changed Functionality in this Release

### Release 5.1.7.5

- No Changed Functionality in this Release



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Release 5.1.6.3

- No Changed Functionality in this Release

## Release 5.1.5.1

- The firmware support for PowerConnect 8132/8164/8132F/8164F switches are migrated to the 6.x.x.x releases which includes fixes from 5.x.x.x releases. Dell PowerConnect 8132/8164/8132F/8164F switches are no longer supported on the future 5.x.x.x releases. The last 5.x.x.x firmware version supported for PC8100 series switches is 5.1.4.5. The latest 6.x.x.x firmware version available for PC8100 series is 6.1.0.6. N4000 Series and PC8100 Series shares the same 6.x.x.x firmware image (N4000v6.1.0.6.stk)

## Release 5.1.4.5

- NTP to support RFC4330

## Release 5.1.3.7

- No Changed Functionality in this Release

## Release 5.1.2.3

- No Changed Functionality in this Release

## Release 5.1.1.7

- No Changed Functionality in this Release

## Release 5.1.0.1

- IGMP Snooping  
IGMP snooping is enabled by default.  
Traffic addressed to reserved multicast IP addresses is flooded.  
Unregistered multicast is flooded to all ports in the VLAN until a multicast router port is identified.  
Once mrouter port is identified the traffic is forwarded to mrouter port and listener ports only.
- PIMSM  
PIMSM Rendezvous Points can be positioned anywhere in the network, not just as the first hop router. Although multiple Rendezvous Points can be configured, only one Rendezvous Point is active at any time.
- Auto-Configuration  
Auto-configuration recognizes any of the assigned internal switch's MAC addresses when present in an auto-configuration file. The switch re-writes the file to use the base MAC address of the switch.
- Dot1x Clients  
The maximum number of 802.1x clients (i.e. supplicants) that can be authenticated per port is increased to 24. This increase does not include a corresponding increase in the maximum number of 802.1x clients that are supported on an entire switch or stack.

## **Release 5.0.1.3**

- No Changed Functionality in this Release

## **Release 5.0.0.4**

- Stacking Ports Change  
The maximum number of ports that can be configured for stacking per switch is limited to 8. This is done to ensure that the Hardware limits for maximum stack trunk members are not exceeded.
- Stacking Over QSFP+ Ports  
Stacking is supported over standard QSFP+ ports at either 1x10G or 4x10G mode. The ports must be configured as stacking ports.
- Bootcode upgrade  
Bootcode program is enhanced to automatically upgrade bootcode on migrating switches from pre-4.x version to 5.x version.

## **Release 4.2.2.3**

- No Changed Functionality in this Release

## **Release 4.2.1.3**

- VoIP Phone Limits  
The limitation on the number of VoIP phones has been increased to 576 phones for the PowerConnect 7024/7048/7024P/7048P/7024F switches.

## **Release 4.2.0.4**

- LAG Limits  
Ports can be formed into LAGs in a more flexible manner. The system supports up to 128 total LAGs. Up to 144 ports can be assigned to dynamic LAGs. Up to 72 LAGs can be configured as dynamic. A LAG may contain up to 8 ports. The M8024 supports 12 total LAGs (static or dynamic) with up to 24 ports assigned to dynamic LAGs.
- Stacking Over Ethernet Ports only on M8024-k/8024/8024F  
Stacking is supported over standard Ethernet SFP+ ports. The ports must be configured as stacking ports.
- iSCSI Default Changes  
iSCSI optimization is enabled by default. iSCSI optimization will reconfigure ports that are attached to Dell EqualLogic arrays to utilize spanning-tree portfast and unicast storm disable.

## **Release 4.1.1.9**

- No Changed Functionality in this Release

## **Release 4.1.0.19**

- PHY microcode upgrade process  
The PHY microcode upgrade process has been enhanced to upgrade the PHY microcode to the latest version based on PHY revision. If the user experiences problems links on the combo ports after the upgrade completes, a reboot may be required in order to activate the new PHY firmware.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## ➤ Asymmetric flow control

Asymmetric flow control is implemented for the PC8024X, PCM8024, PCM6348, PC70XX, and PCM8024-k switches. The switch does not generate pause frames when congested. It will honor pause frames as per industry standards.

## Release 4.1.0.6

## ➤ Authentication

The enable and line authentication methods will no longer perform authentication if a password for the method is not configured. Previously, these methods would always succeed if no password was configured. To achieve the same functionality, add the “none” method to the list after enable or line method.

The default authentication list for telnet and SSH has been changed to enableNetList. The only authentication method contained in enableNetList is enabled. The net effect of these two changes is that a password is required to enter privileged exec mode when using telnet or SSH.

Administrators wishing to maintain the previous PowerConnect behavior can set the default authentication list for telnet and SSH to enableList, which has the enable and none authentication methods (no password required to enter privileged exec mode). The following commands change the telnet authentication method to enableList.

```
console(config)# line telnet
console(config)# enable authentication enableList
console(config)# exit
```

## ➤ New Web Interface

The Web interface has been enhanced with new navigation features for ease of use.

## ➤ CLI Syntax Changes

The CLI has changed significantly to be compatible with the PowerConnect switch standard CLI. Configurations for previous releases may not be compatible with this release and may need to be updated. Refer Configuration Migration document for more info.

## ➤ Unit/Slot/Port Naming Conventions

In-band interfaces are named based on stack unit, slot, and port. Units range from 1-12. Slots range from 0-2. Ports range from 1-48. Slots for plug-in modules are numbered 1 and 2. Fixed ports belong to slot 0.

The service port is still addressed using the *out-of-band* keyword.

## ➤ Management VLAN Deprecated

The PowerConnect series switches do not have an in-band management VLAN by default. Administrators can designate a VLAN for support of in-band management operations.

## ➤ VLAN interface configuration mode enables routing

When executing the “interface vlan x” command, routing is automatically enabled on that VLAN.

## ➤ Service/Out-of-band Ethernet Port Defaults to DHCP Addressing

By default, the service/out-of-band Ethernet port will attempt to obtain an address via DHCP.



**NOTE: It is recommended that administrators attach the service/out-of-band Ethernet port to a physically separate network for out-of-band network management. The service port does not offer routing or switching capabilities nor does it offer enhanced protection from DOS attacks. Configure a VLAN on one or more in-band interfaces for management of PowerConnect switches over the operational network.**

➤ LACP Ports Inactive Until Attached

Ports in a LAG configured to use LACP (dynamic LAG) remain inactive (discard received traffic) until they become attached to the LAG. LACP ports that are attached to a LAG will enter the discarding state if they become detached from the LAG for any reason.

Port level configuration for a port that is configured in a dynamic LAG is disregarded. Remove the port from the LAG to restore use of the port level configuration.

Ports in a static LAG begin forwarding on link up. Ports in a static LAG disregard port level configuration. Configure static LAG functions on the static LAG interface.



**NOTE: It is recommended that administrators disable portfast and auto-portfast on physical interfaces configured in a LAG. Portfast and auto-portfast can interfere with an interface entering into LAG mode on a reboot and possibly enable a packet storm.**

➤ Spanning Tree Changes

Administrators may assign more than 1024 VLANs to MSTP instances. Only VLANs that are configured on the switch will forward traffic.

The PowerConnect switches implements the 802.1Q-2005 standard which builds on 802.1D-2004. 802.1D-2004 incorporates the 802.1t, 802.1w and 802.1s revisions. Port path costs are calculated based on the interface speed as shown below and are dynamically recalculated on interface activation and link speed changes.

External Port Path Cost values (Port Path Cost in 17.14 of 802.1D-2004) are applicable in STP, RSTP, and MST modes (Ref. Table 17-3 802.1D-2004). Use the *spanning-tree cost* command in interface mode to set the external port path cost.

<u>Link Speed</u>	<u>Default Value</u>
10 Gb/s	2000
1 Gb/s	20000
100 Mb/s	200000
10 Mb/s	2000000
1 Mb/s	20000000

Internal Port Path Cost values are specific to MST mode only (Ref. Table 13-3 802.1Q-2005). Use the *spanning-tree mst <instance> cost* command in interface mode to set the internal port path cost.

<u>Link Speed</u>	<u>Default Value</u>
10 Gb/s	2000
1 Gb/s	20000
100 Mb/s	200000
10 Mb/s	2000000
1 Mb/s	20000000

➤ User Configurable CLI Banners

Administrators may configure banners for the following: MOTD, login, and exec. The banners may consist of multiple lines of text. Each new line will consume an extra two characters (CR/LF) that count against the maximum length banner that can be configured.

➤ Captive Portal

Captive portal has been extended to support user logout and localization.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## ➤ 802.1Q

The following changes have been made to the operation of VLANs.

### VLAN Membership:

By default, trunk ports participate in all VLANs. VLANs created after a trunk port is created are added to all trunk ports. VLANs deleted are removed from all trunk ports. The operator may configure a trunk port to explicitly disallow certain VLANs.

### Native VLAN Configuration on Trunk Ports:

It is now possible to configure the native VLAN on a port in trunk mode. Trunk mode ports will accept untagged frames but will always transmit tagged frames except for the native VLAN which will always transmit untagged frames. It is also possible to configure a trunk port to drop untagged frames by filtering on the native VLAN, e.g. by using the *switchport trunk allowed vlan remove* command.

A trunk port always has a native VLAN (default is VLAN 1), so the default behavior is that untagged packets are treated as if they are tagged in VLAN 1. To drop untagged packets, configure *switchport trunk allowed vlan remove <vlan>* which has the side effect of dropping tagged packets in that VLAN.

### Switchport Mode Configuration Preserved:

When switching between switchport modes (access, trunk, and general), the switchport configuration applicable to the selected mode is maintained. This means that when switching from one mode to another and back, the port will have the same configuration as it had in the original mode. Only the configuration applicable to the selected mode is active on the port.

## ➤ VRRP

The following enhancements have been made to the operation of VRRP to increase usability and robustness of operation in the network:

### Preemption Delay:

Per the VRRP RFC 3768, when preemption is enabled, the backup router discards advertisements until the master down-timer fires. When the preemption delay timer is set to a non-zero value and the backup switch receives a PDU with a lower priority from the master, then backup switch waits for the preemption delay value before advertising itself as the master.

### Timer Advertisement Learning:

In VRRP, all participating routers should be configured with coherent advertisement timer interval values. The operator can now enable timer learning which causes a backup router to learn the master advertisement interval and change its master down interval accordingly.

### Ping-able VRRP Interfaces:

RFC 3768 specifies that a router may only accept IP packets sent to the virtual router's IP address if the router is the address owner (master). In practice, this restriction makes it more difficult to troubleshoot network connectivity problems.

This capability adds support for responding to pings by the VRRP master, but does not allow the VRRP Master to accept other types of packets. A configuration option controls whether the router responds to Echo Requests sent to a VRRP IP address. When enabled, the VRRP master responds to both fragmented and unfragmented ICMP Echo

Request packets. The VRRP master responds to Echo Requests sent to the virtual router's primary address or any of its secondary addresses. When the VRRP master responds with an Echo Reply, the source IPv4 address is the VRRP address and source MAC address is the virtual router's MAC address. The VRRP master does not respond to pings sent from the master.

Members of the virtual router who are in backup state discard ping packets destined to VRRP addresses, just as they discard any Ethernet frame sent to a VRRP MAC address.

#### Fragmentation and Reassembly:

Fragmentation and reassembly of VRRP packets is not supported.

#### ➤ DHCP Relay

The following enhancements have been made to the operation of DHCP Relay to bring the implementation into conformance with RFC 4649:

##### DHCPv6 Relay Circuit Id/Remote Id Types

RFC 4649 specifies the IANA assignment of the Relay Circuit Id sub-option and Remote Id option. The implementation has been changed so that the administrator can no longer assign a numerical value to these TLVs as the IANA assigned number is now used. The administrator can still enable or disable the insertion of these TLVs in messages sent to the DHCP server.

#### Relay Information Option:

The operator has the ability to enable DHCP Relay Information Options both globally and on a physical interface. The interface configuration overrides the global configuration for the selected interface.

#### Relay Information Option Check:

When DHCP Option-82 insertion is enabled for a relay agent, the server should echo received Option 82 unaltered back toward the client. The relay agent is required to strip Option 82 information before relaying the BOOTPREPLY to the DHCP client. When enabled, the Relay Information Option Check will cause the BOOTPREPLY packet to be dropped if invalid sub-options are echoed by the DHCP server.

#### ➤ L2 Address Table

The administrator can disable MAC address table aging.

The administrator can configure static forwarding of a MAC address on a specific VLAN.



**NOTE: By default, multicast frames are flooded by the switch. Utilize the *mac address-table multicast filtering* command to disable flooding of multicast frames.**

#### ➤ LLDP Enhancements

##### Multiple Neighbor Support:

Multiple neighbors are supported on a single LLDP interface. The number of recognized neighbors is limited to two per port or 834 LLDP neighbors on a fully stacked set of switches. There is no restriction on the number of neighbors connected to an LLDP port. If more LLDP neighbors are present than are supported, then only the last two neighbors that communicate with the local LLDP interface are recognized and any additional neighbors are ignored.

##### EEE Support:

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Support is added to process/communicate the EEE TLV to partner devices. The EEE TLV is an 802.3 organizationally specific TLV used to report on the EEE Data Link Layer capabilities.

## LLDP-MED Support:

LLDP-MED uses LLDP's organizationally specific TLV extensions and defines new TLVs which make it easier to deploy VoIP in a wired or wireless LAN/MAN environment. The LLDP implementation supports the following TLVs:

### Mandatory 802.1AB TLVs

- Chassis ID TLV (subtype shall default to MAC Address)
- Port ID TLV (subtype shall default to MAC address)
- TTL TLV
- MAC/PHY configuration/status TLV
- End of LLDP PDU

### Optional 802.1AB TLV

- Systems Capabilities TLV
  - Power via MDI TLV
- NOT recommended for transmission in order to conserve LLDPDU space.

### Mandatory LLDP-MED TLVs

- LLDP-MED Capabilities TLV  
This TLV allows the network connectivity device to definitively determine whether particular connected devices do support LLDP-MED and to discover which specific LLDP-MED TLVs the particular end point devices are capable of supporting as well as what specific device class they belong to.
- Network Policy TLV  
This TLV allows the device to advertise its VLAN and associated Layer 2 priority and Layer 3 DSCP attributes which apply for a set of specific protocol applications on this port.
- Location Identification TLV  
This TLV provides the advertisement of location identifier information Class II endpoint Devices. This is expected to be related to wire map or similar network topology data, such that the configuration of the network Connectivity device is able to uniquely identify the physical location of the connected MED endpoint.
- Extended Power-via-MDI TLV  
This TLV allows for advanced power management between endpoints and network connectivity devices. It transmits fine grained power requirement details. This TLV provides significantly more value than the 802.1AB Power via MDI TLV.
- EEE TLV  
The EEE TLV is used to exchange information about the EEE Data Link Layer capabilities. Devices that require longer wake up times prior to being able to accept data on their receive paths may use the Data Link Layer capabilities to negotiate for extended system wake up times from the transmitting link partner. This mechanism may allow for more or less aggressive energy saving modes.

## ➤ Dynamic VLAN Assignment

Dynamic VLAN assignment is intended to support the connection of hosts to a router with enhanced levels of service, typically either security or QoS. This release supports dynamic VLAN assignment as assigned from the RADIUS server as part of port authentication. The following additional checks are performed in support of dynamic VLAN assignment:

Before assigning the port to RADIUS assigned VLAN, dot1x checks if the given VLAN is in the VLAN database or not. If the assigned VLAN is not in the VLAN database and dynamic VLAN assignment is enabled, a VLAN is created on the port over which the client is authenticated. Each time a client is de-authenticated on an interface with a particular VLAN, a check verifies if there any other interface which a VLAN member is. If there is no interface as a member, the VLAN is deleted. This behavior is same for MAC based authentication as well.

➤ Usability Enhancements

In the output of the *show running-config* command, the slot and member configuration is commented with the switch/slot type in human comprehensible form.

When in interface config mode, CLI users can navigate to a different interface by entering the appropriate interface command without leaving interface config mode.

CLI users can log out of the switch using the *exit* command (*exit* is an alias for *quit*).

The CLI Reference Guide is updated with acceptable character sets and maximum lengths for string parameters to commands.

Management ACLs permit specification of *service any* as shorthand for enabling all services access for in-band management.

VLANs may be administratively assigned to MSTIs in excess of the switch physical limits and without regard to whether the VLAN is actually configured. Frames are only forwarded on VLANs assigned to interfaces.

Administrators can re-enter SYSLOG server config mode for a particular SYSLOG server entry without requiring the deletion and re-creation of the entry.

Administrators can configure the web timeout by navigating to: System -> Management Security -> Telnet Server -> Telnet Session Timeout.

User configured banners (login, exec, MOTD) appear in the running config.

By default, auto-install supports image downgrade for network installs, specific version USB installs (using a .setup file), and stack firmware synchronization.

A comprehensible message and recommendation is issued when configuring multiple services (telnet, http, etc.) to listen on the same TCP port.

The *terminal length* command allows user control over terminal paging.

➤ Simple Mode

The PowerConnect M8024-k is the only modular switch that defaults to the simple mode of operation. Simple mode contains a restricted set of commands suitable for control of a port aggregation device that can be deployed in a network without requiring updates to the network by a network administrator. Users needing switch capabilities which require the network administrator to modify the network configuration can exit simple mode using the *no mode simple* command.

➤ AAA Authentication

In prior releases, more than one method could be specified for dot1x authentication even though only the first method was attempted. The CLI and Web now only accept a single method for dot1x authentication.

## Issues Resolved

The following issues from previous releases have been corrected. The issues listed here may have been discovered on any of the switches listed on the title page.

## Release 5.1.12.2

Summary	User Impact	Resolution	Affected Platforms
SNMPWalk of "ifSpeed" object not returning logical interfaces [CS3827063, FIELD-2538]	ifSpeed object is not returning entries for port-channel interfaces.	Addressed issue retrieving interface speed and duplex settings.	All Platforms
StkMgrTask crashes while replacing standby unit. [CS3744904, FIELD-2521]	Standby switch crashes due to invalid memory access exception.	Addressed invalid memory access.	All Platforms
Switch crashes with "emWeb_main" task while performing vulnerability scan [CS2871784, FIELD-2344]	Vulnerability scan uses all available SSH sessions exhausting system resources.	Added CLI command to configure maximum secure HTTP sessions allowed to limit the number of sessions.	All Platforms
Switch reboots with crash log. [CS3497559, FIELD-2468]	Switch crashes when I3 interface deletion fails.	Addressed handling of error condition.	All Platforms



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Syslog format violate RFC3164 [CS263533, FIELD-2404]	Some syslog-servers are not accepting log messages if unit-id present with IPv4 address in the hostname field.	Used hostname instead of IP address if available.	All Platforms
Multicast error logs [CS2780734, FIELD-2325]	Candidate-RP advertisements are failing transmit due to NULL destination address causing errors.	Addressed handling of error condition by handling NULL address.	All Platforms
DHCP Clients unable to get an IP address with "DHCP SNOOP DB MATCH FAILURE" logs. [CS3416542, FIELD-2437]	Random DHCP Clients doesn't get assigned with an IP address dynamically.	Addressed by porting relevant DHCP fixes.	All Platforms

## Release 5.1.11.1

Summary	User Impact	Resolution	Affected Platforms
OpenSSH CVEs Vulnerabilities. [FIELD-2270]	Not-vulnerable: CVE-2007-4752, CVE-2008-1483, CVE-2006-5051, CVE-2006-5052, CVE-2006-5794, CVE-2014-2653, CVE-2014-2532, CVE-2015-8325, CVE-2010-5107, CVE-2006-4924, CVE-2016-1907 Vulnerable: CVE-2016-6515	Applied patch for vulnerability: CVE-2016-6515	All Platforms
Switch console & telnet session hangs with aaa accounting configuration. [PSE037972]	Switch hangs when aaa accounting is configured and acct-method as tacacs which is not reachable.	Corrected the problem initiating TACACS request.	All Platforms
Switch crashes at lldpTask [PSE036768]	Switch crashes with "lldpTask" when switch receives LLDP packet with TLV length of 75	Corrected the switch buffer free issue.	All Platforms
Constant switch fan-speed changes without temperature change. [PSE036954]	Switch frequently receives a fan speed change log within the normal range of operation(0-50 degree)	Corrected the error in reporting fan speed	PC70XX
DHCP Snooping entry NOT removed after lease time expired. [PSE033483]	DHCP Snooping entry NOT removed after lease time expired	Corrected the error in calculating DHCP lease time.	All Platforms
Error message: radius_api.c(194 1) 444 radiusServerSourceIPGet(): Failed to find server [PSE029930]	Error message is being produced even though the switch is successful in sending the radius-request to radius server.	Corrected the radius initialization error.	All Platforms

## Release 5.1.10.1

Summary	User Impact	Resolution	Affected Platforms
The Received Oversize Packets counter increases when using tagged traffic. (PSE030067)	When VLAN tagged packets with MTU size from 1519 to 1522 are sent to 1G ports, the Received Oversize Packets counter increases.	Corrected the counter issue for 1G ports.	All Platforms

PCM6348 (RSTP) connected to a HP switch (PVST) - Learning MAC addresses on blocked ports. (PSE029755)	MAC addresses are learnt on the port even though it is in disabled state.	Corrected a sync issue with HW L2 Table.	PCM6348
The current date on GUI changes only after 8am. ( PSE030638)	The current date on GUI changes only after 8am.	Corrected a web database pointer issue.	All platforms
Expansion module - Shutting down a port shuts down a different port. (PSE031705)	When a port in an expansion module is shut down, a different port in the same expansion module gets shut down.	Corrected a CPLD register access issue.	PCM8024

### Release 5.1.9.4

Summary	User Impact	Resolution	Affected Platforms
Under certain scenarios, the system experiences a software exception.	The system experiences a software exception randomly due to certain transient software parity errors.	Changed the DMA settings to the optimal values to avoid DMA operation timeouts. Introduced syslog alerts to log parity errors to be consistent with standard industry practice.	All Platforms.
While monitoring the system using SNMP, the following error message is seen: Error "macal_api.c(873 ) 576286 macalRuleAction Get(): List does not exist"	While monitoring the system using SNMP, the following error message is seen occasionally: Error "macal_api.c(873) 576286 macalRuleActionGet(): List does not exist"	Corrected an error in the SNMP walk operation.	All Platforms.
When IPv6 MLD snooping is enabled, IPV6 multicast RS packets are dropped.	When IPv6 MLD snooping is enabled, IPv6 DHCP address assignment does not work.	Corrected the length check when validating IPV6 MLD packets.	All Platforms.

### Release 5.1.9.3

Summary	User Impact	Resolution	Affected Platforms
Dot1x Radius authentication fails when source-ip and/or attribute changed	Dot1x Radius authentication fails when the source IP address or VLAN ID change.	Corrected an error when updating changed attributes.	All Platforms
Log messages flooding "Max Response Expiry Timer for vlan"	Log Messages "Updating the Max Response Expiry Timer for vlan X to Y secs."	Corrected logging level to debugging.	All Platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Network directed broadcast stops working after being re-enabled via GUI	Network directed broadcast stops working after being re-enabled via GUI	Corrected mismatch between Web UI and CLI.	PC70XX
IPv6 neighbor solicitation multicast not distributed to non-management stack members	Traffic Loss is seen on IPv6 Neighbor solicitation packets on the non-master member of the stack	Corrected CoS queue priority of IPv6 messages.	All Platforms
Syslog shows wrong port mapping when optics is inserted/removed	Occasionally, optics map to the wrong port when removed/inserted.	Corrected error in identifying the port when the port ID is retrieved from HW.	PCM8024
Crash in the radius task	Crash seen in the Radius Server task after receiving "interface change" message	Corrected an error when receiving the "interface change" message	All Platforms
Change pre-emphasis settings (0x4bb0) to support 26 AWG 3M Stacking cable	Change pre-emphasis settings (0x4bb0) to support 26 AWG 3M Stacking cable	Changed pre-emphasis settings.	PC70XX
Management ACL Log message flooding	Error message: "Number of packets denied by management ACLs = XXXX" seen in logs.	Reduced severity of the log messages to the appropriate level.	All Platforms
1G+forced settings not retained in 10G port after reload in a stack	Manually configured port speed is not applied to the interface after a stack reload.	Corrected error in port configuration.	PCM8024K
ip ospf and rip authentication encrypt string is showing in clear-text	ip ospf and rip authentication encrypt string is showing in clear-text	Encrypted authentication string	All Platforms
ssh public key authentication doesn't work	ssh public key authentication fails on challenge phrase.	Corrected error in evaluating challenge phrase.	All Platforms
No switch console/telnet/ssh access with "l7_usl_macsync" error.	Occasionally no management (console/telnet/SSH) access to the switch	Corrected issue with MAC address aging flood.	All Platforms

## Release 5.1.8.2

Summary	User Impact	Resolution	Affected Platforms
Routing issue, null address in ARP table after VLAN manipulation	NULL address in ARP table if VLANs are not created in numeric order.	Corrected enumeration of internal data structures.	All Platforms

Power LED displays red in switch GUI	Power LED displays red in switch GUI	Corrected display of Power LED.	PCM8024-K
Temperature warning messages in switch logs.	Temperature warning toggles when temperature changes between 50 and 51.	Corrected temperature mapping.	All Platforms
SSL/SSH vulnerability	SSL/SSH vulnerabilities: CVE-2009-3555 weak ciphers and RC4 ciphers CVE-2008-5161 Nessus ID : 42873	Applied SSL/SSH patches.	All Platforms
CLI command "terminal length 0" not working as expected	CLI command "terminal length 0" output shows "Incorrect input! Use 'terminal length <0-512>'."	Corrected handling of zero as the input value	All Platforms
Switch crashes when applying 'show ip igmp mrouter' command in SSH	The switch crashes when issuing 'show ip igmp mrouter' command in SSH if there is a need to display more than 14 mrouter-interface entries for an interface.	Corrected the display of 'show ip igmp mrouter' command output.	All Platforms

## Release 5.1.7.5

Summary	User Impact	Resolution	Affected Platforms
Incorrect DIR timestamps and PowerSupply output.	Observed incorrect DIR timestamps and PowerSupply output in IOMs only as they don't have a RTC (real time clock).	Removed DIR timestamp for IOM that doesn't support a RTC.	PCM6348 PCM8024-K
SNMP MIB Walk "boxServicesTempSensorsTable" doesn't match with "show system temperature" CLI command output	SNMP MIB walk on a stack should display the information of the rest of the stack members, even if any member is removed from the stack.	Corrected retrieval of temperature data from stack member units.	All Platforms
Incorrect status message when downloading image via FTP	Message should show FTP code transfer starting... but it is showing TFTP code transfer starting.	Corrected status message.	All Platforms
Terminal length CLI command suggest to use range <31-1>	The error message is incorrect when invalid arguments are passed to "terminal length" command	Corrected error message.	All Platforms
Unable to enable/disable HTTPS from WebUI.	Unable to enable/disable HTTPS from WebUI with error message.	Corrected web page error.	All Platforms
Console debug logs prints a wrong message.	When attempt to add a user account with a wrong password, the message "New user has been added" logged when it is not.	Corrected user creation error.	All Platforms
WebUI Error when adding pre-existing SNMP community but still adds the community	WebUI Error "Error! Failed to Set "NLS ERROR"" when re-entering a previously existing community string. But still the community string is added.	Corrected community creation error.	All Platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Error when trying to add DHCP option 42	DHCP Server Option 42 support was not available when DHCP Server was integrated.	Added DHCP Server Option 42.	All Platforms
Unable to create port-channel on combo ports with different duplex setting across stack units.	Unable to create a port-channel interface on combo ports (RJ45 and fiber ports) with different duplex settings across the stack members.	Corrected error when checking LAG members for speed.	All Platforms
Management SSH connections time out in simple mode	Multicast packets are processed by the snoopTask as the snooping is enabled by default.	Disabled IGMP Snooping in simple mode.	All Platforms
External uplink-ports on standby member are not listed under "show switch stack-ports" CLI output.	External uplink-ports on standby member are not listed under "show switch stack-ports" CLI output.	Corrected error in "show switch stack-ports" CLI output.	All Platforms
SNMP MIB Walk for Power Supply and Fan Tray info of all member units in the stack.	SNMP MIB Walk of "boxServicesPowSuppliesTable" and "boxServicesFansTable" gets the "power-supply" and "fan info" only from the "Master" unit in the stack.	Added member unit information.	All Platforms
Unable to add ports into port-channel across the stack when ports are down	If transceivers not inserted into ports, unable to add ports in to port-channel across the stack.	Corrected error when checking port capability.	All Platforms
'show passwords result' output is incorrect	'show passwords result' output is incorrect	Corrected error in 'show passwords result' command	All Platforms
After deletion of VLAN, the member port is not added back to the default VLAN	If a port is in access mode and the access VLAN is deleted from VLAN database, the port PVID is modified to 1 but the port is not member of any VLAN.	Corrected error in VLAN membership.	All Platforms
Link flap when attempt to change the speed which is not supported	Link flap when attempt to change the speed which is not supported on a 10G copper port.	Corrected check for unsupported speeds.	PC8024
gvrp registration-forbid is not working if there are two interfaces b/w GVRP client and Server	gvrp registration-forbid is not working if there are two interfaces b/w GVRP client and Server	Corrected error in check for forbidden interfaces.	All Platforms
Inconsistent error message b/w WebUI and CLI for GARP Join Timer	GARP Join timer WebUI and CLI Errors are not consistent.	Corrected the error message to be the same as the CLI.	All Platforms
Multiple OpenSSH Vulnerabilities	OpenSSH issues CVE-2006-4924 & CVE-2006-4925	Applied OpenSSH patches for CVE-2006-4924 & CVE-2006-4925.	All Platforms

POODLE vulnerability in SSLv3	The Padding Oracle On Downgraded Legacy Encryption (POODLE) vulnerability allows a man-in-the-middle attacker to decrypt ciphertext	Disabled SSLv3 and applied patch for CVE-2014-3567	All Platforms
Stack failover forces the combo ports of the standby unit to "duplex full"	Stack master reboot forces the combo ports of the standby unit to "duplex full" mode	Corrected error in check for port configuration.	All Platforms
Unable to remove duplex setting on switch-ports	Unable to remove duplex setting on switch-ports	Corrected error in duplex setting.	All Platforms
Port-channel member loses its configuration after reloading the switch	When ports with different speeds or from different IO modules are added to the port-channel, and switch reloaded, one of the ports loses its configuration.	Reverted the port-channel configuration behavior to as in pre-5.1.4.x firmware, i.e. does not support mixed speed LAG but will not provide any warning message during configuration; allows the configuration and the port with lower speed (in mixed configuration) will not link-up, so will not be part of active port-channel.	All Platforms
User password length is not checked when using the Easy Setup Wizard.	User password length is not checked when using the Easy Setup Wizard.	Corrected error in check.	All Platforms
Inconsistency in output of 'show link-dependency'	'show link-dependency' shows incorrect 'Group state'	Corrected the loop that fetches group status	All Platforms

### Release 5.1.6.3

Summary	User Impact	Resolution	Affected Platforms
VoIP & 802.1x issue	The phones are being placed in the wrong VLAN occasionally while the phone is being booted and going through the authentication process	Corrected the race condition between VoIP and Dot1x authentication	PC70XXP
Stack loses connection to directly attached servers on master-failover(with uplink on)	Directly attached hosts will not ping after stack failover is initiated.	Corrected failover synchronization issue	All Platforms
Logs are filled with the output stating "Copy of running configuration to backup unit complete"	Logs are filled with "Copy of running configuration to backup unit complete"	Corrected issue when saving the DHCP configuration.	All Platforms
External ports located on SFP+ module stay up during reload	Ports that belongs to SFP+ plug-in module stay up while switch is reloaded.	CPLD update version 6 to allow SW control of plug-in module.	PCM8024-K

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Error when trying to add DHCP option 42	DHCP server option 42 support was not available when DHCP server was integrated.	Added DHCP server option 42 support.	All Platforms
OpenSSL SSLTLS MITM vulnerability CVE-2014-0224	OpenSSL SSLTLS MITM vulnerability CVE-2014-0224	Fix for OpenSSL SSLTLS MITM vulnerability CVE-2014-0224	All Platforms
RADIUS authorized clients were removed from authorized VLAN.	RADIUS authorized clients were removed from authorized VLAN.	Corrected Dot1x re-authentication issue on stacked switches	All Platforms
IPv6 v6LC.2.3.16: Redirect Issue	IPv6 v6LC.2.3.16: Redirect Issue	Corrected IPv6 redirect issue.	All Platforms
Spanning Tree BPDUs sent out on Alternate Port	Rapid Spanning Tree BPDUs sent out on Alternate Port	Corrected check for designated port.	All Platforms
SNMP traps with wrong agent-address	SNMP agent address is not shown in the SNMPv1 trap. The agent-addr field value shows zeroes in trap PDU.	Corrected address update issue.	All Platforms
Occasional crash in tasks tArpCallback & IpHelper.	Occasional crash when processing a UDP packet	Corrected check for UDP packets	All Platforms
Master LED shows red indicator in OpenManage Switch Administrator GUI	Master LED shows red indicator in OpenManage Switch Administrator GUI	Corrected LED color selection issue.	PC70XX
STP status of a physical port bound to a port-channel interface changes from DSC to Forward after adding VLAN	After adding a VLAN, the STP status of the physical interfaces bound to the port-channel interface is transitioned from discarding to forwarding state.	Corrected port status issue.	PC8024
ClearPass filters are not applied to the switch interface(s) occasionally.	If a filter is defined using Class Maps, Policy Maps and Service Policies on a ClearPass RADIUS server, the filter on the switch for the specific authentication port is not applied.	Corrected filter update issue on dot1x re-authentication.	All Platforms

## Release 5.1.5.1

Summary	User Impact	Resolution	Affected Platforms
“show running-config all” CLI command is not working as expected.	“show running-config all” will not be generated if stack has more than 9 member units.	Corrected memory allocation problem	All Platforms

Switch crashes intermittently with tArpCallback & IpHelperTask task related errors	Switch crashes with tArpCallback & IpHelperTask messages	Corrected corrupted IP header handling.	All Platforms
"show system" CLI command shows blank "Power Supplies" status	Non-IOM modules should display the power supplies	Corrected IOM validation.	PCM8024-K
ip_util.c error message when default route is configured	"Failed to configure static route to 0.0.0.0/0.0.0.0" log message observed when performing initiate failover.	Corrected error checking for static route.	All Platforms
Global Health Status is abnormal	MIB OID - productStatusGlobalStatus, On a system with a single Power Supply which is powered up, should be reported as OK rather than NON-CRITICAL.	Corrected power reporting problem	PC70XX
IPv6 Cert - Device under test does not stay in state No Neighbor Cache Entry.	Device under test does not stay in state No Neighbor Cache Entry if next neighbor does not respond.	Corrected state timer problem	All Platforms
Storm control is not working as expected	Receive Packets Discarded does not increment when storm control rate is set for multicast, broadcast and unicast.	Corrected storm control counter problem	All Platforms
Switch stops responding to Serial console, Telnet, SSH and WebUI	Occasionally, Users will not have access to the serial console, SSH, telnet sessions after a download.	Corrected socket timeout problem	All Platforms
RADIUS "Access-Request" packet having "Stat (24)" attribute included when doing re-authentication.	"Stat (24)" attribute is present in the Access-Request during re-authentication.	Corrected State attribute reception	All Platforms
emweb_main crash	Occasionally the WebUI will crash.	Corrected memory allocation problem	PCM8024-K
igmp snooping/flooding implementation across the range	Flooding happens when mrouter is configured and link to mrouter is down	If mrouter is configured always use mrouter port	All Platforms
Stack stops responding to ICMP, WebUI & Telnet	Occasionally, IP Stack will not respond to any requests like ICMP, Telnet, SSH	Corrected IP stack buffer leak.	All Platforms

## Release 5.1.4.5

Summary	User Impact	Resolution	Affected Platforms
Unable to restore config via GUI/HTTP	A configuration file could be corrupted when saved causing the restore to fail.	Fix corruption when saving a configuration file.	All Platforms



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

IPv6 - Duplicate Address Detection issue	Violation of RFC 4862 Section 5.4.5:  "If the address (DAD failed) is a link-local address formed from an interface identifier based on the hardware address, which is supposed to be uniquely assigned (e.g., EUI-64 for an Ethernet interface), IP operation on the interface SHOULD be disabled."	Corrected link-local address issue.	PC8132 PC8132F PC8164 PC8164F
BSR action shutdown functionality is not working.	Storm control is hitting threshold early compared to the configured threshold value.	Corrected storm control counter issue	PC8132 PC8132F PC8164 PC8164F
cpdTest command reports a fan control error	cpdTest reports fan errors which are invalid errors because the incorrect bits were tested.	Corrected fan status query.	PC8024 PC8024F
"show tech-support" output is incomplete and overwritten by "show arp" entries.	The incorrect pagination by "show arp" over writes other portions of the show tech-support output	Corrected pagination issue	All Platforms
Error reported when generating 2nd self-signed certificate from CLI	First self-signed certificate is still in process of generating when the second certificate is requested.	Corrected error message to indicate the proper reason why the second certificate failed.	All Platforms
storm control action support for broadcast and multicast streams	Added storm control action support for broadcast and multicast streams	Added storm control action support for broadcast and multicast streams	All Platforms
Storm-control	Storm-control as documented in the CLI and user configuration guide is fully implemented.	Implementation of storm-control includes multicast, Broadcast and Unicast packets.	All Platforms
Show mac address-table command is crashing the switch	Occasionally the switch will crash if "show mac-address-table" command is issued	Corrected buffer overflow issue.	All Platforms
SNTP KoD packet stops time synchronization	If a switch receives a KoD packet (stratum 0 and ref.ID = INIT) from an NTP server which just reloaded and is synchronizing time with higher strata, then the switch, contrary to RFC 4330, stops synchronizing to that server if no other server is configured.	Corrected back-off time issue	All Platforms
ICMP Redirect status of VLAN is enabled when "no ip redirects" applied globally	Applying "no ip redirects" command globally does NOT have any impact on VLAN interfaces	Corrected global command sync issue.	All Platforms
Error reported when importing a certificate via GUI	Certificate larger than 1024 would generate and error.	Corrected a size issue when pasting a certificate in the Web UI.	All Platforms

LAG allows interfaces of different speeds to get bundled	LAG allows interfaces of different speeds to be bundled into a single port channel. After addition, the interfaces added later stay down. Though, speed change for an interface which is already a member is not allowed.	Added a message when a user attempts to add an interface of different speed.	All Platforms
Add show running-config interface <intf-id> all command	Enhancement to add show running-config interface <intf-id> all command	Added new command.	All Platforms
Unwanted print and error log is seen when one configure ip address on loop back interface.	Unwanted error logs and console messages are seen when configuring an ip address on a loop back interface.	Corrected error message conditions.	All Platforms
Image and Config download using HTTP through HTTP session is failing.	Download of configurations through HTTP fail on VxWorks switches.	Corrected download issue.	PC7024 PC7048 PC8024 PCM8024K PCM6248 PCM6220
VLAN is down with physical interfaces associated for that VLAN is up	VLAN routing interface is going down even though physical interfaces associated for that VLAN are up	Corrected issue when adding route to the database	PC8132 PC8132F PC8164 PC8164F
Mellanox ConnectX-3 Mezz card fails to link	Mellanox ConnectX-3 Mezz card fails to link	Corrected NextPage generation issue.	PCM8024K
Power negotiation fails with Cisco 9971 IP Phone	USB camera, when attached to a CISCO 9971 Phone fails to power up when using PoE power negotiation.	Corrected error in Power TLV handling.	PC70XXP
NetLogic XLP unaligned access patch	Occasionally, in the Netlogic processor, an unaligned memory access can cause the processor to hang.	Implemented the recommended register settings to handle this condition.	PC8132 PC8132F PC8164 PC8164F

## Release 5.1.3.7

Summary	User Impact	Resolution	Affected Platforms
Switch crashes IpMapForwardingTask and Interrupt Thread process.	Random switch crashes are occurring in the IpMapForwardingTask and Interrupt Thread process.	Resolved VRRP semaphore deadlock.	All Platforms
Switch crash when VRRP configuration applied.	Switch management becomes unstable after saving VRRP configuration and switch crashes eventually.	Resolved VRRP semaphore deadlock.	All Platforms
Stack member unit crash with "hapiMcAsyncTask"	Random switch crashes are occurring in the "hapiMcAsyncTask"	Corrected failover issue with multicast routes	All Platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Stack member reboots with task bcmRPC	Random switch crashes are occurring in the bcmRPC task.	Corrected problem when all RPC buffers are exhausted.	All Platforms
WebUI shows the temp status as medium, while the CLI status shows good temp	WebUI is showing medium temp, while the CLI is showing good temp	Corrected temperature value issue when displaying temperature in the WebUI.	All Platforms
MIB Walk on blade switches not returning the same results	Two different PowerConnect modular switches should return the same value for hardware health MIB.	Corrected data mismatch issue.	PCM8024-k PCM6348
After failover, VLAN is getting associated with physical interface.	After master is rebooted and stack failover to standby completes, the VLAN is getting associated with physical interface instead of just the port channel interface.	Corrected VLAN association and ports state mismatch between warm start and cold boot.	PC70XX
After failover, the spanning-tree status of the physical interface is transitioned from discarding to forwarding	After master is rebooted and stack failover to standby completes, the spanning-tree state of the physical interface is transitioned from DSC state to FWD state.	Corrected ports spanning-tree state transition between warm start and cold boot.	PC70XX
SSH related switch crash	SSH session to switch will occasionally result in crash if SSHv1 with public key authentication is used.	Corrected memory allocation issue.	All Platforms
OpenSSH Vulnerability issue: CVE-2012-0814	CVE-2012-0814 vulnerability addresses: Debug information is sent to SSH clients and this debug information includes private information	Applied OpenSSH recommended fix.	All Platforms
Using WebUI to set fields Dynamic VLAN creation and GVRP Registration issue	In WebUI, setting the fields "Dynamic VLAN creation" and "GVRP Registration" to "enable" actually sets them to "forbidden".	Corrected WebUI to accurately reflect operation requested.	PC70XX PC81XX
Error with temperature status reporting	Temperature status does not transition through "Medium" on the way to "High"	Corrected temperature status reporting for medium state.	PCM6220 PCM6348 PCM8024 PCM8024-k
dot1sBpduReceive(): Discarding the BPDU, cannot get buffer from buff pool log message	Log message is being thrown for an incorrect state.	Corrected display of error message for invalid state.	All Platforms
One switch intermittently doesn't join a stack after reboot from CLI	Upon reboot from the CLI a switch intermittently does not rejoin the stack.	Corrected timing issue with communications between master and slave units.	All Platforms

nimTask crash on stack while routing traffic with OSPF enabled	Occasionally the stack will crash in the minTask when routing OSPF traffic.	Correct processing delay that resulted in this crash.	PC70XX PC8024
No Receive Discards counter available	No Receive Discards counter available in the CLI	Added Receive discards counter to the CLI command "show statistics"	All Platforms
SNMP Product Status OID does not change after a fan/power failure	productStatusGlobalStatus OID (1.3.6.1.4.1.674.10895.3000.1.2.110.1.0) does not change after a fan/power failure	Corrected status change of power supply when power supply fails and switch remains powered through the other power supply.	PC8024/PC8024F
SNMP OID not incrementing snmpEngineBoots	snmpEngineBoots OID (1.3.6.1.6.3.10.2.1.2) not incrementing on switch reloads.	Added functionality to increment snmpEngineBoots OID value.	All Platforms
Software routing when using secondary SVI	When a secondary VLAN Interfaces are configured on the same VLAN, routing among those networks can cause the CPU utilization to become high as it is performed at the software layer.	The ip redirects command now makes use of hardware functionality in global and per VLAN mode. This allows ICMP redirect to be efficiently disabled on a specified port.	All Platforms
IPv6 PIM Multicast traffic stops working with MFC-V6 error messages	IPv6 PIM Multicast traffic stops working and MFC-V6 error messages are output	Corrected a synchronization issue for received port of the IPMC entry	All Platforms

### Release 5.1.2.3

Summary	User Impact	Resolution	Affected Platforms
Switch crashes every 30-40 days while SNMP monitored	Telnet login/logout through SNMP causes a buffer leak that results in a crash.	Corrected problem with buffer leak.	PCM6220 PC70XX
Stack reporting random failed PSU's and fans	Stack occasionally reports failed power supply fans erroneously.	Corrected problem resetting power supply assert.	PC8132 PC8132F PC8164 PC8164F PC70XX
Routing issue, null address in ARP table after VLAN manipulation	ARP replies destined to the switches L3 MAC address will occasionally be dropped.	Corrected problem when removing L3 host policy when a port is removed from a VLAN.	All 5.1 supported platforms
Pulling 3 out of 4 stack cables will result in loss of connectivity & STP topology change	Pulling 3 out of 4 stacking links leaving one remaining stack link will separate the stack.	Corrected a problem with resolving the stack trunk to one link.	All 5.1 supported platforms
Interface in static LAG goes into inactive state while physical interface is up	When a static LAG member flaps, the remaining LAG members will occasionally deactivate even though the physical link it up.	Corrected conflict with active LAG members when one LAG member's physical interface flaps.	PCM6348 PC70XX
Wireless client EAPOL authentication failing	Link local EAPOL frames are dropped as per the RFC.	Enhanced EAPOL handling to allow pass through of EAPOL packets.	All 5.1 supported platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

TACACS not possible to use special characters in password when created using GUI	TACACS passwords only allow alphanumeric characters	Changed TACACS password handling to allow all printable characters.	All 5.1 supported platforms
SCP or SFTP file transfers to FreeBSD and Mac causes switch to crash	SCP file transfer causes fatal kernel task-level exception crash.	Corrected SCP loop error.	All 5.1 supported platforms
serial console does not respond to any input when using USB to serial converter	Serial to USB converter will not work when being used for console connections.	Corrected UART reset problem.	PCM8024-K
UDLD connection issue	UDLD disables both physical ports by putting them into STP discarding state	Corrected UDLD protocol problem.	All 5.1 supported platforms
Switch fails to establish fip-snooping sessions	FCoE logical link occasionally fails to establish.	Corrected FCoE TLV problem.	All 5.1 supported platforms
stack crash with Log points to DMA failed:	DMA operation fails occasionally.	Corrected DMA coherency problem.	PCM6220 PCM8024 PCM8024K PCM6348 PC70XX PC8024
SSH and Telnet not working	SSH and Telnet not working when failover to the standby unit of the stack.	Corrected problem when creating the new socket.	All 5.1 supported platforms
VLAN ACL blocks traffic across stack members	VLAN policy was occasionally being applied on stack ports.	Corrected problem that allowed VLAN ACLs to be applied to stack links.	All 5.1 supported platforms
Stack master reboot forces the combo ports of the standby unit to Duplex Full mode	Stack master reboot forces the combo ports of the standby unit to Duplex Full mode	Corrected problem detecting active copper or fiber connection.	All 5.1 supported platforms
VoIP VLAN reply not being sent via CDP/ISDP	VOIP phones won't receive Voice VLAN configuration from switch if there is an ISDP entry on a port ID which is one port less from VOIP phone connected port.	Corrected Voice VLAN indexing problem.	All 5.1 supported platforms
Stack routing issues	Whenever a reload is done on a slave unit, the trunk fails to synchronize with the newly added unit causing routing to that trunk to fail.	Corrected trunk port synchronization problem.	All 5.1 supported platforms
MS NLB cluster not reachable after rebooting the stack	NLB cluster not reachable after rebooting the stack due to trunk ID assigned to static MAC address.	Corrected trunk ID update problem.	All 5.1 supported platforms
SSLT: SSL_ERROR_SYSCALL on https web gui login, switch hangs.	The ssltask consumes too much CPU when try to open web page causing the UI to hang.	Corrected sslt task socket write problem.	All 5.1 supported platforms

## Release 5.1.1.7

Summary	User Impact	Resolution	Affected Platforms
Switch crashes in tIomEvtMon() task once per week.	FRU service tag value updates from CMC might result in buffer overflow as service tag and other related tag fields are updated in the switch.	Correct buffer overflow.	PCM6220 PCM6348 PCM8024 PCM8024-k
Switch crashes in tCptvPrtl task.	Switch crash occurs in captive portal after a reload which brings down the entire switch	Corrected captive portal initialization problem	All 5.1 supported platforms
Stack member crash with "SDM Template mismatch" error	Switch crash occurs occasionally when an SDM Template id mismatch occurs.	Corrected the SDM Template ID problem so that invalid SDM template ids will be ignored.	PC8132 PC8132F PC8164 PC8164F
Stack member crash when "ISO count mismatch has been detected"	Switch crash occurs occasionally when the stack unit detects that it is isolated.	Corrected a stack data plane communications problem.	PC8132 PC8132F PC8164 PC8164F
Stack member crash from DMA hang	Switch crash occurs occasionally when packet DMA from the switching fabric to the CPU stops.	Enhanced DMA retry logic to allow DMA status information to update completely.	PC8132 PC8132F PC8164 PC8164F
Stack member crash in mcastMapTask	Switch crash occurs occasionally with routing and multicast traffic.	Corrected multicast routing problem.	PC8132 PC8132F PC8164 PC8164F
Stack master can move on stack reload	On a stack reload the stack master can move to a different switch based on the plug-in modules being used.	Corrected stack master timing problem when 10GBaseT plug-in modules are used.	PC8132 PC8132F PC8164 PC8164F
iomEventLog() might result in switch crash	Communications error in the m1000e Chassis CMC can result in a crash.	Corrected index range error on data received from the CMC	PCM6220 PCM8024 PCM8024K PCM6348
Switch crash in DHCP server task	Switch crash in DHCP server task	Corrected memory corruption problem.	All 5.1 supported platforms
Stack member crash in bcmRLINK task	Switch crash in bcmRLINK task due to unit id being out of range	Corrected memory corruption in ATP process.	PC8132 PC8132F PC8164 PC8164F
Stack member crash in DMA processing	Switch crash in DMA processing due to memory corruption	Corrected in problem in cache coherency which was causing data corruption.	PC8132 PC8132F PC8164 PC8164F
Port detection mechanism fails with SNMP Query using Q-BRIDGE-MIB	dot1qVlanFdbId SNMP object returns incremental indexes of the VLANs.	Corrected problem so that the object will return VLAN IDs	All 5.1 supported platforms
Incorrect stats for "show logging email statistics"	"No of email Failures so far" in command "show logging email statistics" is incrementing even if there are no failures.	Corrected problem in checking for non-urgent messages.	All 5.1 supported platforms
Telnet to port 80 hangs management	Console hangs when telnet session to localhost is initiated	Corrected task communication problem in telnet tasks.	All 5.1 supported platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Switch Hangs after using Web GUI -> SNMP -> Access Control	Switch Hangs when navigating to SNMP -> Access Control -> Show All page	Corrected problem accessing access control data structure	All 5.1 supported platforms
MIB file parsing errors	Errors related to undefined objects in 802.1ag MIB are displayed when snmpwalk is performed on netsnmp software.	Corrected parsing errors.	All 5.1 supported platforms
WebUI config issues with pre-provisioned ports in stacked environment	Copy-from/Copy-to WEB UI functionality doesn't work properly on IE 8	Corrected copying for duplex parameters	All 5.1 supported platforms
Trunk port tags traffic after upgrading from v3.x firmware	Switchport mode trunk & switchport trunk commands changed from previous firmware version	Corrected configuration migration problem	All 5.1 supported platforms
Web UI issue attributed to ip local-proxy-arp setting	Attribute to ip local-proxy-arp enabled by default on routed VLANs if WebUI is used to configure.	Corrected default attribute.	All 5.1 supported platforms
Stack fail-over causing loss of access to ESX VM environment	Switch will send tagged traffic out of the ports in native vlan.	Corrected problem in native VLAN check.	All 5.1 supported platforms
PC70xx returns the chassis service tag as N/A instead of NULL	PC70xx returns the chassis service tag as N/A and it causes issue with network management system applications.	Corrected default value for chassis service tag.	All PC70xx platforms
IPv6 VLAN interface fails to handle size specification	ipv6 ping fails when the size parameter is specified	Corrected packet fragmentation problem	PCM6220 PCM8024 PCM8024K PCM6348 PC70xx PC8024
Need to throw ERROR/Warnings on switch when PIM SM neighbor exceeds 256 neighbor count	PIM SM neighbor count gets beyond 256 random neighbors gets deleted without any error or warning messages.	Add validation such that no new neighbors are entertained if the router maximum neighbor capacity is reached.	All 5.1 supported platforms
Traffic loss after restarting traffic after power cable pull/insert, high CPU utilization.	After restarting multicast traffic for hard power cycle of a switch in the network there may be multicast data lost.	Corrected problem in event notification logic.	All 5.1 supported platforms
OOB interface loses the static default gateway configuration after multiple failover	Out of Band interface state is down during initiate failover event causing default gateway configuration failure.	Corrected link state check in the service port.	PC8132 PC8132F PC8164 PC8164F
M8024-K switch can cause high fan speed with CMC 4.2	Temp range difference between M8024k and CMC with FW 4.2 and above causing chassis fan speed stuck at 100%	Modified fan speed change parameters and added new temperature handling logic.	PCM8024-K
All entries in IGMP snooping are added and deleted immediately in a specific time for 5 minutes	Group entries in IGMP snooping are added and deleted immediately in a specific time for 5 minutes	Corrected timer rollover problem that happens every 49.71 days	All 5.1 supported platforms



Manager is rebooted while doing clear config due to crash in mcastMapTask.	During multicast traffic flow, on initiating a NSF failover, the unit acting as standby crashes and there will be traffic loss.	Corrected data copy problem when check pointing MFC data.	PC8132 PC8132F PC8164 PC8164F
Routing issue, null address in ARP table after VLAN manipulation	ARP replies destined to the L3 MAC address will be dropped.	Corrected problem when removing ARP table entries	All 5.1 supported platforms
With Traffic Running, cannot PING VRRP IP from VRRP backup router	The ping packets destined to VRRP Master IP are coming in the same CPU CoS queue as the unresolved data packets. Since these ping packets are not prioritized, they are getting dropped at the CoS queues itself resulting in ping to fail	Corrected ping priority problem.	All 5.1 supported platforms

## Release 5.1.0.1

Summary	User Impact	Resolution	Affected Platforms
M6220 crashes when issuing command "show interfaces switchport po1"	Switch crashes when using this command	Fixed memory issue in a loop	All 5.0 supported platforms
Cannot apply ACL on VLAN 'out bound' direction from GUI	User needed to use CLI	Fixed the issue to be able to apply in both directions from the web	All 5.0 supported platforms
Default VLAN cannot be made static from GUI	Cannot change VLAN member ports settings	Fixed VLAN membership web page	All 5.0 supported platforms
Incorrect SFP interface log messages on stack	The wrong port may get reported in the trap notification	Calculate the correct internal interface number	Platforms that support XFP, SFP and SFP+ transceiver modules
SNMP management IP address can only be set from WebUI and lost after reboot.	command is missing in the CLI in Simple Mode	Added CLI command support	All 5.0 supported platforms
Simple mode In-band IP address missing after reboot.	"ip address vlan" command disappears from the running-config after reboot	Put "ip address vlan" after "port-aggregator group" commands in the text config	PCM6220 PCM6348 PCM8024 PCM8024-k
ARP entries are purged for unknown reason	L3 egress objects are not programmed correctly resulting in incorrect L3 forwarding.	Use the SDK init function to set defaults for egress object.	All 5.0 supported platforms
OOB Static IP unreachable after stack failover	After failover stack loses static IP address configured on OOB interface.	Proper checks prevent using the previous DHCP mode.	All platforms that support the OOB interface
http[s] authentication against RADIUS only allows privilege level 1 access	HTTPS authentication through RADIUS grants only read-only access.	parse RADIUS server response properly	All 5.0 supported platforms



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

SNMP v1/2 community manager address no longer functions with network address.	When a subnet IP is set as SNMP community IP address then snmp requests from hosts of that subnet are not accepted on the box.	Get the mask from the community IP address configured and set it instead of the hard coded value.	All 5.0 supported platforms
Switch service tag not displayed by "show system id" command	Switch service tag not displayed with "show system id" command	Added retry to get the Service Tag value	M8024-k, M8024, M6348
CLI commands are not authorized after Password Recovery	Enabling password recovery will not allow the user to run CLI commands on the serial console.	Fixed the issue to enable commands from serial console also	All 5.0 supported platforms
LINK UP on all interfaces during POST,	Links are UP and flapping during power reset and reloads.	Changed the CPLD and reset logic	PC8024 and PC81xx
FCoE -M8024-k setting TSA map to link strict and assigning bandwidth allocation to TC	In the CEE mode there is no way to specify the TSA mode in the ETS TLV	Check if any weight is configured for the TCGs, if so set the mode to ETS.	Platforms running DCBX and including ETS
Switch GUI forcing 100Mb speed on External ports when cloning port configurations	Switch GUI set all external ports to 100Mb speed when cloning port configurations.	Corrected port speed processing from WEB	M6348
PowerConnect M6348/General port GUI issue	Vlan membership information on web is displayed and applied incorrectly	Javascript fixed to pick correct enum values	M6348
M6348 - service tag not displayed in GUI	Service tag shows up as none on GUI	Synchronization issue fixed to retry and get the tag information	M6348
email addresses with underscore "_" are rejected	A valid email id with an underscore cannot be used	Underscore is now considered valid character	All 5.0 supported platforms
phone port configuration macro incomplete	The macro never returns and appears to hang	Fixed the issue and return error	All 5.0 supported platforms

## Release 5.0.1.3

Summary	User Impact	Resolution	Affected Platforms
Re-enable Auto Negotiation using GUI doesn't work properly	The Auto Negotiation can't be enabled back on "Port Configuration->Show All" page once it has been disabled.	Corrected error in Port Configuration page.	All 5.0 supported platforms
VLAN ACL blocks traffic across stack members	ACL prevented traffic from reaching destination	Prevented VLAN ACL from being applied to stack ports.	All 5.0 supported platforms
Power supply logging	Power Supply messages are only sent to the log file.	Elevated failure messages to ERROR severity	All 5.0 supported platforms

'no ipv4 or ipv6 address found in response for request id' error	'no ipv4 or ipv6 address found in response for request id' error message flooding the switch	Corrected problem that was causing extra error messages to be displayed.	All 5.0 supported platforms
phone port configuration macro incomplete	The phone port is missing some needed commands	Added missing commands to the phone port macro.	All 5.0 supported platforms
web session timeout	Web session would timeout regardless of the timeout setting	Corrected the hard timeout to be one hour.	All 5.0 supported platforms
RX Equalizer setting on Stacking ports.	RX Equalizer was not set on the stacking port which caused stacking errors to be reported.	Added RX Equalizer value.	All PC70XX Switches
interface speed options	Invalid speed options message is not clear	Changed the message reported when an invalid speed option is input.	All 5.0 supported platforms
Change PoE Disconnect Type to DC disconnect	PoE controller Disconnect Type was changed to DC Disconnect.	PoE controller Disconnect Type was changed to DC Disconnect.	PC7024P PC7048P
stacking with extension modules	Stacking with redundant stack rings caused packet flooding on the stacking links.	Corrected problem with stack link queuing.	All 5.0 supported platforms
DHCP Req pkts are not being forwarded to Voice VLAN Component	When using Avaya phone on a switch running dot1x, the phone will NOT get authenticated and thus will not boot	Corrected DHCP forwarding problem.	All 5.0 supported platforms
Netlogic memory and B0 CPU support	Netlogic memory and B0 CPU support	Added support for Netlogic memory and B0 CPU.	PC8132 PC8132F PC8164 PC8164F

## Release 5.0.0.4

Summary	User Impact	Resolution	Affected Platforms
OpenManage UI does not accept blank space character for port description	Port description does not accept space	Correction the port description validation to accept spaces.	All 4.2 supported platforms
"show spanning-tree detail" counters are non-zero for inactive interfaces	The user may think that there is traffic over interfaces that are supposed to be inactive as far as spanning tree is concerned.	Corrected the counters.	All 4.2 supported platforms
Unable to remove 0.0.0.0 as default gateway on OOB interface using the web.	The user may not be able to remove the default gateway for the OOB interface causing unwanted traffic to go over the OOB interface.	Added support for setting the gateway to 0.0.0.0.	All 4.2 platforms that support the OOB interface

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

When connecting via SSH, the user is not prompted to acknowledge the MOTD	The user may log in without having acknowledged the MOTD.	Add functionality to send the acknowledge question when new SSH connection is created, but after authentication.	All 4.2 supported platforms
"encapsulation" command is unavailable in interface range mode	The user could only set VLAN encapsulation on a single VLAN at a time.	Added support for the encapsulation command in interface range VLAN mode.	All 4.2 supported platforms
M8024-k OpenManage Web UI stack view display	The user could not get accurate information about a stack of M8024-k switches from the stack view web page.	Corrected the information displayed on the stack view web page.	PCM8024-k
"spanning-tree transmit hold-count" command's value is not reflected in show command	The user could not see the configuration of the hold-count parameter.	Corrected the output of the "show spanning-tree detail" command to include the configuration of the hold-count parameter.	All 4.2 supported platforms
Inconsistent behavior in single and range interface mode of "spanning-tree port	The user may be able to configure an invalid spanning tree port priority in range mode.	Corrected the error handling so that the invalid priority is not used.	All 4.2 supported platforms
CLI command "no passwords strength exclude-keyword" requires <keyword>	The user could not reset the excluded keywords to the factory default of no excluded keywords with a single command. It was necessary to remove each excluded keyword one at a time.	Correctly implemented the "no" form of the "passwords strength exclude-keyword" command.	All 4.2 supported platforms
Inline help for "spanning-tree loopguard" is incorrect.	The help text might lead the user to think the command only applied to a single port instead of all ports.	Corrected the help text so that it indicates that the command applies to all ports.	All 4.2 supported platforms
Some of the options of "show ip pim" command are not available in user EXEC mode.	Some of the options of "show ip pim" command are not available in user EXEC mode.	Added missing options to the CLI tree.	All 4.2 supported platforms
Configuration command "logging <hostname>" accepts more than 63 characters.	Configuration command "logging <hostname>" accepts more than 63 characters, but saves only 63 characters in running-config.	Added checks to return error when hostname is larger than 63 characters.	All 4.2 supported platforms

dot1dTpPortMaxInfo is displaying maximum frame size that includes MAC header.	dot1dTpPortMaxInfo is displaying maximum frame size that includes MAC header.	Excluded the MAC header length when retrieving the OID information	All 4.2 supported platforms
If a user attempts to create a certificate request with information that is not identical to the key generated, the user is not given an error/informative response letting them know there is a conflict between their key and their request.	No error message was given.	Added a message once an exit is issued from the request or generate command. This is to tell the user whether the operation was successful or not.	All 4.2 supported platforms
OIDagentInventorySupportedUnitExpectedCodeVer provides incorrect display string 1.0.176.0	agentInventorySupportedUnitExpectedCodeVer object returns incorrect values.	Made the OID that is in private MIB obsolete as it's not required.	All 4.2 supported platforms
<p>1. Changes are not applied to the correct interfaces on the pages "System-&gt;sFlow-&gt;Sampler Configuration" "System-&gt;sFlow-&gt;Poll Configuration"</p> <p>2. Incorrect error message is displayed when not configured Receiver index is applied to interface on "System-&gt;sFlow-&gt;Poll Configuration" page.</p>	<p>1. Changes were not applied to the correct interfaces on the GUI pages referred to.</p> <p>2. An incorrect error message was displayed.</p>	<p>1. Used initialized buffers.</p> <p>2. Correct the error message.</p>	All 4.2 supported platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

"show ip route configured ...longer-prefixes" reports that default gateway is not configured, which is incorrect.	The default gateway would not be shown on executing "show ip route configured"	Corrected the implementation of this command so that it functions correctly.	All 4.2 supported platforms
CLI command "show ip route 192.168.2.2 /24" not ignoring host bits.	The user would not always get the correct list of routes from the "show ip route" command.	Corrected the logic in the implementation of the "show ip routes" command so that the appropriate list of routes are shown, depending upon which optional parameters are given.	All 4.2 supported platforms
CLI command "show spanning-tree detail" missing information.	The user could not see the configured values for spanning tree max hops.	Changed the output of the "show spanning-tree" and "show spanning-tree detail" commands to include the configured value of max hops.	All 4.2 supported platforms
"ipv6 pim join-prune interval" command does not work	The user could not change the configuration of the IPv6 PIM join interval.	Corrected the implementation of this command so that it functions correctly.	All 4.2 supported platforms
Macro input string does not accept more than 20 characters	The interface string length is limited to 20 characters for the "macro global apply" command.	Increased the acceptable string length for the "macro global apply" command to 256 characters.	All 4.2 supported platforms
startup-config failed error message is displayed when finishing the Dell Easy Setup Wizard	startup-config failed error message is displayed when finishing the Dell Easy Setup Wizard	Corrected the implementation of this command so that it functions correctly.	All 4.2 supported platforms
In stacking environment, "show system temperature" command output is corrupted	CLI output for command "show system temperature" is corrupted when pagination is used.	Corrected pagination in the command handler.	All 4.2 supported platforms
Error message for port enable / disable on IE on 8024F combo ports	When a copper port was disabled, port was getting set in no negotiating mode.	Corrected by disabling negotiation on combo ports	PC8024F
Alignment issues in the output of "show voice vlan interface" command	The alignment issues make it difficult for the customer to read the page.	Corrected alignment issue	All 4.2 supported platforms

CLI command "show ip igmp snooping" output is truncated.	The displayed info is not complete on page.	Corrected the implementation of this command so that it functions correctly.	All 4.2 supported platforms
vrrp ip command accepts invalid IP addresses	Switch allowed user to misconfigure VRRP IP	Added checks to return error when invalid VRRP IP address is given.	All 4.2 supported platforms
CLI command "isdsp enable" does not work for a range of ports	User cannot enable isdp on range of interfaces	Added support to "isdsp enable" command in interface range mode	All 4.2 supported platforms
"show interface Priority-Flow-Control" command output is not formatted correctly	The user sees the info but it looks messy and is hard to read.	Corrected formatting issues	PC8024 PC8024F PCM8024-K
CLI command "show ip route 192.168.2.2 /24" not ignoring host bits.	The user would not always get the correct list of routes from the "show ip route" command.	Corrected the logic in the implementation of the "show ip routes" command so that the appropriate list of routes are shown, depending upon which optional parameters are given.	All 4.2 supported platforms
Port channel goes down during master failover.	The members of the stack other than the master unit and their port channels, i.e. the Standby units and their port channel interfaces, are now not affected by a master failover and the port channel stays up during failover.	Corrected the logic to check for active port channels in the new Standby master unit.	All 4.2 supported platforms
switches rebooting - possible crash dump w/ emWeb	The switch crashes when it receives the url with the maximum characters.	Corrected URL length problem	All
general mode vlan does not show up after a reload, it shows up in access vlan	The general mode for switchport won't work properly in several cases, such as, script apply, nsf failover and save and reload.	Corrected memory initialization problem	All
SNMP OIDs 1.3.6.1.4.1.674.10895.3000.1.2.1 10.7.x causing switch crash	Walk of any member of envMonFanStatusEntry and envMonSupplyStatusEntry with 67109251 index causes crash.	Corrected unit number range check.	All
Stack ARP Problem	ARP replies to a routing interface are not received at the CPU after clearing the config and reconfiguring the routing interfaces.	Corrected ARP reply policy problem	All
Stack member units port display is missing in web GUI.	Stack member unit ports were not displayed properly.	Corrected power LED element id name problem which was causing this display problem.	PCM8024-K
No response to ICMP with jumbo (ping)	Third IP fragment was being dropped in jumbo Ping packet.	Corrected jumbo Ping packet problem.	All

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Ports connected to Intel X520 NIC do not return online after reboot.	When customer is using the Intel X520 NICs, sometimes the ports never came back up after a reboot of the switch.	Corrected port configuration timing issue.	PC8024 PC8024F
switch reboots randomly	switch reboots randomly	Corrected memory corruption problem.	All

## Release 4.2.2.3

Summary	User Impact	Resolution	Affected Platforms
IP routing unexpectedly after reboot despite its not having been enabled.	Traffic will get forwarded by software when global routing is not enabled.	Correct the default action so that global forwarding is enabled for the hardware.	All 4.2 supported platforms
Telnet existing session is interrupted when "New Telnet Sessions" is set to "Block".	"New Telnet Sessions" are changed to Block, All the current telnet sessions are closed and using "Telnet Server Admin Mode" to set Disable will only block new telnet sessions.	Functionality was corrected so that "New Telnet Sessions" will only block new telnet sessions and "Telnet Server Admin Mode" will close all the sessions if the mode is Disabled.	All 4.2 supported platforms
OOB interface unreachable after failover	Out-Of-Band interface will be unreachable after a stack failover	Corrected MAC address for new manager.	PCM6220 PCM6348 PCM8024 PCM8024-k
Switch CLI help does not locate the 'initiate failover' command properly	Warning message printed during execution of the deprecated "movemanagement" command incorrectly states that "initiate failover" command is executed from privileged EXEC mode whereas it's available from stack config mode only.	Corrected the warning message	All 4.2 supported platforms
Timeout during SNMP walk on root	SNMP walk on root ends with timeout	Corrected delay that caused timeout.	All 4.2 supported platforms
"show interfaces switchport" command shows incorrect General Mode Tagged VLANs value	"show interfaces switchport" command shows incorrect General Mode Tagged VLANs value.	Corrected the display of the General Mode Tagged VLANs value.	All 4.2 supported platforms
Error while adding an access-list to an access-group	Error message when trying to apply ACLs to VLANs.	Corrected the condition that resulted in the error.	PC8024 PCM8024 PCM8024-k
Walk of agentDaiVlanStatsTable returns statistics for all the 4096 VLANs	Walk of agentDaiVlanStatsTable returns statistics for all the 4096 VLANs even they do not exist in the system	Corrected the VLAN Stats Table data.	All 4.2 supported platforms

OOB interface configured with default IP via Setup Wizard though not to do so	When the Setup Wizard is used the OOB interface IP address is incorrectly set to 192.168.2.1 static IP by default	Corrected the setting of the OOB interface IP address.	All 4.2 supported platforms
Unable to create VLAN ID and name VLAN in Web GUI	Unable to create new VLAN with its name using the Web GUI	Corrected the VLAN creation GUI	All 4.2 supported platforms
"Failed to get CPU cosq 0 drop counters, error -16" messages in logs	"Failed to get CPU cosq 0 drop counters, error -16" messages in logs	Corrected the retrieval of cosq 0 counters.	All 4.2 supported platforms
Default "ip address dhcp" command on VLAN 1 causing "failed to bind socket" error repeatedly	Default "ip address dhcp" command on VLAN 1 causing "failed to bind socket" error repeatedly	Corrected DHCP socket problem.	All 4.2 supported platforms
agentPortSpeed DuplexStatus SNMP MIB object documentation error	Mistakes in the agentPortSpeedDuplexStatus SNMP MIB object description	Corrected MIB object description.	All 4.2 supported platforms
ifIndiscards is still counting VLAN discards if the interface switchport mode is in trunk mode	ifIndiscards is still counting VLAN discards if the interface switchport mode is in trunk mode (acceptable frame type is all)	Corrected ifIndiscards counter collection.	All 4.2 supported platforms
Switch doesn't register all the 576 devices if LLDP-MED has all the optional TLVs.	Switch doesn't register all the 576 devices if LLDP-MED has all the optional LLDP-MED Location TLVs.	Corrected the allocation of LLDP-MED Location TLVs.	All 4.2 supported platforms
SNMP and LOG errors when setting ifAdminStatus	When setting ifAdminStatus "adminState 2d is not valid" errors are produced.	Corrected error check when using invalid testing options.	All 4.2 supported platforms
Cannot type input into external serial connector after reboot of switch	After reboot external serial connection can become inoperative.	Corrected initialization of serial connection.	PCM6220
Web GUI doesn't display port 24 if using Internet Explorer 9	Device View doesn't display one port on IE 9. (IE9 is currently unsupported)	Corrected problem for IE9.	All 4.2 supported platforms
Switchport general configuration, VLAN1 tagged not saved in running config	"switchport general allowed vlan add 1 tagged" is not displayed in running config	Corrected check of enabled VLAN.	All 4.2 supported platforms



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Cannot rename vlan1	Cannot rename vlan1 running v4.2.1.3.  It is correct that the default VLAN cannot be renamed (same as a Cisco switch).	Updated error message to reflect this behavior.	All 4.2 supported platforms
SNMP Port tag/untag issue	When setting VLAN un-tagging for a specific port using the dot1qVlanStaticUntaggedPorts object, All the other ports are automatically added to that particular VLAN as tagged.	Corrected the port un-tagging set.	All 4.2 supported platforms
DNS client error in logs and switch locks up and needs to be rebooted.	Upgrade of 3.1.4.5 to 4.1.0.6 DNS client error "osapiSocketRecvFrom returned error " in logs and switch locks up and needs to be rebooted.	Corrected service port link status during upgrade.	All 4.2 supported platforms
Terminal Length setting not working as in 4.1	Terminal length is not setting per-session is an enhancement scheduled for the next release.	Corrected a problem with terminal scrolling.	All 4.2 supported platforms
Trunk port multiple vlan assignment doesn't work properly after reboot	Trunk port multiple VLAN assignment doesn't work properly after reboot.	Corrected command parsing problem.	All 4.2 supported platforms
FIP snooping session is not getting established after script apply.	FIP snooping session is not getting established after script apply.	Corrected FIP snooping command problem.	All 4.2 supported platforms
"ip http secure-server" command not getting migrated from 4.1.0.19 build to 4.2.1.3 build.	ip http secure-server command not getting applied when we migrate from 4.1.0.19 to 4.2.1.3 release	Corrected command parsing problem.	All 4.2 supported platforms
Data loop in Simple mode when adding VLAN	A data loop occurs in the port-aggregator if a new VLAN is added to an interface.	Corrected the VLAN creation error.	PCM6220 PCM6348 PCM8024 PCM8024-k

## Release 4.2.1.3

Summary	User Impact	Resolution	Affected Platforms
The "show fiber optical-transceiver" command shows LOS even though link is up.	The "show fiber optical-transceiver" command was reporting incorrect values when optical transceivers that did not support diagnostics were used.	Correct diagnostics so that diagnostics for unsupported transceivers are not displayed.	All 4.2 supported platforms

Unable to ping with jumbo frames set	MTU size configured on the combo ports will be lost after a save and reload and also when changes the media preferences are made.	Corrected the storing of the MTU size	PC72xx and PC80xx platforms
cpCaptivePortalWebLangCode. 1.1 displays en when mib says only supported value active (1)	The description of the cpCaptivePortalConfigWebLangCode object doesn't correspond to the values it returns.	Corrected the description in the fastpath_captive_portal.mx file	All 4.2 supported platforms
LLDP Assignment of port ID for Port-Description TLV	When Port-Description is set as no description in LLDP port configuration, the TLV should contain the Port Interface name as the port description by default instead of 0.	Corrected the default Port-Description.	All 4.2 supported platforms
The CLI shows incorrect media type 10GBASE-T for fiber ports	The "show interface advanced firmware" shows incorrect information under "Type" column.	Removed the Type column which was not valid.	All 4.2 supported platforms
Can't assign a name to a VLAN	Config migration for the "name <vlan name>" command was not correct.	Corrected the config migration for the "name <vlan name>" command.	All 4.2 supported platforms
No default route or static showing in ip route table	"Show ip route" commands will not display route even though there were routes in the router(static routes, ospf routes) for terminal length 0.	Corrected the display of the "Show ip route" command.	All 4.2 supported platforms
CLI command "show dot1x users" is missing	CLI command "show dot1x users" is missing	Corrected the command tree for the "show dot1x users" command.	All 4.2 supported platforms
Missing port membership from SNMP (dot1qVlanStaticUntaggedPorts and dot1qVlanStaticEgressPorts)	Changing VLAN configuration for general mode affected trunk mode configuration and there from the port membership returned via SNMP.	Corrected the issue.	All 4.2 supported platforms
The VRPP track port priority changes in the running config	The VRRP track port priority in the running config is retrieving the operational value instead of the configured value.	Corrected the retrieval of the configured value	All 4.2 supported platforms
Firmware won't allow domain names with hyphen "-" in logging email	The hyphen is part of the allowed characters available for the email address.	Added the hyphen to the allowed characters for email addresses.	All 4.2 supported platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Internal ports are up during most of the switch POST	Internal ports were up while switch is booting, this was causing traffic loss in network.	Corrected the initialization of the internal ports. CPLD Code Update is required. 1. Update the CPLD using the command 'dev cpldUpdate' Console#dev cpldUpdate 2. Power cycle the switch. (Power Cycle from CMC WebUI. Do not run "reload" from the console prompt)	PCM8024-K
Continuous log message at default settings	POE log message comes up during power up sometimes.	Removed unwanted message.	PC7024P/PC7048P
DNS client error	The meaning of the DNS error message: "DNS Client: osapiSocketRecvFrom returned error for addr 0x1214BCA8" is unclear.	Corrected the text of the message.	All 4.2 supported platforms
VRRP Intermittent Connectivity Issues	Ping to a remote host will not work if switch acts as VRRP master	Corrected a VRRP communication issue.	All 4.2 supported platforms
VLAN membership port names not consistent in GUI	VLAN membership port names are not consistent.	Corrected the port numbers displayed in the GUI.	All 4.2 supported platforms
Radius crash	Sometimes switch crashes when receiving of Radius packets	Corrected the crash.	All 4.2 supported platforms
In a Stack, the "show system temperature" CLI command breaks CLI	CLI output for command "show system temperature" is corrupted when pagination is used because the stack displays much more data.	Corrected the pagination issue.	All 4.2 supported platforms
QOS on port channel	There is no way to see the match packet counts of a policy-map on a port-channel.	Command "show policy-map interface port-channel <port-channel number>" was added.	All 4.2 supported platforms
Dropped VLAN frames are included in Discards counters.	Customer is really not able to use this counter to monitor their network outage activity.	Corrected by not ignoring the dropped VLAN frames in the Discards counter	All 4.2 supported platforms
PC7048 Combo ports are not passing traffic.	Combo ports are randomly not transmitting traffic, but receiving frames when media type preference set as SFP	Corrected by adding a property to bypass the lane initialization when media-type preferences is set.	PC70xx
Order of switchport commands in running-config changed	The "show running-config" command shows the detailed switchport configuration before the switchport mode. This caused problems with some scripts.	Corrected the order of running-configuration output.	All 4.2 supported platforms

## Release 4.2.0.4

Summary	User Impact	Resolution	Affected Platforms
PowerConnect sFlow implementation is not per specification	sFlow implementation is not per specification	Issues corrected and passes conformance test	All 4.2 supported platforms
Using config wizard to setup 8024 causes iscsi error messages off out-of-band in console	Doesn't affect any iscsi traffic. Constant log messages with the error "Can't create static rule".	Issue is corrected.	PC8024
8024 stack does not follow similar banner execution for console, telnet and ssh	If a user logs in via console - motd and login banners are executed If a user logs in via ssh - only exec banner is executed If a user logs in via telnet - all 3 banners are executed	Behavior is now as follows:  Add motd banner display for telnet connection before motd acknowledge question is asked.  Remove motd banner after motd acknowledge question.	All 4.2 supported platforms
Simple Switch should have FC enabled by default	FC not functional	FC is enabled by default in simple switch mode.	All 4.2 supported platforms
OSPF error message after reboot	With 128 IPv4 & IPv6 interfaces & OSPF configured a reboot caused the following error messages to be generated: Failed to send message to OSPF mapping thread in ospfMapRoutingEventChangeCallBack()  These lost events could lead to incorrect routing.	Issue has been corrected.	All 4.2 supported platforms
show crypto key mypubkey generates two error messages	After generating DSA & RSA keys, executing the command "show crypto key mypubkey" generates the following error messages:  <187> APR 23 09:09:22 192.168.1.2-1 OSAPI[162603392]: osapi_file.c(657) 426 %% File close failed for descriptor 37  <187> APR 23 09:09:22 192.168.1.2-1 OSAPI[162603392]: osapi_file.c(657) 427 %% File close failed for descriptor 37  There is no impact on the keys themselves.	Resolved	All 4.2 supported platforms
Web GUI ARP table does not match the CLI ARP table	The Web GUI does not display the static/local ARP entries. However, once an external port is linked up some, but not all, of the Static/local appear in the Web GUI.	All ARP entries are now shown.	All 4.2 supported platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

The copper auto negotiation process fails at 100mb FD and fails to link up	The copper ports 1-24 fail on 8024 to negotiate at 100Mb FD.	8024 copper ports negotiate to 100M FD.	PC8024
PCM6220 - Wrong information for current link status in port configuration page on the GUI	The current stacking port status does not display "stacking linkup"	The web stack display has been updated to accurately reflect the correct information as well as address some style issues.	All 4.2 supported platforms
PC8024 - VLAN membership change on interface affects unrelated interface	If user changes VLAN membership configuration on trunk port via the WEB he loses ports configuration on access ports and access ports are put into default VLAN.	Issue is resolved.	All 4.2 supported platforms
Implement dot1qVlanStatic Table in M8024-K	The dot1qVlanStaticTable is not available on M8024-k.	the dot1qStaticVlanTable is implemented for the M8024-k	All 4.2 supported platforms
Trunk mode native vlan implementation not compatible with Cisco	Native vlan implementation is incompatible with Cisco. Switch will egress native vlan traffic as tagged and Cisco will drop ingress tagged native vlan traffic.	Implementation of native vlan changed to be compatible with Cisco.	All 4.2 supported platforms
PCM6220 - Switch hangs when user tries to transfer a file from the flash to the server using sftp	Switch hangs and needs a hard reboot.	None – issue is resolved.	All 4.2 supported platforms
No message logged for "Max number of SSH login sessions exceeded"	The switch does not log an error message when the maximum number of SSH sessions has been exceeded.  The switch does accept 5 SSH sessions normally, when the 6th session connection is attempted via SSH, the connection is refused, but no error message is logged.	A Log message "Unable to find a free connection. Exceeded the maximum number of allowed connections." has been added.	All 4.2 supported platforms
CLI command "show ipv6 interface" does not paginate correctly	The CLI command "show ipv6 interface" does not paginate correctly when a large number of interfaces/addresses are configured.	Pagination mechanism corrected.	All 4.2 supported platforms
2nd and 4th block of copper ports 5-8 and 13-16 think they are fiber ports, possible problems	Ports report to be fiber ports and not copper ports.	Corrected error checking logic to correctly select fiber ports for fiber diags and copper ports for copper diags.	PC8024/PC8024F

WebGui Secure Shell SSH Remote Access	On the WebGui under Management Security,  Secure HTTP, Secure Shell does not work on the Web UI	Issue is corrected	All 4.2 supported platforms
Web UI MSTP Instance pull down menu displays 4k MSTIs	In the "MSTP Interface Settings" page of the Web UI, the Instance pull down menu has a range of 1-4094 MSTIs.	Issue is corrected	All 4.2 supported platforms
Flowcontrol negotiation issues with 10GBase-T module	Flowcontrol negotiation issues between 6200 and 8024/8024F	Driver update applied.	PC8024/PC8024F
PC8024 - GUI - Under Port Configuration page get error on 10GB ports when you change any setting	When you change the port setting, for example the duplex settings or description, from the GUI under switching -> Ports -> Port Configuration you will get outputs error when changing port settings on 10G ports. The popup says 10G speed is invalid. Error message attached. This is a problem with code version 4.1.0.6 under the GUI no problem when using the command prompt.	Erroneous pop-up message removed.	All 4.2 supported platforms
Unable to config secure ssh from web interface. error 'sshcfg_load start' missing pops up	Unable to configure Secure Shell from web interface. Error pops up.	Corrected web page	All 4.2 supported platforms
Web interface fails to provide an iSCSI web page when selecting the iSCSI item.	The web page for iSCSI fails to open when selected with OpenManage. .	Corrected web index page	All 4.2 supported platforms
Line "no passive-interface V132" in startup-config does not get loaded on startup	The following is displayed when startup-config is loaded:  Applying Global configuration, please wait ... Applying Interface configuration, please wait ...  ***** The following lines in "startup-config" failed:  ***** Line 57:: no passive-interface V132	Corrected stored config	All 4.2 supported platforms
Web GUI Admin Duplex setting on 10G Fiber ports	Switching-->Port-->Port Configuration Select a ten gigabit interface Te1/0/1 and you can see that "Admin duplex" and "speed" are still active and can be changed, but when you apply it gives an error message saying "Error failed to set current auto negotiation with disable".	Invalid selections disabled on page load.	PCM6348

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Advertise LLDP Management Address as IP Address assigned to OOB interface	LLDP advertises the switch's MAC address as the Management Address. Request to advertise the management IPv4 or IPv6 address instead.	The following behavior is now implemented:  1) Will advertise service port address if it is there 2) If service port is not there, then will send network address 3) If both of the above are not there and if it is routing interface will send IP address of the routing interface 4) If none of the above not there, will send MAC address.	All 4.2 supported platforms
PCM6348 - Log message output	Messages repeated in the switch logs <190> APR 28 19:39:22 10.1.208.10-1 STATSMGR[239558880]: collector.c(1066) 3445 %% Failure in function collectorGet <190> APR 28 19:39:22 10.1.208.10-1 STATSMGR[239558880]: presenter.c(102) 3446 %% ERROR!! Failure in preStatsGet 0x0002011e <188> APR 28 16:40:31 10.1.208.10-1 ARP[301140128]: ipmap_arp_api.c(855) 3325 %% Received ARP Reply on interface V1208 with bad target IP address 255.255.255.255. Sender IP is 10.1.209.60, sender MAC is 76:f7:b9:cf:06:7e.	SNMP walk/gets on counters for CPU/vlan routing ports not supported by platform no longer log a warning message	All 4.2 supported platforms
Firmware missing port VLAN membership in the GUI	Port VLAN membership will not be shown in the GUI.	Web code updated to display VLAN membership	PCM6220
M8024 - 1GB link being negotiated on 10GB Intel X520-KX4	The M8024 is negotiating 1GB speed connection with the 10GB X520-KX4 Intel card in the blade server. Issue is only present with new	Incorrect pre-emphasis values have been corrected.	PCM8024
Feature request - Display "client-DUID" in DHCP binding table.	The "Client-DUID" is used to uniquely identify an individual host receiving DHCP address configuration. In the case of a multi-homed host, it is possible to determine that the host has multiple bindings for different interfaces and which interfaces belong to each host.	Client-DUID parameter has been added to show "ip dhcp binding" command output.	All 4.2 supported platforms
clock summer-time recurring EU offset 60 zone "GMT" not offsetting the time by 60 minutes	Time change offset is applied early.	Day of month calculation has been corrected.	All 4.2 supported platforms

M6220 - Simple mode, VLAN setting not active when move port to another group	Modular switch in Simple mode. Interfaces have VLAN settings different from default. If you move port from one aggregation group to another, VLAN settings are retained and are listed in running config but it is not active until system is rebooted or VLAN information removed and reentered again.	None – issue corrected	All 4.2 supported platforms
SSH configuration not restored after reboot	SSH config is not restored after reboot.	ssh configuration saved	All 4.2 supported platforms
PC8024 - VLAN trunk assignment CLI change	On 4.1.0.6 if VLANS are assigned to a trunk, the switch CLI will display the VLANS not assigned instead of the VLANS that are assigned	VLANs are displayed in positive format, i.e. assigned VLANs are displayed.	All 4.2 supported platforms
Web UI displays incorrect session timeout duration	After the browser session timeout (default 10 minutes), Web UI displays incorrect session timeout duration in the message "Your session had been inactive for more than 240 minutes"	The displayed message was corrected.	All 4.2 supported platforms
PC8024 - Secure HTTP Random Characters - 4.1.0.6	If you go to system management, Secure HTTP, you will see random characters populating the fields. Even if you delete these entries and re-populate with valid chars, it will repopulate with invalid characters making it impossible to generate a cert using the web interface.	The random character rendering has been corrected.	All 4.2 supported platforms
Upgrades to 4.1.0.9 are causing network outages. The wizard from 4.1.0.9 fails to setup interfaces	The wizard in 4.1.0.9 fails to create any or very few interfaces and there was no config for any or very few of the ports, thus, the ip, icmp traffic was not working between ports as well.	Issue with switch upgrade has been resolved.	All 4.2 supported platforms
PC6220M GUI shows stack-ports down but CLI does not. In previous version issue didn't exist	The issue using CLI stack ports shows up and counters shows no transfer rate but GUI shows stack ports down.	Web shows stack ports up if they are up	All 4.2 supported platforms
M6220 - Routing fails on VLAN	Customer has multiple M6220 switches, and as part of a network change they wanted to remove a VLAN routing interface that was no longer in use. When they removed the IP address from this VLAN, they lost routing across the entire switch.	Ports are now checked to ensure they are not part of other routing VLANs before clearing the ARP policy on the port.	All 4.2 supported platforms
MIB walk crashes switch	SNMP MIB walk crashes switch.	A large array is allocated statically instead of on the stack.	All 4.2 supported platforms



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

M8024 - No password min length error using web GUI	On the web GUI-->system-->management security-->password management,  If the password min length is unchecked and applied, there is an entry in the running config for "no passwords min-length". This can be verified through CLI. After this, on enable passwords page if we try to set a password which is any length less than 8, we get an error message as shown in the attachment.	Password ranges are now allocated dynamically on web pages.	All 4.2 supported platforms
Bug in Simple Switch GUI.	Once you select the Tagged-Vlans, there is NO way to unselect them again via GUI. Using command-line configuration is the only way to unselect those.	Tagged VLANs can be unchecked in simple mode	All 4.2 supported platforms
M6348 simple mode issue with 10G ports in aggregator group	Can't remove what running config says is there	Add interface command is corrected.	All 4.2 supported platforms
Banner motd configuration changes after reload.	The "banner motd" configuration changes after a switch reload.	Previously, the input mechanism ignored ANY lines beginning with an exclamation point. Now, the CLI engine will allow lines with a leading "!" in the banner	All 4.2 supported platforms
Error message via Web UI refers to "Management VLAN"	Attempting to assign an ACL to VLAN 1, via Web UI, generates an error message referring to the Management VLAN. "Error! Cannot Bind ACLs to Management VLAN."	the hard coded value has been removed in favor of the correct VLAN value	All 4.2 supported platforms
Web UI not generating error for out bound ACL & applies the config.	Binding an IP ACL as out bound to an interface, via Web UI, does not generate an error message. Furthermore, the config gets applied to the interface as an inbound ACL. When the same action is done via CLI, an error message is generated and the config is not applied.	Use of the direction object has been corrected.	All 4.2 supported platforms
Auto-neg option via Web UI is not grayed out for 10Gb fiber ports.	Auto-neg is an option in the port configuration via Web UI for 10Gb fiber ports. Ideally the auto-neg option should be grayed out for 10Gb fiber ports.	Auto-negotiation selection is disabled for 10G ports in the Web as auto-negotiation must always be enabled.	All 4.2 supported platforms
CLI command "show interface detail port-channel" locks up console session	The CLI command "show interface detail port-channel" generates the following errors:  Max number of lines in the scroll buffer reached. Output will be truncated.	The scrolling issue has been corrected.	All 4.2 supported platforms

Creating VLANs, assigning ports using vlan membership detail page causes removal from running-config	Using web GUI to create and assign ports via vlan membership detail page causes previous vlan ports and sometimes previous vlan to be removed from running-config.	VLAN creation addition/removal behavior is corrected.	All 4.2 supported platforms
Assigning ACL Priority to a VLAN interface does not get set via Web UI	When binding an ACL to a VLAN interface, via Web UI, the "Assign ACL Priority" field does not get set as it would if it were configured via CLI.	Web interface has been corrected.	All 4.2 supported platforms
Incorrect Model numbers and revision date in dellref.my	The last revision date has not been revised. This could lead a customer to believe they do not need to update their MIB file. LAST-UPDATED "200311210000Z" -- 21 Nov 2003 12:00:00	The MIB has been corrected. Administrators are advised to load the new MIBs when updating to this release.	All 4.2 supported platforms
Links do not show status	Link dependency CLI "show link-dependency" shows "Member ports" and "Ports depended on" port numbers along with group id, but does not show the status of the members or the depended-on ports.	The display has been updated to show the requested information	All 4.2 supported platforms
M8024 does not save complete MST vlan configuration	Show spanning-tree mst-config not working.	All MSTP configurations are now saved.	PCM8024
Need to increase the VRRP routing instances or VRID to greater than 50	Previous limit was 20.	VRRP instances are now set to 50.	All 4.2 supported platforms
On the 8024F, inserting or removing the cable on ports 1 and 2 causes both ports to shut down briefly	The PowerConnect 8024F ports 1 and 2 will flap briefly when cables are removed and reinserted.	All inter-phy operation is fixed.	PC8024F
The CLI command terminal length is not setting terminal length value	When executing the command terminal length <value>, the value is not updated after execution.	Terminal length settings now take effect immediately.	All 4.2 supported platforms
The Service tag is being deleted on modular platforms.	When executing the "show system id" is not showing the service tag on modular platforms.	The service tag was accidentally being deleted and is now being saved correctly.	All 4.2 modular platforms.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Release 4.1.1.9

Summary	User Impact	Resolution	Affected Platforms
PC7048R-RA switch has boxes req cpu process 38-54% utilization with single power supply.	PC7048R-RA switch has cpu process boxes req running between 38-54 % utilization if it's running either only with primary or secondary power supply.	Corrected CPU utilization issue when running with one power supply.	PC7048R-RA
Router crashes on OSPF network type change.	The switch can crash when changing the configuration from the default of broadcast to point-to-point.	Corrected process synchronization problem	All Platforms
Occasional crash when configuring VRRP.	With routing globally disabled, bouncing VRRP on a host interface occasionally causes a crash.	Correct the transition between routing being disabled and routing being enabled.	All Platforms
Cannot create Dynamic LAG with Interface range command	Dynamic LAG cannot be created from CLI using interface range command.	Correct the command syntax to "auto " instead of "active"	All Platforms
PC8024 cannot forward packets on port9 to port16 while linked on at 100Mb.	PC8024 cannot forward packets on port9 to port16 while linked on at 100Mb.	Correct interoperability problem between the PHY and the switching core.	PC8024 PC8024F
Show fiber-ports optical-transceiver is not displaying the correct interface numbers.	Instead of reporting on exact ports that had modules, diagnostics were reported on the ports that did not have modules	Corrected register problem when accessing the SPF+ ports	PCM8024
VRRP routing instances increased to 50.	VRRP routing instances increased to 50.	Increased VRRP routing instances table.	All Platforms
DHCP on in-band and out of band ports	The warning message about IP address conflict is not printed in case DHCP is configured on in-band and out-band ports and they both receive an IP address from one subnet.	Add warning message in case offered IP address is conflicting with the configured one on another port	All Platforms
Config commands did not migrate correctly from version 3.1.5.13	Command "spanning-tree mode mstp" doesn't migrate correctly from version 3.1.5.13.	Correct the command tree to migrate the old syntax.	All Platforms
Auto-neg option via Web UI is not grayed out for 10Gb fiber ports.	Auto-neg option via Web UI is not grayed out for 10Gb fiber ports for the PCM8024-k.	Corrected the Web UI.	PCM8024-k
Simple mode, VLAN setting not active when a port is moved to another group	if a port is moved from one aggregation group to other, VLAN settings are retained but not applied until reboot.	Correct initialization when port is moved.	PCM6220
Unable to configure secure SSH from web interface.	Error message 'sshcfg_load start' missing is returned.	Corrected Web page error.	All Platforms
Secure HTTP Random Characters	Random characters populate the Secure HTTP web page.	Corrected Web page data initialization.	All Platforms
IP PIMSM BSR/RP Mapping is not robust	When the RP or the BSR changes, the data traffic may get affected and in some case get software forwarded.	Corrected RP join processing.	All Platforms
Error messages when issuing a show statistics command while traffic running.	Accessing unsupported counters causes error messages to be displayed.	Change the logging priority of the messages for unsupported counters so that they are not output.	All Platforms

Summary	User Impact	Resolution	Affected Platforms
PCM6348 - Log message output	SNMP walk through unsupported counters cause error messages	Change the logging priority of the messages for unsupported counters so that they are not output.	All Platforms
Missing port VLAN membership in the GUI.	If switch has less than 24 ports, Port VLAN membership will not be shown in the GUI.	Corrected the VLAN port data issue.	PC70xx
Routing fails on VLAN.	Removing a VLAN routing interface causes routing to be lost across the entire switch.	Corrected the VLAN interface removal problem	PCM6220
PIM BSR join messages.	PIM Join messages using wrong RP Address	Corrected Join without a Prune condition.	All Platforms
PIM-SM Not all data passed down to the RPT.	When network re-configuration happens, the multicast traffic may not properly converge thus resulting in loss of some traffic.	Corrected Join condition.	All platforms
Port Configuration page gets errors on 10GB ports when any setting is changed.	Port Configuration page gets errors on 10GB ports when any setting is changed.	Corrected Web page error.	All Platforms
PIM-SM RP Fails to send Register Stops.	Register-Stop messages may not be sent out on the correct interface through to the First Hop Router.	Corrected Register Stops message error.	All Platforms
IGMPv3 querier sent in error with source address 0.0.0.0	Switch will get moved to non-querier mode if an IGMP membership query arrives with source address 0.0.0.0.	Corrected valid address check for membership query packet.	All Platforms
PIM-SM Joining messages using wrong RP address	PIM-SM Joining messages using wrong RP address	Corrected Join message processing.	All Platforms
Fails to reconfigure and forward multicast message	Switch fails to reconfigure and forward multicast messages following link failure	Correct an RPF information problem when link goes down.	All Platforms
DNS client error in logs and switch locks up and needs to be rebooted.	Error message "DNS Client: osapiSocketRecvFrom returned error for address 0xAABBCCDD" being logged	Corrected error in task that handles changes of the Service Port link status	All Platforms
PIM-DM Prune states expiring.	The router might end up sending Graft messages even though there are no intended hosts.	Corrected a PIM-DM timeout error.	All Platforms
Email alerts do not contain log message.	Current e-mail messages display in e-mail applications with a blank body, log message is not displayed.	Corrected error in email header section.	All Platforms
Log message "internal interface number 183 out of range" is seen.	Message: "nimCheckIfNumber: internal interface number 183 out of range" is displayed.	Corrected error in VLAN create web page	All Platforms
"no enable authentication" does not disable access to privileged EXEC over the telnet line	"no enable authentication" does not disable access to privileged EXEC over the telnet line	Corrected error in authentication processing.	All Platforms
dot1q_api.c error during MIB walk	If LAG port is configured as general trunk then log message is getting printed when snmpwalk is accessing the MIB OID agentLagSummaryAccessVlanID.	Corrected VLAN access error.	All Platforms
sFlow Timeout settings for CLI command	sFlow receiver timeout value should be optional	Changed receiver timeout value to be optional.	All Platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Resolution	Affected Platforms
sFlow: Limit of 32 for the number of interfaces for which sFlow can be enabled	Current limit of 32 for the number of interfaces for which sFlow can be enabled.	Changed the limit to allow all sFlow instances.	All Platforms
sFlow: Formatting errors with some of the records	Some of the sFlow records had formatting errors.	Corrected sFlow header problems.	All Platforms
sFlow: The sample Pool field is not being incremented properly	Sample pool field will not be incremented in the sFlow packet sent to the collector.	Corrected sample pool field error.	All Platforms
sFlow: The sFlow agent field isn't being filled in	The sFlow agent field isn't being filled into sFlow Packet.	Corrected problem adding sFlow agent address.	All Platforms
Stack module inserted in Bay 1 and SFP+ module in Bay 2	With the presence of stack module at bay1, SFP+ module in bay2 will not get detected until the stack-module at bay1 is removed.	Corrected error that prevented the detecting of SFP+ module in bay 2.	PCM6220
CLI "switchport general acceptable-frame-type" different options than GUI	The CLI "switchport general acceptable-frame-type" contains different options than GUI.	Options are now the same.	All Platforms
startup-config cannot be restored via tftp	TFTP script download or saved script validation will leave the Switch in an unusable state.	Corrected script validation problem.	All Platforms
"show ip ospf database" does not respect configuration of "terminal length 0"	The CLI handler of the "show ip ospf database" command does not consider the terminal length configuration.	Corrected terminal length configuration handling.	All Platforms
Occasionally, "clear config" from console triggers wio_api.c traceback	Occasionally, "clear config" from console triggers wio_api.c traceback	Corrected "clear config" internal message error.	All Platforms
Radius config stops working after reboot.	Radius config stops working after reboot, needs to be removed and re-added in order to work again.	Corrected error in Radius user authentication processing.	All Platforms
ISDP timers running fast.	ISDP entries are timing out and dropping off the list before the next update comes in.	Corrected an error in the ISDP timer disable processing.	All Platforms
VRRP hang	VRRP loss of mastership causes the switch to hang.	Corrected an error in the VRRP processing of the new IP address.	All Platforms
IPMC error messages and forwarding issue.	Error messages indicating that IPMC table are not set correctly in hardware.	Corrected error message processing which generated false error messages.	All Platforms
Dynamic LAG Ports are flapping/continuous trace messages.	LAGs do not stay up on combo ports.	Corrected an error in mapping the physical ports to a LACP logical port.	All Platforms
Simple Switch should have FC enabled by default	Enable Flowcontrol on simple mode.	Flowcontrol enabled on simple mode.	All Platforms
Need to change message on console when try to downgrade anything below 4.1.0.19 release for new DDR	If a switch contains new DDR, downgrading to 4.1.0.19 is not allowed.	Modified the downgrade message.	PCM8024 PCM8024-k (with new DDR)

## Release 4.1.0.19

Summary	User Impact	Resolution	Affected Platforms
Combo ports flapping when fiber port connected to certain other vendor switches	Users unable to reliably operate over combo ports	Corrected combo port flapping issue with new PHY firmware. Added new media-type command to configure the preference on a combo port	PC8024 PC8024F
New M8024/M8024-k cards have different memory parts requiring changes to DDR timings	User unable to downgrade to earlier version of firmware	No resolution. Newer IOMs do not support earlier versions of firmware.	PCM8024 PCM8024-k
10GBaseT ports do not come up	Unable to use 10GBaseT ports on PC7048R-RA	Corrected internal addressing of port. Ports now come up properly.	PC7048R-RA
Switch crashes when executing "show interfaces detail tel/2/1" command with no space between "te" and the unit/slot/port identifier	Service interruption due to crash	Issue has been corrected.	M8024 M6220 M6348 M8024-k
OOB Default Gateway does not save when using CLI setup wizard	There was no way to configure the gateway on Out-Of-Band interface.	Add functionality for configuring gateway on Out-Of-Band interface.	All Platforms
Upgrades to 4.1.0.6 are causing network outages. The wizard from 4.1.0.6 fails to setup interfaces	Ports on some devices will not attach.	Corrected the Configuration Wizard to properly apply the configuration to all ports.	All Platforms
The combo port is not coming up after performing repeated plug-out and plug-in.	The fibers port associated with Fiber / RJ45 combo ports may flap or not link up with certain other switches.	Add commands to allow operator to prefer or force RJ45 or SFP port selection on combo ports.	PC8024F/ PC8024
Line "no passive-interface V132" in startup-config does not get loaded on startup.	The "no passive-interface V132" configuration does not get loaded from the startup-config on startup.	Corrected the loading of the "no passive-interface V132" configuration.	All Platforms
Unable to configure Secure Shell from web interface.	Proper web page operation is prevented.	Web page has been corrected.	All Platforms
OpenManage web interface fails to provide an iSCSI web page when selecting the iSCSI item.	The web page for iSCSI fails to open when selected with OpenManage.	Web page has been corrected.	All Platforms
Wrong information for current link status in port configuration page.	Incorrect stacking link status is presented in the Web page.	Web page output has been corrected.	PCM6220
PFC sends packet after quanta extension received.	This can cause FCOE failures when using PCM8024-k as a transit switch between some switches.	Switch no longer sends packet after quanta extension received.	PCM8024-k
CLI command "show ipv6 interface" does not paginate correctly.	A large number of interfaces cause information to scroll off the viewing area.	Fixed the pagination for the command.	All Platforms
MOTD Banner appears at the wrong time.	MOTD and Login Banner is not visible before login for SSH users.	Fixed the banner processing function.	PCM6220

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Resolution	Affected Platforms
Summertime function running early.	The summertime function resets the time on the wrong week.	Corrected the function that returns the day of the week to account for particular months and leap years.	All Platforms
Switch does not save complete MST VLAN configuration.	The correct configuration was not being saved if there are more than 1K VLANs in a single MST instance.	Corrected the VLAN configuration buffer size.	PC8024 PCM8024
Switch failed to generate new RSA/DSA crypto keys.	"Failed to generate RSA key." message was produced and keys were not generated.	Fixed error condition when generating keys.	PCM8024
Banner MOTD configuration changes after reload.	After reload a MOTD with an embedded! Character will be truncated.	Fix the MOTD engine to not ignore the leading '!' character.	PCM8024
VLANs can get removed from running-config.	Creating vlans, assigning ports using the vlan membership detail page causes removal from running-config.	Corrected default VLAN checks when updating VLAN information.	All Platforms
Console session locks up.	CLI command "show interface detail port-channel1" locks up console session.	Corrected buffer overflow during "show interfaces detail" execution.	All Platforms
Fiber diagnostics reporting incorrect port type.	When running fiber diagnostics, Ports 5, 7, 8, 13, 15, 16 report to be fiber ports and not copper ports.	Fixed reporting of valid copper ports.	PC8024
BROADCOM-REF-MIB reporting incorrect values.	Incorrect Model numbers and revision date in BROADCOM-REF-MIB dellref.my	Model numbers which are described in dellref.my are corrected.	PC70XX
Switch crashes when full vlan range assigned to MST regions.	When the full range of VLAN instances is assigned to a MST region the switch crashes.	Corrected VLAN instance buffer overflow.	PCM6220
Config Wizard causes iSCSI error messages.	Using the config wizard to setup the PC8024 causes iSCSI error messages.	Correct the handling of iSCSI admin mode.	PC8024
SSH configuration not restored after reboot.	The 'ip ssh protocol 2' is not being included in the running configuration.	Corrected the ability to place 'ip ssh protocol 2' in the running-config.	All Platforms
1GB link being negotiated on 10GB Intel X520-KX4	Some internal links on the Modular switches will not link at 10Gb.	Corrected the port mapping to allow proper port configuration.	PCM8024 PCM8024-k
No message logged for "Max number of SSH login sessions exceeded"	When the Max number of SSH sessions is reached no error is logged.	Added an error message.	All Platforms
VLAN web page not updating.	When VLANs are removed using the web, the GUI doesn't display the ports that are members of the VLAN.	Corrected the fetch of current VLAN data.	All Platforms
No password min length error when using web GUI.	If "no passwords min-length" Is set an error results if the password is less than 8 characters.	Correct password length range check.	All Platforms
MIB walk crashes switch.	When running a large SNMP MIB walk the switch crashes.	Corrected a memory problem in the MIB walk.	All Platforms
Unable to deselect VLAN tags in web GUI.	Once Tagged-Vlans are selected there is no way to unselect them again via the web GUI.	Corrected the Web page that allows tagged VLANs to be unselected.	PCM8024 PCM8024-k



Summary	User Impact	Resolution	Affected Platforms
Access is allowed to files on the switch without log in permissions required	If the file name is known, the file can be downloaded through the web browser without having to be logged in.	Corrected the web process to require login credentials before downloading a file.	All Platforms
Switch crashes when downloading without the .stk extension.	Switch crashes when trying to download code without .stk extension through HTTPS using HTTP.	Corrected download web page.	All Platforms
Switch crashing when HTTPS session is enabled.	Switch is crashing when HTTPS session is enabled from CLI but not from WEB	Corrected task table memory size.	All Platforms
Switch crashing when trying to open more than 3 HTTPS sessions	Opening more than 3 or more HTTPS sessions will crash the switch.	Corrected task table memory size.	All Platforms
Mozilla Java Script error when selecting VLANs.	In Mozilla, when 1-4085 VLANs are *selected* in the web page for Tagged VLAN Java Script error appears.	Corrected the code looping error.	All Platforms
IE7 error when selecting VLANs.	In IE7, when 1-4085 VLANs are *selected* in the web page for Tagged VLAN IE7 error appears.	Corrected the code looping error.	All Platforms
SDRAM test does not run the specified number of iterations.	When running the SDRAM test a <cntl-c> must be used to exit the test.	Correct the SDRAM test iteration loop.	PCM8024-k
PCM8024-k Web page and help page mismatch.	The help page for the PCM8024-k Switching--> Network Security--> Dot1x Authentication--> Authentication Detail page did not match the page.	Corrected the help page.	PCM8024-k
VPD CRC check hang	When the switch boots, If the CRC check of the VPD fails, the switch will hang.	Corrected check for valid VPD before CRC check.	All Platforms
Packet Buffer Optimization.	Improved Performance with High Utilization iSCSI Workloads.	Improved performance.	PC70XX PCM8024 PCM8024-k PC8024 PC6348
PCM6220 Stack View needs PCM70XX styling	PCM6220 Web pages did not have the same styling as PC70xx.	Updated the PCM6220 web pages.	PCM6220

## Release 4.1.0.6

Summary	User Impact	Resolution	Affected Platforms
SSH crash - memPartAlloc: block too big	Reduced switch functionality.	Memory allocation issue is corrected and checked for memory leaks	All Platforms
PC M8024 switch reset out-of-band address to none when switchports were changed	Inability to access switches via OOB port.	The out-of-band address is maintained over switchport changes.	PCM8024
Web page shows IP address as '0.0.0.0' for '1.1.1.1' routing interface.	Potential operator confusion over switch operations	The web page output has been corrected.	All Platforms
Read-Only Web page is populating all configured IP and IPv6 ACL names when we select the ACL Name.	Potential operator confusion regarding web page operations.	The web page has been corrected to only populate the selected entry.	All Platforms



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Resolution	Affected Platforms
FAN LED graphic on web page needs to glow in RED when FANs are not operational (stopped).	Inability to determine switch status.	Web page has been corrected	All Platforms
Incorrect command is being displayed in running-config, when boot host dhcp is disabled.	Potential operator confusion regarding web page operations.	The running config now shows the correct configuration	All Platforms
Switch crashes while configuring max dynamic VLANs.	Network outage possible.	The PowerConnect does not crash when using maximum dynamic VLANs	All Platforms
Manager of the stack is changing when trying to learn maximum number of VLANs using GVRP.	Potential operator confusion regarding switch operations.	The stack manager does not change during learning with GVRP	All Platforms
Switch prompts to save config data when no changes have been made	Potential operator confusion regarding switch operation.	The switch no longer prompts to save config data if no changes have been made	All Platforms
Crash while RFC3918 Group Capacity test is running	Network outage possible.	The PowerConnect switch runs the RFC3918 test without crashing	All Platforms
'no' version of 'key' command is not implemented	Potential operator frustration with switch management.	The <b>no key</b> command is implemented to return the key configuration to the default.	All Platforms
Password is not accepting quotation ( " ) character	Potential operator confusion regarding switch configuration.	Passwords can be enclosed in quotes (contain embedded blanks). A password may not contain a quote. The accepted character set and length is documented in the CLI reference manual.	All Platforms
Incorrect warning message displayed while executing the command "boot system <unit> image1"	Potential operator confusion regarding switch operation.	The error message has been corrected to indicate that the unit selected for reboot does not exist.	All Platforms
IPv6 command displays wrong output	Potential operator confusion regarding switch operation.	The IPv6 output has been corrected to remove the duplicate display lines in <b>show ipv6 help</b> .	All Platforms
LLDP-MED log messages showing 5 sec difference in entry age out information	Potential operator confusion regarding switch operation.	The LLDP timer has been updated to account for processing skew.	All Platforms
DHCPv6 web issues	Potential operator confusion regarding switch configuration.	The acceptable character sets are documented in the CLI Reference guide.	All Platforms
LLDP MED application should not allow configuration of location and inventory transmit TLV's as underlying application not present	Potential operator confusion regarding switch configuration.	Location and inventory TLVs cannot be enabled for transmission in LLDP MED.	All Platforms

Summary	User Impact	Resolution	Affected Platforms
SysUpTime is not being shown correctly during an SNMP walk (Poll interval 1sec)	Potential operator confusion regarding switch operation.	The correct variable is used to write SysUpTime	All Platforms
Log messages need to be corrected on ip dhcp snooping rate limit scenario.	Potential operator confusion regarding switch configuration. Inability to diagnose network issues.	Interface representations in log messages use unit-slot-port format.	All Platforms
The <b>show ip vlan</b> command output is not proper after more-quit prompt is encountered, i.e. after around 16 routing interfaces	Potential operator confusion regarding switch configuration.	The paging has been corrected.	All Platforms
Invalid error port number displayed on log message when vlan is changed to forbidden mode from access mode	Potential operator confusion regarding switch configuration.	The error message is no longer issued.	All Platforms
The <b>banner motd XXXXX</b> does not appear in show running-config	Potential operator confusion regarding switch configuration.	All banner configuration appear in the running-config	PCM8024
Web page mac-vlan table too slow to load.	Potential operator frustration with switch management.	For certain browsers, paging has been implemented to speed up load times.	All Platforms
Confused between <b>ip default gateway</b> and <b>ip default route</b> (update manual with how to set a default route).	Potential operator confusion regarding switch configuration.	The ip default route command is deprecated. Use the <b>ip default route</b> command to set a default route.	All Platforms
Auto Install <b>show boot retry</b> count line needs to be left aligned by one space.	None.	The retry count alignment is corrected	All Platforms
Cannot Access Optical Transceiver Diagnostics Page if Multiple Submits done prior to initial refresh completing	Potential operator frustration with switch management.	This is a browser dependent issue (IE 6) that is not seen in later versions. The web session recovers after doing a refresh.	All Platforms
Error messages for non-existent stack members non-informative	Potential operator confusion regarding switch configuration.	The user can pre-configure stack units. If the stack unit does not exist for a switch configuration operation, an error message indicating same is issued.	PC70XX
Traffic is forwarding when IPv6 forwarding is disabled	Incorrect operational state in network.	The ipv6 forwarding command is deprecated. To disable traffic forwarding, use the <b>"no ipv6 unicast-routing"</b> in place of the <b>"no ipv6 forwarding"</b> command.	PCM8024
A LAG member comes UP if configured individually as no shutdown, even though the port-channel's state is down	Incorrect operational state in network.	LAG members are placed in the blocking state for dynamic LAGs and only come up when the LAG link comes up.	All Platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Resolution	Affected Platforms
Re-authenticate Now check box is not highlighted when edit check box is selected	Inability to configure switch.	The Re-authenticate Now check box is highlighted when the edit check box is selected	All Platforms
Block command is not seen in show running config through web and cli	Potential operator confusion over switch operations.	The block command is a temporary administrative assignment and is not maintained persistently in the saved or running configs.	All Platforms
FDB entries are getting aged out before default age-out time, when both FDB and MFDB tables are full.	Potential operator confusion over switch operations.	On the PCM6220, the MFDB and FDB tables are a shared resource. The user is continually sending new MFDB entries, which causes old FDB entries to be removed to make a place for the new MFDB entries.	All Platforms
DHCP packets forwarding is not proper to/from the trusted and un-trusted ports	Incorrect operational state in network.	The frame flooding routing in DHCP snooping now takes into account trust status.	All Platforms
Configuring all ports in all VLANs takes a long time	Potential operator frustration with switch management.	VLAN configuration has been optimized.	All Platforms
Max number of OSPF neighbors not supported	Potential operator confusion over switch operations.	The maximum number of neighbors is supported.	All Platforms
Cable fault distance not getting displayed in WEB in case of cable with one or more pairs cut or short.	Potential operator confusion over switch operations.	The fault distance is displayed in the web page.	All Platforms
Ports representation need to be changed in debug messages	Potential operator confusion over switch operations. Inability to diagnose network issues.	Ports are now displayed in C/S/P standard format	All Platforms
No error message for illegal characters in various command parameters	Potential operator confusion over switch configuration.	The accepted character set and length is documented in the CLI reference manual.	All Platforms
The ARP entry is not seen in the ARP table when an ARP reply is sent to switch.	Potential operator confusion over switch operations. Inability to diagnose network issues.	ARP entries are stored properly	All Platforms
Mapping Table configuration is not being displayed on Read-Only mode user web page.	Potential operator confusion over switch configuration.	The mapping table is displayed for a read-only user.	All Platforms
ACL is getting deleted when trying to create max+1 rule.	Potential operator confusion over switch operations. Possible security issues.	Corrected error checking logic.	All Platforms
LLDP-Med TLV information not registered for jumbo frame sizes greater than 8000	Potential operator confusion over switch operations.	Jumbo LLDP frames are now processed properly	All Platforms
VLAN binding entries are not being displayed on Read-Only mode user web page.	Potential operator confusion over switch operations.	VLAN binding entries are available to read only users	All Platforms

Summary	User Impact	Resolution	Affected Platforms
Unable to execute the command dot1x timeout tx-period 1	Potential operator confusion over switch operations.	This command is accepted with a timeout period of 1 second. Corrected range check on input.	All Platforms
In switching> network security >dot1x authentication web page in read-only user mode, the Re-Authenticate Now check box can be checked	Potential operator confusion over switch operations. Possible security issue.	Read-only properties are set for the check box	All Platforms
System Device information web page LED information not in sync with front panel LED information.	No Potential operator impact expected.	This issue was regarding various stylistic aspects of the system device web page. The system device web page conforms to the requirements as it exists and does not necessarily match the CLI with regarding to capitalization or naming conventions	All Platforms
DHCP snooping static binding thru DHCP request is denied as this is an expected behavior.	Potential operator confusion over switch operations.	Removed the log message indicating that a bound DHCP client with an existing binding sent a DISCOVER. Added a counter for this condition to the DHCP debug statistics.	All Platforms
Mode of transfer is displaying "unknown," while downloading the code from ftp	Potential operator confusion over switch operations.	ftp transfer mode is displayed	All Platforms
Allow disabling and enabling of terminal paging	Potential operator frustration over switch configuration.	The terminal length command is now implemented.	All Platforms
Web does not allow to configure image descriptor to its max length i.e. 255 characters.	Potential operator confusion over switch operations.	Images descriptors up to 255 characters are allowed	All Platforms
CDP (ISDP) is active on port-channels instead of the member Ethernet interfaces. For dynamic LAGS, the ISDP information is not exchanged on the interface until the port-channel becomes active.	Potential operator confusion over switch operations. Inability to interoperate with other switches.	CDP is active on the member ports for dynamic LAGs when the LAG is active.	All Platforms
CLI Manual Has No Index	Potential operator frustration over switch configuration.	The CLI manual has an index.	All Platforms
Script validation fails when max Sntp servers are configured.	Potential operator confusion over switch configuration.	Corrected CLI validation check so that existing server can be entered multiple times.	All Platforms
Configured SYSLOG server parameters cannot be updated without deleting and re-configuring	Potential operator frustration over switch configuration.	Syslog server parameter can be updated in the CLI without deleting the server.	All Platforms

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Resolution	Affected Platforms
CLI will not let user configure available parameter for the given IGMP command	Potential operator frustration over switch configuration.	IGMP configuration commands can be entered in interface VLAN mode at any time.	All Platforms
Inconsistent behavior - using same port number for multiple services	Potential operator confusion over switch operations.	Attempting to add a service with a TCP port overlapping a TCP port used by an existing service is denied with an appropriate error message.	All Platforms
LLDP Assignment of port ID for Port-Description TLV	Potential operator confusion over switch operations. Inability to diagnose network issues.	The LLDP port id TLV is supported by PowerConnect and can be displayed on peer devices.	All Platforms
Management ACL list needs "Match every packet" option	Potential operator frustration over switch configuration. Possible security issue.	New syntax has been added to the management ACL to allow the <b>any</b> specification for the service type.	All Platforms
SNMP support for Dell-LAN-TRAP-MIB	Potential operator frustration over switch configuration.	The Dell-LAN-TRAP-MIB is supported.	All Platforms
Simple mode BPDU will pass thru port-aggregator to other port-aggregator when using a single link per aggregator	Network outage if connected to Cisco with BPDU-Guard enabled	BPDU flooding is now disabled on aggregator ports.	All Platforms
Fatal error crash and reload when uplinked to Cisco 6509 - 3.1.3.9 - Believe to be ISDP	Inability to connect to Cisco 6509 CDP enabled ports	The switch now handles CDP mega-packets of size 1376.	PCM6220
Interface metric not working on 8024 OSPF passive interface	Interface metric is advertised as 0 when configured as passive – passive interface preferred over active interface	The interface metric is advertised properly when the interfaces is configured in passive mode.	All Platforms
Local system MAC address displayed as partner MAC address in "show lacp port-channel"	Potential operator confusion over network topology	The partner MAC address is displayed in the Partner system MAC address field.	All Platforms
SNMP going unresponsive on modular switches within 6 hours	Potential operator frustration over switch operations	SNMP operations have been corrected and tested without issue for over 24 hours.	All Platforms
Network performance and connectivity issues. Evidenced by "l7utils_inet_addr" messages in log.	Potential operator frustration over switch operations	The internal timer operations have been highly optimized resulting in lower overall CPU utilization.	All Platforms
H323 VoIP traffic and Crashing/Rebooting switch. CPU PID '17c31570 voipTask' spikes as seen in the 'show process cpu'.	Potential operator frustration over switch operations. Switch degradation in VoIP deployments.	The VOIP QOS code is no longer processing VoIP packets when it is admin disabled.	All Platforms
LACP not working with Juniper EX-4200, show inactive port channel state. System is sending oversize (132 bytes) LACP PDUs.	Potential operator frustration over switch operations. Inability to interoperate with Juniper switches.	The LACP process now sends 128 byte LACP PDUs. Interoperability with Juniper switches is verified.	All Platforms

Summary	User Impact	Resolution	Affected Platforms
Stack splits into multiple masters when MU fails.	Potential operator frustration over switch operations.	Issue in SDK MAC reset function resolved such that connected unit respond to master within 1 ms. Stacking stability verified under the conditions where issue occurred.	All Platforms
VLAN name issues in web UI on modular. Old VLAN name is retained on web page when switching to new VLAN.	Potential operator confusion over switch operations.	The correct VLAN name is always displayed.	All Platforms
Discards Occurring After Firmware Update to current version 3.1.5.4.	Potential operator confusion over switch operations.	The wrong counter was being displayed in the CLI. The CLI commands “show statistics port-channel” and “show statistics <interface>” are corrected to use the same counter as SNMP.	All Platforms
STP topology changes when an OOB SSH connection is established	Potential operator frustration over switch operations.	The SSHD task was starving other tasks in the system and causing topology changes. The SSHD task priority is now set to the shared time slice priority.	All Platforms
ARP broadcast traffic not forwarded through static/dynamic 10Gb LAGs	Potential operator frustration over switch operations. Potential network instability.	A field was being utilized in the LAG hash algorithm that could result in different hash indices on different units of a stack. This field (modid) has been removed from the hash selection algorithm.	All Platforms

## CLI Reference Guide Updates

### Release 5.1.12.2

#### ➤ Command “ip http secure-max-sessions”

**Syntax:** ip http secure-max-sessions ?

<max-sessions> Enter maximum number of HTTP secure sessions allowed in the range <1-16>.

The default value is 16.

#### **Default Configuration:**

The default value is 16

#### **Command Mode:**

Global Configuration mode

#### **Description:**

The maximum HTTPS sessions allowed is 16 and is the legacy default value.

#### **User Guidelines:**

User can restrict the SSL connection task by setting the max sessions from 1 to 4. From 4 onward, number of SSL tasks will be set to default value (32).

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

- ip http secure-max-sessions 1 - 8 SSL connection tasks allowed.
- ip http secure-max-sessions 2 - 14 SSL connection tasks allowed.
- ip http secure-max-sessions 3 - 20 SSL connection tasks allowed.
- ip http secure-max-sessions 4 - 26 SSL connection tasks allowed.
- ip http secure-max-sessions 5 to 16 - 32 SSL connection tasks allowed.

## Release 5.1.9.3

- No Updates

## Release 5.1.8.2

- No Updates

## Release 5.1.7.5

- No Updates

## Release 5.1.6.3

- No Updates

## Release 5.1.5.1

- No Updates

## Release 5.1.4.5

- No Updates

## Release 5.1.3.7

- No Updates

## Release 5.1.2.3

- **Command “show switch stack-ports stack-path”**

### Syntax:

- show switch [stack-ports [ stack-path {from-unit | all} to unit]]**
- **unitid**—The unit number.
- **stack-ports**—Display summary stack-port information for all interfaces.
- **stack-path**—Display the active path from one stacking unit to another.
- **From-unit**—The unit from which the packets originate.
- **All**—Displays all unit paths.
- **To-unit**—The unit to which the packets are sent.

### Default Configuration:

The default is “media-type auto-select sfp”

### Command Mode:

User EXEC, Privileged EXEC modes, Configuration mode and all Configuration submodes

**Description:**

The **show switch stack-ports stack-path** command is useful in tracking the path a packet may take when traversing stacking links. The command shows active paths only, not those that may be taken after a stack failover or stack re-convergence.

**User Guidelines:**

When both media types are connected, the preference as determined by the auto-select keyword parameter selects the active media. When the auto-select keyword is not specified, the selected media type is powered on and the alternate media type is powered off. Note that when the auto-select keyword is used with any media type, the SFP port will remain powered and the laser, if any, will remain on in order to allow connections over the SFP port.

**Examples:**

```
console#show switch stack-ports stack-path all 1
```

Packet-path from unit 2 to unit 1:

```
-----
1 unit-2 port Te2/0/49 to unit-1
```

Total hop count: 1

Packet-path from unit 3 to unit 1:

```
-----
1 unit-3 port Te3/1/1 to unit-1
```

Total hop count: 1

**Release 5.1.1.7**

➤ No Updates

**Release 5.1.0.1**

The following table lists issues found in the CLI Reference Guide after publication:

Command	Issue
<b>ip igmp snooping querier query-interval</b>	The guideline under this command refers to the IGMP Snooping Max Response Time. A reference that this can be configured using command <code>ip igmp query-max-response-time</code> under IGMP commands is missing. The default IGMP/MLD snooping Max Response Time is 25 sec
<b>terminal monitor</b>	The command does not have any arguments or a particular expected output hence an example for this is missing in the guide.  prompt#: terminal monitor ( in privileged exec mode to display logging messages on terminal )
<b>ip mtu</b>	The guideline should be augmented with the below text: Use the <code>ip mtu</code> command in Interface Configuration mode to set the IP Maximum Transmission Unit (MTU) on a routing interface. The IP MTU is the size of the largest IP packet that can be transmitted on the interface without fragmentation. Packets that are L2 forwarded in hardware ignore the IP MTU. Packets that are L3 (VLAN routing) forwarded in hardware observe the IP MTU. Packets forwarded in software are dropped if they exceed the IP MTU of the outgoing interface.
<b>rate-limit cpu direction input pps pps_value</b>  <b>no rate-limit cpu direction input pps</b>	Use the <code>rate-limit</code> command to reduce the amount of unknown unicast/multicast packets forwarded to the CPU. Use the "no" form of the command to set the rate limit to the default value. pps_value – range 100-1024 packets per second (100-3000 for PC81xx switches). The default ingress rate limit is 1024 packets per second (3000 for PC81xx switches). This command allows the administrator to reduce the rate limit for which



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

	<p>unknown unicast and multicast packets are forwarded and/or copied to the CPU. It does not affect the rate limits for control plane packets. It is almost never necessary to use this command to change from the default value. The use of this command should be restricted to situations in which moderate to high rates of unknown unicast/multicast are continually sent to the switch CPU as evidenced by the show proc cpu command and where the ipMapForwardingTask is showing high CPU usage. This will occur most frequently in networks where a high number of ARPs are continually received on untrusted ports, high numbers of L2 stations are timing out and reappearing or multicast flooding is occurring in the network. If problems with L2, L3 or multicast learning occur after changing this value, set the rate limit back to the default value and take other steps to correct or mitigate the underlying network issue directly.</p> <p>Note: This command is not available on the PCM6220 switch.</p>
<b>show system internal pktmgr internal control sw-rate-limit</b>	<p>The show command is to display the configured CPU rate limit for unknown packets in packets per second.</p> <p>Note: This command is not available on the PCM6220 switch.</p>

## Release 5.0.1.3

➤ No Updates

## Release 5.0.0.4

Command	Issue
<b>Show snmp filters Snmp-server filter</b>	<p>The following note should be added to the command usage guidelines.</p> <p>When a filter is defined, SNMP treats the filter as having an 'exclude all' statement at the beginning of the filter. Unless an include statement is specified, all notifications will be excluded.</p>
<b>aaa authorization {exec } {default   &lt;list_name&gt;} method1[method2]  no aaa authorization {exec} { default &lt;list_name&gt;}  authorization exec [default  &lt;list_name&gt;]  no authorization exec  debug aaa authorization exec  no debug aaa authorization exec</b>	<p>The following Exec Authorization CLI commands are missing from the CLI reference guide</p> <p>aaa authorization {exec } {default   &lt;list_name&gt;} method1[method2] no aaa authorization {exec} { default &lt;list_name&gt;} authorization exec [default  &lt;list_name&gt;] no authorization exec debug aaa authorization exec no debug aaa authorization exec</p>

## Release 4.2.2.3

➤ No Updates

### Release 4.2.1.3

Command	Issue
<b>Storm-control broadcast</b>	The supported syntax is <b>Storm-control broadcast [level <i>rate</i>]</b> where <i>rate</i> is a parameter to <b>level</b> and defined to be: The storm-control threshold as percent of port speed. Percent of port speed is converted to PacketsPerSecond based on 512 byte average packet size and applied to HW. If <b>level</b> is not used the default <i>rate</i> is 5.
<b>name "RDU-NOC Management VLAN"</b>	The VLAN name command has been migrated to VLAN Config mode and is no longer available in interface VLAN mode.

### Release 4.2.0.4

- Please refer Dell PowerConnect CLI Reference Guide for more details

### Release 4.1.1.9

- No Updates

### Release 4.1.0.19

The following commands are supported on switches that have combo ports:

#### Command media-type

##### Syntax:

media-type { auto-select [rj45 | sfp ] | rj45 | sfp }

auto-select rj45 - utilize RJ45 media when both media types are active

auto-select sfp - utilize the SFP media when both media types are active

auto-select – return the selection to the default (auto-select sfp)

rj45 – force connection on the RJ45 port. Power off SFP media port

sfp – force connection on the SFP port. Power off RJ45 media port

##### Default Configuration:

The default is “media-type auto-select sfp”

##### Command Mode:

Interface Config mode

##### Description:

Select the media type for the interface. This command is only valid on combo ports.

##### User Guidelines:

When both media types are connected, the preference as determined by the auto-select keyword parameter selects the active media. When the auto-select keyword is not specified, the selected media type is powered on and the alternate media type is powered off. Note that when the auto-select keyword is used with any media type, the SFP port will remain powered and the laser, if any, will remain on in order to allow connections over the SFP port.

##### Examples:

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

! Select the RJ45 port and power off the SFP port  
console(config-if-Te1/0/24)#media-type rj45  
! Prefer the RJ45 port and leave the SFP port powered on  
console(config-if-Te1/0/24)#media-type auto-select rj45

## Command show interfaces media-type

### Syntax:

show interfaces media-type

### Default Configuration:

N/A

### Description:

Display the configured and active media type for the combo ports

### User Guidelines:

N/A

### Examples:

```
console#show interfaces media-type
```

Port	Configured Media-Type(s)	Active
Te1/0/21	auto-select, SFP preferred	SFP
Te1/0/22	auto-select, SFP preferred	SFP
Te1/0/23	auto-select, SFP preferred	Down
Te1/0/24	auto-select, SFP preferred	Down

## Release 4.1.0.6

The Dell PowerConnect CLI Reference Guide is completely new. Users are referred to the Dell PowerConnect Configuration Migration White Paper for information on how to migrate configurations from previous releases of Dell PowerConnect firmware to the 4.0.0.6 Dell PowerConnect firmware.

The following table lists issues found in the CLI Reference Guide after publication:

Command	Issue
<b>show service-policy in</b>	The supported syntax is <b>show service-policy {in out}</b>
<b>show copper-ports cable-length</b>	This command is deprecated. Use the <b>show copper-ports tdr</b> command to display the stored information regarding cable lengths and the <b>test copper-port tdr</b> command to perform a cable length test. Testing a port brings the port down momentarily.

## User's Configuration Guide Updates

The following table lists issues found in the User's Configuration Guide after publication:

### Release 5.1.9.4

## Expansion Slot for Plug-In Module for PC7XXX switches

Section: "Expansion Slot for Plug-In Module" is correct.

- Plug-in modules are hot-swappable and no need to reboot the switch

### Release 5.1.6.3

## LED Definitions

This section describes the light emitting diodes (LEDs) on the front panel of the switch and on the optional modules that plug into the back panel.

### Port LEDs

The integrated external 10/100/1000Base-T switch ports on the PowerConnect M6220 and M6348 switches include two LEDs. The integrated SFP+ switch ports on the PowerConnect M8024-k include one LED.

#### 10/100/1000Base-T Port LEDs (PowerConnect M26220 and M6348)

Each integrated external 10/100/1000Base-T port on the PCM6220 and PCM6348 has two LEDs. Figure 3-5 illustrates the 10/100/100Base-T port LEDs.

Figure 3-5. 10/100/1000Base-T Port LEDs




Table 3-1 contains port LED definitions for the integrated 10/100/1000 Base-T ports on the PowerConnect M6220 and M6348 switches.

Table 3-1. 10/100/1000Base-T Port Definitions

LED	Color	Definition
Link/Activity	Green	The port is operating at 1000 Mbps.
	Amber	The port is operating at 10/100 Mbps.
	Solid	Link but no activity.
	Blinking	Link and activity.
	Off	No link.
Duplex	Green	Full-duplex mode.
	Off	Half-duplex mode.

#### SFP+ Port LEDs (PowerConnect M6348 and M8024-k)

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Each integrated SFP port on the PowerConnect M6348 switch includes two LEDs. Table 3-3 contains SFP port LED definitions for the PowerConnect M6348.

Table 3-2. PowerConnect M6348 SFP+ Port LEDs Definitions

LED	Color/Activity	Definition
LNK	Green solid	The port is linked.
	Off	The port is not linked.
ACT	Green blinking	The port is sending and/or receiving network traffic.

Each integrated SFP port on the PowerConnect M8024-k switch includes one LED. Table 3-3 contains SFP port LED definitions for the PowerConnect M8024-k.

Table 3-3. PowerConnect M8024-k SFP+ Port LEDs Definitions

LED	Color/Activity	Definition
LNK/ACT	Green solid	The port is linked.
	Green blinking	The port is sending and/or receiving network traffic.
	Off	The port is not linked.

## Release 5.1.5.1

➤ No Updates

## Release 5.1.3.7

➤ No Updates

## Release 5.1.2.3

➤ No Updates

## Release 5.1.1.7

➤ No Updates

## Release 5.1.0.1

The following paragraphs need to be added to the User's Guides for all platforms except the PCM6220:

Unknown unicast and multicast packets are copied to the CPU on the lowest priority QoS queue. Unknown packets are those that do not have hardware forwarding entries. Known unicast/multicast packets are hardware forwarded and are not queued to the CPU. Control plane packets (e.g. spanning tree BPDUs) are copied or forwarded to the CPU on higher priority queues. The rate limiting for unknown packets occurs on the internal CPU port and does not affect hardware based traffic routing/forwarding in any way. Typically, the switch will examine the received packets in software to check if there is a forwarding entry, create a forwarding entry (e.g., add a L2 MAC address or ARP response), and then either discard the packet or software forward the packet (only occurs during the brief transitional period when the system is actively adding a hardware forwarding entry but the hardware is not yet updated). Processing delays for higher priority packets may occur when the internal CPU queue is continually kept busy handling low priority packets.

A command was created to allow the administrator to reduce the rate limit for which unknown unicast and multicast packets are forwarded and/or copied to the CPU. It does not affect the rate limits for control plane packets. It is almost never necessary to use this command to change from the default value. The use of this command should be restricted to situations in which moderate to high rates of unknown unicast/multicast are continually sent to the switch CPU as evidenced by the show proc cpu command and where the ipMapForwardingTask is showing high CPU usage. This will occur most frequently in networks where a high number of ARPs are continually received on untrusted ports, high numbers of L2 stations are timing out and reappearing or multicast flooding is occurring in the network. If problems with L2, L3 or multicast learning occur after changing this value, set the rate limit back to the default value and take other steps to correct or mitigate the underlying network issue directly.

See the CLI Reference Guide updates section of this document for the description of the "rate-limit cpu" CLI command and its use.

## Release 5.0.1.3

- No Updates

## Release 5.0.0.4

Issue
The following message needs to be added to warn the user that Hotplug of a module is not supported if one of the ports on the module is operating in stacking mode.
<i>Warning: One of the modular ports is operating in stacking mode. Hotplug of a module requires system reboot. Failure to do so will make the system unstable!</i>
The following copper SFP needs to be listed as the supported module. However, diagnostics are not supported on copper SFP's.
Finisar FCLF-8521-3
When a filter is defined, SNMP treats the filter as having an 'exclude all' statement at the beginning of the filter. Unless an include statement is specified, all notifications will be excluded.

## Release 4.2.2.3

- No Updates

## Release 4.2.1.3

- Please refer Dell PowerConnect Users Guide for more details

## Release 4.2.0.4

- Please refer Dell PowerConnect Users Guide for more details

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Release 4.1.1.9

➤ No Updates

## Release 4.1.0.19

### The default authentication profile has changed from "enableList" to "enableNetList:

Telnet and SSH default to using the enableNetList authentication profile which requires an enable or line password. The serial console defaults to using the enableList authentication profile which does not require the use of a password. This change increases compatibility with industry standard behaviors. In previous releases, telnet, SSH and the serial console defaulted to using the enableList profile which does not require a password.

The following table lists changes to the User's Configuration Guides after publication:

Change	Affected Platform
Added examples of how a user would implement VLAN or QoS policy assignment in the Port Based Security section.	All Platforms
Added a table of the RADIUS attributes supported by the PowerConnect switches in the Controlling Management Access section.	All Platforms
The valid VLAN range is described as 1 to 4093 (multiple sections)	PC70xx
A better description of the RADIUS 'deadtime' parameter is added to the Controlling Management Access section	All Platforms
The CLI command "monitor session 1 mode" is described in the Configuring Port Mirroring section	All Platforms

## Known Issues

The following are all the outstanding known issues from previous releases. The issues listed here may have been discovered on any of the switches listed on the title page.

### Release 5.1.9.4

Summary	User Impact	Workaround
Unable to transfer files via TFTP using snmpset.	Unable to transfer files via TFTP using snmpset	1) Copy running-config startup-config from CLI. 2) <pre>snmpset -v 2c -c public 192.168.60.162 .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.1.0 i 1 .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.4.0 s "running-config" .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.5.0 i 3 .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.6.0 i 1 .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.8.0 i 1 .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.9.0 s "192.168.60.17" .1.3.6.1.4.1.674.10895.5000.2.6132.1.1.1.2.9.1.13.0 s "test.cfg"</pre>

### Release 5.1.8.2

Summary	User Impact	Workaround
Parity Errors	Parity Errors detected by the hardware are reported by the firmware. Parity errors are usually temporary and will happen from time to time.  Parity errors can cause DMA engine failures and dropped packets.	3) Power off and un-plug the switch 4) Wait for 3 minutes while all the capacitors discharge and the electrical state of the switch reaches ground level. 5) Power on and monitor the switch.

### Release 5.1.6.3

Summary	User Impact	Workaround
After deletion of vlan, the member port is not added back into the default vlan	If a port is in access mode and the access VLAN is deleted from VLAN database, the port PVID is modified to 1 but the port is not member of any VLAN.	This will be fixed in a later release.  Fixed in the 5.1.7.5 Release.

### Release 5.1.4.5

Summary	User Impact	Workaround
Active ports are becoming inactive and inactive ports are becoming active in lag after lag shutdown/no shutdown with speed change.	Occasionally, this condition can affect a LAG if a link auto-negotiates to a speed that is slower than the LAG should run at and if the slower link comes up first. The first port to link up sets the rate of the LAG and link that are not of that speed are blocked.	This is the result of a configuration mismatch and should be corrected in the topology.
CLI is not updated with default storm control configuration when disabling the storm control configuration from WEB.	When the storm control configuration is disabled from WEB, the change in configuration it is not getting updated to CLI.	If possible use the CLI to disable storm control.  Fixed in the 5.1.5.1 Release



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Workaround
Duplicate Address Detection (DAD) is not working on link-local addresses.	Occasionally, when deleting a IPv4 VLAN and re-adding the VLAN as an IPv6 VLAN to a port the Duplicate Address Detection (DAD) can fail for that link.	Only affects PC8100 switches. This will be fixed in a later release.
Storm control action feature is not working on 10G copper/SFP+/pluggable module ports.	Storm Control counters are no accurate on the 10G copper/fiber/pluggable module ports.	Only affects PC8100 switches. This will be fixed in a later release.
Unable to change the speed negotiation capabilities of an interface from web but can be done from CLI.	Changing the speed of a port in a LAG is not recommended and is discouraged. The checks for this fail on the CLI and allow this configuration to be changed.	Only affects PC8100 switches. This will be fixed in a later release.

## Release 5.1.3.7

Summary	User Impact	Workaround
Error reported when importing a certificate via WebUI	Before any CSR is issued, there seems to be already a request with no valid information (common name: 0.0.0.0). This is a cosmetic error which is a clean-up problem when creating the default certificate.  When importing the certificate through the Web page the certificate is truncated causing the length test to fail.	Import the certificate through the CLI. Corrected in release 5.1.4.5
"Total errors" column in "show switch stack-port counters" is not reset to zero after "clear counters stack-ports".	When the CLI command "show switch stack-port counters" is used "Total errors" column is not reset to zero after "clear counters stack-ports" command is issued.	None. Reloading the switch will clear the counters. This will be corrected in a future release.
Receive/Transmit Packets Discarded counters missed on port-channel counters	The CLI command "show interfaces counters port-channel 1" does not show an accurate count of Rx/Tx packets discarded.	None. This will be corrected in a future release.

## Release 5.1.2.3

Summary	User Impact	Workaround
PCM6220 - Multicast traffic can be flooded to other VLANs with IGMP snooping enabled	When both IGMP and IGMP snooping are configured using VLAN routing interfaces, the UDP data from one routing interface to the known MC group is forwarded to another VLAN and the same data traffic can be flooded among the members of the egress VLAN.	None. This will be corrected in a future release.
M6220/M8024 - poor https performance with 1024 or 2048 bit key	Using a key that is longer than 1024 will cause high CPU utilization for 5-10 seconds. This will occasionally result in a browser timeout for the session login. After 5 – 10 seconds CPU utilization will return back to normal.	Workaround: Use a key less than 1024 bits.

## Release 5.1.1.7

Summary	User Impact	Workaround
PC8100 - SCP or SFTP file transfers to FreeBSD and Mac causes switch to crash and reboot.	SCP or SFTP file transfer from PowerConnect 8100 switches to a FreeBSD or Mac client/server causes the switch to crash and reboot. Eventually connectivity comes back after a few seconds, but the connectivity loss is long enough to cause iSCSI connections to drop.	Workaround: None.  Fixed in 5.1.2.x release
8024 - Routing issue, null address in ARP table after VLAN manipulation	Some null mac address (0000.0000.0000) present in PC8024 ARP table. This happens after vlan manipulation (like create, delete, define IP address, add and remove on trunk port). Issue occurs randomly and not immediately (take between 30min and 1h between vlan manipulation and routing issue)	Workaround: Reloading the switch resolves the issue temporally (till next vlan reconfiguration). Add static entry in ARP table resolves the issue.  Fixed in 5.1.2.x release
PCM6220 v5.0.1.3 switch crashes every 30-40days while SNMP monitored	PCM6220 Switch crashes every 30 to 40 days when SNMP monitoring with cacti version 0.8.8a	Workaround: None. Fixed in 5.1.2.x release
M6348 Stack - interface in static LAG goes into inactive state while physical interface is up	Due to a race condition, while the LAG member links flap, the LAG member that linked up may be put into standby, when at the same moment any existing members in the LAG goes down.	Workaround: None. Fixed in 5.1.2.x release

## Release 5.1.0.1

Summary	User Impact	Workaround
Molex QSPF DAC Cable with part number 111040-1104 does not comply with QSFP specification SFF-8436. These cables do not support 'voltage' diagnostics.	Voltage is displayed as 0.00 instead of "N/A" for this diagnostic parameter.	Ignore the voltage displayed field for this part or use a SFF-8436 compliant cable.
Show AAA IAS-USERS <Username> Command Missing	The “show aaa ias-users [username]” command seems to have been deprecated even though it still exists in the CLI guide.	The same information can be seen within the running configuration of the switch with the “show running-config” command.
External CDP/ISDP traffic occasionally forwarded onto internal ports	Occasionally external CDP/ISDP packets are being forwarded to the internal ports. This results in confusing information from the blade server point of view as multiple directly connected neighbors appear to be seen.	None.
Multicast sources that cease sending multicast are timed out and removed from the multicast forwarding cache after 150 seconds	If an intermittent multicast source that has been aged out of the multicast forwarding cache begins sending again before the corresponding S,G entry has timed out at the RP (185 seconds per RFC 4601), any *,G entries (joined hosts) may take up to one IGMP Query interval to begin receiving the multicast stream.	The default IGMP query interval is 125 seconds. In practice, this situation is very unlikely to occur as a multicast source that fails to send even one packet for 150 seconds is unlikely to start sending packets before the S,G entry at the RP times out.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Release 5.0.0.4

Summary	User Impact	Workaround
QSFP Base CR4 with copper DAC cable lengths greater than 3 meters will not work on PC8100 switches	When using the DAC copper cables with QSFP CR4s (which are rarely used) and cable more than 3 meters, the switch may not even detect this device and so link up never happens. Only the following cables are recommended with these CR4 QSFPs:  111040-1104 – 1m Passive Copper Assembly 111040-1204 – 3m Passive Copper Assembly	None
On PC8100 switches, sharp decrease in 6to4 tunnel traffic is observed when ipv4 static route is deleted and added back to the switch.	This is a corner case issue requiring many steps to get to this state but if the state is reached, the user will see less through-put on the tunnel.	Stop traffic for a minute or two so that the stale entry in the Linux stack is cleared.
Failure log messages may show up on console on doing a SNMP walk on root node.	There is no effect besides the annoyance of these messages while doing an SNMP walk.	None
Speed is not applied to combo (copper) ports after saving and reloading the switch (8024/8024F).	Since these configuration variables exist for both copper and fiber modes (combo ports), the speed and duplex are not saved since the port assumes that it will only save fiber parameters and thus the customer will notice that the port auto-negotiates after reload instead of goes to a static speed or duplex.	Always reconfigure the speed on copper combo ports after reboots on the 8024/8024F.
SFP+ module is still detected in running-config after clear config on PC8100 with QSFP to 4x10G	The information that will be stored in the running-config specific to the 4x10G port (QSFP to 4x10G) will not be cleared after the clear config command.	User can negate these commands manually after a clear config.
Status is not shown after the image upload using HTTP through IPv4 HTTPS session	The user may not be aware that the download has completed when using the GUI.	User must refresh screen or go to version screen for indication that the download has completed.
Console logs/syslogs are not generated if we disable LAG local preference.	This will only be seen when disabling the local LAG config and will not affect the system.	None
The following unwanted logs may come up on console after running the “clear config” command. 1) dot1s helper logs 2) snooping logs 3) “ATP RX: Failed to alloc” logs	There is no effect to the switch or user, just unwanted log messages on console.	None

Summary	User Impact	Workaround
The following unwanted logs may come up on console after running the “show tech-support” command with UDLD and MSTP configured: “ATP RX: Failed to alloc” logs	There is no effect to the switch or user, just unwanted log messages on console.	None
On PC8100 switches, console gets locked for 20-30 seconds if trying to add a 6to4 tunnel source within 30 seconds of deleting another tunnel source.	This only happens after repeated attempts at adding and deleting a tunnel source and thus the impact is very small to the customer.	Wait for 30 seconds after deleting the tunnel source and then add a new tunnel source.
'out of mBlks' logs are observed on console if ICMPv6 echo requests are sent to OOB port at line rate	There is no effect to the switch or user, just unwanted log messages on console.	None.
Invalid characters are shown under reason column for some entries in the “show ip ospf statistics” command.	This only happens with this CLI command output and thus might be bothersome.	The Web interface will not show these characters.
LPI samples are not shown for the first time on selecting a different unit number using the GUI.	This can be confusing to the user since the switch will not show the stats for the port after a new unit is selected but then the stats will show up after going to new port and then back.	Select a random port from the web and then re-select the desired port to view the LPI samples.
"show fiber port optical-transceiver" command is showing current as zero for QSFP transceivers.	This field does not apply to QSFP transceivers and should display “NA” instead of zero.	None.
Image uploaded with HTTP method can't be downloaded back to the switch if switch and PC are located in different networks and the networks are very slow.	This might require the User to have to retry the download or change the IP address or VLANs on the switch or PC.	Use alternate transfer methods like TFTP, FTP, etc.
Console messages shows "Thermal state raised to WARNING" often.	Our customers requested this warning to indicate better visibility into the Thermal settings and sensors.	Configure the logging level to be higher than “Warning”.
Finisar LRM 10G SFP+ transceiver model – FTLX137D3BCL - drops packets intermittently.	This specific model is not recommended for use with our switches.	Please use the Avago 10G-BaseLRM model – AFBR-707SDZ-D1.
OpenManage displays incorrect session timeout duration	OpenManage timeout warning window is displaying the wrong value but uses the set value.	None.
Command "show fiber-ports optical-transceiver" causes UI to become slower with multiple transceiver count.	Executing the command “show fiber-ports optical-transceiver” with multiple transceivers inserted will cause the console prompt a long time to return (possibly up to 60 seconds).	None.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Workaround
Port goes down if the port is excluded from native vlan with UDLD feature enabled on it.	If the port is operating in Trunk mode and UDLD is enabled, the port goes down if it is excluded from the native vlan.	Include the port in native vlan.
SNMP V3 walk may fail after "initiate failover" command is issued.	After failover, SNMP V3 walk may fail, as MIB browser and agent can become out of time and stop intercommunication.	After a failover, close the browser and re-open it. SNMPv2 works correctly.
OOB static IP entry cannot be the same as the DHCP assigned IP address	After receiving an IP address from the DHCP server, the switch gives an error and will not allow an attempt to add a static IP address and gateway that is the same as the DHCP IP address.	Use a different IP address than the DHCP address given.

## Release 4.2.2.3

Summary	User Impact	Workaround
Stack member units port display is missing in web GUI.	Wrong id for the power LED is displayed.	None
WebUI sFlow Polling page issues.	sFlow>Sampler configuration and sFlow>Poll Configuration don't work for ports Gig1/0/1 - 1/0/9.	None

## Release 4.2.1.3

Summary	User Impact	Workaround
"show interfaces switchport " command shows incorrect General Mode Tagged VLANs value	Some general mode VLANs tagged to the interface may not be displayed using this command.	Use "show vlan" command to interfaces. No other workaround.
M6220 OOB interface unreachable after failover	On a failover on a M6220 stack the OOB interface may not be available.	Recovers when the master is restored.
CLI command "show ip dhcp snooping binding" not displaying client information.	"show ip dhcp snooping binding" not displaying client information. "show ip dhcp snooping statistics" does not display correct message counts.	None
OOB interface configured with default IP via Setup Wizard though told not to do so.	The setup wizard does not honor selection to not setup OOB IP address.	OOB IP address will need to be setup manually.
DHCPv6 - M6220, PC/M 8024/k - Client Solicits do Not Seem to Make it to the Server / Relay	By looking at the counters, the client believes it is sending solicits; but, the relay and the server never see the solicitations.	None

## Release 4.2.0.4

Summary	User Impact	Workaround
File modification date & time is not getting updated with current time & date.	When internal files are modified, they do not get the current time stamp.	None

Summary	User Impact	Workaround
SNMP walk is not successful while doing walk on root port.	SNMP walk on the root port times out.	Do not do SNMP walks using root port.
FIP sessions are getting disconnected for VLAN switchport mode change with default vlan settings.	Users are unlikely to change either the default VLAN or the FIP VLAN while sessions are active.	Do not change the FIP VLAN while sessions are established. The reason is that after a VLAN is re-assigned or even changed to general mode, the sessions will of course be disrupted since the FIP snooping occurs on the VLAN and any change in this will cause problems on the Cisco Nexus side and will require an interruption and reestablishment of the addressing from the CNAs on up.
OpenManage displays incorrect session timeout duration when using secure HTTP	After the browser session timeout (default 10 minutes), OpenManage displays incorrect session timeout duration in the message "Your session had been inactive for more than 240 minutes", which is the actual setting for telnet and ssh. However, the actual timeout occurs after the default period of 10 minutes, so the GUI message is incorrect.	Disregard the time in this GUI message.
Cannot disable the SFS "allow-downgrade" feature	Even with SFS allow-downgrade disabled, the master will still push the older firmware to a stack member running a newer version of code.	Always make sure the master has the wanted version loaded.
Console port locks up when awaiting telnet Radius response	Radius authenticated Telnet login attempt when Radius daemon stopped, causes console port to be temporarily blocked until Radius timeout expires.	Wait for timeout or ensure Radius server is reachable.
Flowcontrol is in inactive state when connected to Partner(PCM6220) with combo ports.	Flowcontrol gets automatically disabled and if the ports have a need for Flowcontrol, there will be no pause frames sent.	Re-enable Flowcontrol on PCM6220 switch.
7048R replacement power supplies reported as incompatible	Although the power supplies part number is the same, the 7048R reports it as incompatible and thus the error message is incorrect. The power supplies still works correctly.	Ignore the error message, since there are no functional issues with this power supply.
PowerConnect 7048P : poe_ldp.c(1741) 23137 %% Failed to get pairs control	After a long period of time and numerous IP phones connected and with at least 5 switches connected as a stack, PoE error messages start filling the logs.	Maximum supported IP phones at this time is 64.
SNMP showing packets discarded while cli doesn't show the same.	SNMP monitoring tool is pulling stats from M8024 and shows very high discard receive rate but switch doesn't say the same.	None.
PC M6220 Running configuration altered after removal of stacking master, 4.1.0.19, 4.1.1.7	When master member was removed from and reinserted into an M1000e enclosure, some of the configuration was missing from running-config.	Always write the config before removing master.
Stacked m8024-k or 8024/8024F switches running code that supports Ethernet stacking should not be downgraded to older code that doesn't support Ethernet stacking.	Customers downgrading a switch stack to a version of code that does not support stacking are advised to: 1) Break apart the stack into individual units 2) Clearing the saved config on each unit 3) Renumber each unit to unit 1 using the switch X renumber 1 command	Failure to follow these instructions may cause units to crash when booted into the 4.1 firmware. To recover the switch, attach a serial cable and enter the boot menu (press 2 - Start Boot Menu at the prompt). From the boot menu, select 10 - Restore configuration to factory defaults, and then select 1 - Start operational code

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

Summary	User Impact	Workaround
PC7048P, in a stack will error out when all rebooted at the same time.	The stack will stop passing traffic if all switches in the stack are rebooted simultaneously.	If this situation happens, it is recommended that each power switch be rebooted in sequence with a four to five minute interval between each reboot.
Jumbo frames cause transmit errors on port channel	Transmit Errors is seen on port channel, but not on the members of the port channel. Counters remain inaccurate.	None – Inaccurate transmit errors do not cause functional issues.
PC8024F Stacking - CLI/WebUI : stack-ports counters value is always zero	CLI/WebUI shows the stack-ports counters value as zero after stack is formed.	None – Stack-Ports counter values as zero doesn't affect the PC8024F stacking functionality.
CLI command "no snmp-server community-group" doesn't work	CLI command "no snmp-server community-group" is not available.	None
Dot1x ias local authentication method not working	The internal database feature, which is a Dell specific feature, is not working correctly because this feature requires a user to authenticate using MD5, which is not supported by Windows at this time.	Use any other form of dot1x authentication.
"ipv6 pim join-prune interval" command is not working	CLI command "'ipv6 pim join-prune interval 30" does not change the default interval value from 60	None
Incorrect status being reported with show interfaces commands	When PowerConnect 8024F combo ports 21 and 22 are used for stacking, the show interfaces status command and show interfaces media-type commands report the status to be Detached and Down.	None
Power supply descriptions should be modified as "Internal" and "Remote" or "External" for main and secondary power supplies respectively in show system.	There is no impact to the user.	None
M8024-k Internal ports are up during most of the switch POST	Network operators may experience a single bounce during reboots of the M8024-k.	None
M8024, M6220, M8024k, PC8024F - Extra Lines and Tabs in CSR Cause CA Submittal Troubles	CSR may be rejected by Certificate Authority	Users can hand edit the CSR to left align all rows and eliminate blank lines before submission to the CA.
Sflow configurations do not get saved to the config	The operator entered a sflow command that takes a timeout value which makes the sflow configuration valid only for a fixed period of time. As the configuration is temporary (bound by the timeout value), it is not shown in running-config. Storing the vale in the running config/startup config would be an error as the time period may have already expired.	The configuration will show in the running config if the command is used with the "notimeout" option, e.g. <i>sflow 1 destination owner 1 notimeout</i>



Summary	User Impact	Workaround
Password strength - minimum characters not enforced	Operator may become confused regarding switch operations.	As is documented in the CLI Reference Manual, the password strength minimums do not become effective until the user has configured a non-zero value for <i>passwords strength minimum character-classes</i> . Please refer to the documentation for passwords strength minimum character-classes
M8024-k OpenManage Web UI stack view display	Operators using IE 8 may experience issues as follows: (1) Status LED does not glow to identify Master (2) Member units do not show "DELL PowerConnect M8024-k" model info (3) Member units port display is missing (4) LED label should be "Unit No." instead of "Stack No." ? (5) All Stack No. shown are as "01", instead of "01", "02", "03", "04" etc. (6) There are two "Slot 0" in display – confusing	Operators should consider using a browser other than IE 8.
Inline help for "spanning-tree loopguard" is incorrect.	The inline help indicates that the command applies to a single port.	Operators should be aware that this global CONFIG command applies to all ports.
show interfaces advanced firmware displays ports 1-20 as 10GBASE-T on 8024F	Operator should be aware that the type is reported incorrectly on this platform.	Ignore the type in the display for this command.
VLAN name config lost when upgrade from 3.1.5.16 to 4.2.x.x	When upgrading from release 3.1.4.16 to 4.2.0.4 the VLAN names only will not be copied to the upgraded configuration. VLAN numbers are not affected.	The user can cut the VLAN names and save these off before the upgrade occurs and then again reenter them after the upgrade.
Web GUI sFlow configuration , receiver owner inconsistent with CLI	Fails with an error - "Error! Failed to Set 'Receiver Owner' with " However, it is possible to save the same configuration (without receiver owner) via the CLI.  Also, it is also not possible to add any polling device or sampler configuration on the Web GUI with this receiverIndex (seen in the show all option) since an error is thrown stating "Receiver Index is not configured".	Always configure the receiver owner when using the Web interface.
Websense: Order of switchport commands in running-config changed, Impacts scripts	The order that the commands “switchport mode general” and “switchport general allowed vlan” are displayed in the running config has been changed so that now the “allowed” command is first. This may cause problems with customer’s scripts that expect a certain order in the “show running-config” output.	None.
The “show dot1x statistics” command within the User Guide is actually “show dot1x interface statistics” command from the CLI.	The User Guide states that there is a “show dot1x statistics” command for displaying dot1x statistics on the switch when the actual command for doing this is “show dot1x interface statistics”. This can be frustrating to the customer if he has referenced the User Guide to look up the supposed correct command.	Use the “show dot1x interface statistics” command.



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Release 4.1.1.9

Summary	User Impact	Workaround
LLPF is not supported on the PCM6220 switch	The hardware functionality needed to support LLPF is not available on the PCM6220 switch.	Upgrade to a PowerConnect switch that supports LLPF like a PCM6348 switch.
Traffic led solid green with 1Gb and 100Mb link speeds on PC8024/PC8024F	Setting advertisement from other switches or IXIA of 1Gb or 100Mb link speeds to 10G links on 8024, 8024F results in link up and traffic led to be solid green.	None – Traffic LED Solid Green do not cause any functional issues.
Config Lost for the Portchannel on removing a 2 Port 10 G Module on the PCM8024 switch	On boot up, the switch gives an error and rejects all the config for the portchannel as well as the TenGig interfaces in Bay1.	Remove port configuration of 10G module before removing the module from the bay and reboot the switch.

## Release 4.1.0.19

Summary	User Impact	Workaround
Log message output	snmpwalk will report error log message related to CPU-port and vlan routing port	None – error messages do not cause functional issues.
Secure HTTP Random Characters	Under System Management -> Secure HTTP, random characters maybe populating some of the fields.	The CLI must be used to generate certifications.

## Release 4.1.0.6

Summary	User Impact	Workaround
PC7XXX cable diagnostics for the Fiber ports does not work.	Fiber port cable diagnostics are not available for the PC7XXX.	None.
Switch delivers more power than the PD requested via LLDP in high power mode.	Switch may draw more power than negotiated at short cable lengths. PD may draw more power than negotiated, but power loss due to cable impedance is compensated for so that devices with average or longer cable length will receive adequate power.	None – system assumes 5.8W average loss due to cable length and delivers 5.8W extra power to ensure device receives requested power.
L3 routing NSF failover data plane on dynamic LAG - loss duration up to 5 seconds for large configurations	Interruption of voice, video and data service for duration of loss. Data plane loss during failover should not exceed 50 ms.	Disable portfast and auto-portfast on physical ports configured in a LAG.
Trunk mode VLANs transmit tagged frames only	Not compatible with other vendors trunk modes.	Administrators can configure “general” mode VLANs, which transmit PVID frames untagged and all other VLAN frames tagged. General mode is compatible with other vendor’s trunk mode behavior.
Speed/duplex commands available for interfaces which require auto-negotiation	Confusion about how to configure links.	Documentation and CLI prompt clearly states which commands are applicable to which interfaces. <b>Only use speed/duplex commands on fiber interfaces. Only use speed auto/duplex auto commands on copper interfaces.</b>

Summary	User Impact	Workaround
ST : Stack member response times to ICMP ping requests in a 12 unit stack are larger than for stack master	No user impact expected. Observed occasional outlier response time up to 500 ms for stack members in a large stack configuration with heavy traffic. Average response time is well under 100 ms for stack members. All response times are well within ping limits.	None required.
Issue with protocol based VLAN configuration migration.	The command <i>vlan protocol group</i> required a string parameter in earlier versions; now it requires an integer parameter.	The software recognizes if the group name is alphanumeric, however it will not work when the name of the group is numeric (for example 2, 3, etc.).
Read/write user allowed read only access when authentication method is used as TACACS.	The user always gets Read-Only access if using TACACS as a means for HTTP authentication, even if the TACACS user is Read/Write capable.	User can configure the same TACACS user locally and use LOCAL authentication method for HTTP. The user will be able to get access based on the local user access level (Read-write or Read-only).
TFTP gives no reason for file download failures.	Generic failure message is issued.	Administrators can ping the TFTP server from the switch. Administrators should ensure the TFTP server is available, the requested file is available, and the permissions are set correctly.
CLI command stack-port config rejection does not display the cause.	If a user enters an invalid interface, a generic error message is issued.	Utilize the <i>show stack-port</i> command to identify stack port configuration issues.
The 'acct-port' command does not have 'no' version.	The user can configure the acct-port to the default using the positive form of the command	Configure the acct-port to the default using the <i>acct-port 1813</i> command in Radius accounting mode.
Non-configuration file getting loaded to startup-config through HTTP.	Switch does not utilize invalid configuration file information. Earlier versions of startup-config are not available for fallback when overwritten with an invalid startup-config.	In this case, an invalid configuration file was downloaded (on purpose) via the web. When the switch rebooted, it detected that the configuration file was invalid and overwrote the start-up config with the default configuration (an empty configuration). Users are advised to maintain off-line copies of switch configurations.
A v6 ping with the v4 header destination address set to 224.0.0.2 (all routers addr) is not responded to.	Users are not able to ping over 6to4 tunnels using IPv6 addresses.	Users can send pure IPv4 pings to the other end of the tunnel.
Certain packets match system rules that elevate the priority for protocol packets.	Packets may be transmitted out of order when using priority flow control. Additionally, if the queue that the packets are put on is not enabled for lossless PFC, then the packets can be transmitted even when the port was told to pause. This may have an effect on connections that expect packet order to be maintained, e.g. FCoE.	None.

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Known Restrictions and Limitations

### Release 5.1.6.3

Description	User Impact
<p>The Limitation and Restrictions for VLAN interfaces with ACLs applied are consistent across the supported products:</p> <ul style="list-style-type: none"><li>• <b>Maximum VLAN interfaces with ACLs applied - 24</b></li></ul>	<p>Not found in the documentation and are provided here for convenience.</p>

### Release 5.1.3.7

Description	User Impact
<p>Limitations and Restrictions for Private VLAN Operations (also found in the User Configuration Guide)</p> <ul style="list-style-type: none"><li>• Only a single isolated VLAN can be associated with a primary VLAN.</li><li>• Multiple community VLANs can be associated with a primary VLAN.</li><li>• Trunk and general modes are not supported on private VLAN ports.</li><li>• Do not configure access ports using the VLANs participating in any of the private VLANs.</li><li>• Multiple primary VLANs may be configured. Each primary VLAN must be unique and each defines a separate private VLAN domain. The operator must take care to use only the secondary VLANs associated with the primary VLAN of a domain.</li><li>• Private VLANs cannot be enabled on a preconfigured interface. The interface must physically exist in the switch.</li><li>• Secondary (community and isolated) VLANs are associated to the same multiple spanning tree instance as the primary VLAN.</li><li>• GVRP/MVRP cannot be enabled after the private VLAN is configured.</li><li>• The administrator will need to disable both before configuring the private VLAN.</li><li>• DHCP snooping can be configured on the primary VLAN. If it is enabled for a secondary VLAN, the configuration does not take effect if a primary VLAN is already configured.</li><li>• If IP source guard is enabled on private VLAN ports, then DHCP snooping must be enabled on the primary VLAN.</li><li>• Do not configure private VLAN ports on interfaces configured for voice VLAN.</li><li>• If static MAC addresses are added for the host port, the same static MAC address entry must be added to the associated primary VLAN. This does not need to be replicated for dynamic MAC addresses.</li><li>• A private VLAN cannot be enabled on a management VLAN.</li><li>• A private VLAN cannot be enabled on the default VLAN.</li><li>• VLAN routing can be enabled on private VLANs. It is not very useful to enable routing on secondary VLANs, as the access to them is restricted. However, primary VLANs can be enabled for routing.</li><li>• It is recommended that the private VLAN IDs be removed from the trunk ports connected to devices that do not participate in the private VLAN traffic.</li></ul>	<p>These are documentation limitations and restrictions found in the User Configuration Guide also provided here for convenience.</p>

<p><b>IGMP Snooping:</b> IGMP snooping is enabled by default. Traffic addressed to reserved multicast IP addresses is flooded. Unregistered multicast is flooded to all ports in the VLAN until a multicast router port is identified.</p> <p>Once mrouter port is identified the traffic is forwarded to mrouter port and listener ports only.</p> <p>The M6220 floods unregistered IPv4 and IPv6 multicast traffic on all the ports.</p>	<p>Clarification on the operation of IGMP snooping.</p>
<p>ICMP Redirects are a hardware function and not processed by the CPU</p> <p>There has been no change to the functional behavior of the switch not to generate ICMP redirects when primary and secondary IP addresses with different subnets are configured on same VLAN and traffic is destined from primary to secondary subnet on the same VLAN. This is a hardware limitation and as of today we do not have a way to change this behavior of detecting that the traffic is destined to a secondary IP address on same VLAN and not to generate ICMP redirects.</p>	<p>Hardware limitation.</p>

## Release 5.1.1.7

Description	User Impact
<p>PowerConnect 8100 Series QSFP DAC CR4 40GB cable fails to link up with partner switch (for example. Dell Force10 S4810). After upgrading a Power Connect 8100 series switch to firmware 5.1.0.1 customers may experience loss of connectivity when using 40G QSFP CR4 DAC cables with partner switch. Some partner switch vendors may by default leave auto-negotiation disabled for CR4 connections. This will cause a negotiation mismatch and the QSFP CR4 port will not link up.</p>	<p>High</p> <p>In 5.1.0.1 firmware a behavioral change, as per IEEE spec, was made that means that when a QSFP CR4 cable is connected the 40gb port has auto-negotiation enabled. In previous versions of firmware the default behavior was to leave auto-negotiation disabled. This change was required in order to ensure compliancy to the following specifications: IEEE 802.3-2012 Section 6 / Clause 85.3 / Clause 82.6 / Clause 73.9 - explains that auto-negotiation is mandatory for 40GBASE-CR4 and 100GBASE-CR10.</p> <p>Workaround: Enable auto-negotiation on 40G interface of Dell Force10 S4810 switch like below:</p> <pre>S4810#conf S4810(conf)#int fortyGigE 0/60 S4810(conf-if-fo-0/60)#intf-type cr4 autoneg</pre>
<p>When https enabled with a 2048 bit key CPU sslt tasks will require a high CPU processing load for 5 – 10 seconds.</p>	<p>Medium</p> <p>HTTPS login attempt may timeout.</p> <p>Workaround: Use 1024 or lower key.</p>
<p>PCM6220 switch does not support “Private VLAN” feature</p>	<p>Private VLAN feature requires hardware support that the PCM6220 XGS3 switching fabric does not contain.</p> <p>Workaround: None.</p>

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Release 5.1.0.1

Description	User Impact
SNMP walk is not successful while doing walk on root port	Low SNMP walk on root port may result in a timeout if executed without specifying any timeout value. Workaround: Execute walk with a recommended timeout value of 2 sec
The IPMC L2_BITMAP is only updated to reflect ports that should 'not' be flooded when a multicast stream is 'first' seen on a VLAN.	Moderate There will be some flooding of multicast traffic  Workaround: Issue no ip multicast followed by ip multicast
"ip http secure-server" may not be cleared after performing the clear config operation if there is user intervention before prompt returns	Low Clear config operation clears all system components operational and configuration information and then builds the default configuration. This operation takes time to complete and the prompt may not be returned immediately. Prompt is returned after the completion of the operation. Please wait for the prompt, pressing "enter"/CR is not needed in this case.  Workaround: Issue clear config one more time if "ip http secure-server" configuration is not cleared
Reboot needed when critical message "Failed to add local route for network X/X on interface X" appears on the console	High Route is not added and hence critical situation. Need a reboot to recover.

## Release 5.0.1.3

### System – 5.0.1.3

#### Stacking

Description	User Impact
Under certain conditions 5 or more ports identified as stacking ports can cause transmission errors even if the stacking links are not up.	Low This problem happens infrequently and setting those ports back to Ethernet mode has corrected the problem.

## Release 5.0.0.4

### System – 5.0.0.4

#### System

Description	User Impact
8100 switches increment "Internal MAC	Low

Rx Errors” counter, when packets are received with (size > 1518) and (size <= MTU size), and the packet contains an invalid FCS or code error detected or an IEEE length check error	For typical IP networks this problem won't be seen because the length field/Ethertype will contain a valid value.
--	---

## Web

Description	User Impact
The device manager GUI does not support IE9 at this time.	<p>Moderate – Multiple errors are displayed when trying to bring up the device GUI with IE9.</p> <p>Workaround: The User must use an Internet Explorer version prior to IE9 with the GUI.</p> <p>Note: This is not a limitation if running Release 5.1.0.1 or later versions of firmware.</p>

## iSCSI

Description	User Impact
“show iscsi sessions” command does not display established sessions on M8024/M8024-k/PC8024/PC8024F platforms.	<p>Moderate –</p> <p>Workaround: Configure partner devices to send tagged, not priority tagged traffic.</p>

## Release 4.2.1.3

### Management – 4.2.1.3

## CLI

Description	User Impact
CLI command ‘show dot1x users’ is missing in CLI	Low – Use the show dot1x clients command to show the authenticated clients.
Show policy-map interface command does not take a port-channel parameter	Low – the administrator can show the counters on the individual members of the port-channel and sum them manually.
Show dot1x statistics command is missing in the CLI	Low – the administrator can show the statistics on the individual interfaces
Show crypto key pubkey-chain ssh - "username" option does not work	<p>None – the administrator must configure and associate a key to a user in order for the user to be associated with an SSH key. The following example creates and associates an SSH user with a key:</p> <pre> console(config)#username asd password XXXXXXXXX privilege 15 console(config)#crypto key pubkey-chain ssh console(config-pubkey-chain)#user-key asd dsa console(config-pubkey-key)#key-string "ssh-dss AAAAB3NzaC1kc3MAAACBAJRwUAD3AuRACp1MOBehlAgyZb18wf9Bt dip+t+1CbAqiqNEh4lBiew184DSKk0T6SnSSXuCN+bJnQPXJeiQt+OFnmjiYhn HcvI04Q5KnQhloZcEFgSsmQ7zJnReWtLvUQI0QvBIStanzedmQVGHvDrQ5X 2R729ToSH0ibBrnYtAAAAFQDNord7S9EJvUkKKxVBpWE6/skCmQAAAIB MjMO+BPP5KXzNWfZhqAhxBSobvif/z6pzi9xWLIYy99A03zmRYCpcGIoLW iRHsR7NVpxFqwbqvez8KS0CDJ5aoKKLrpBlpg5ETkYEew/uTZ14lQQRBrzPw GBfxvTXKCWiI2j5KFa/WKLsnmWJX0/98qpxW/IMXoXsA9iK4pnMKwAAAI B4Jrt6jmoLybpzgOPOI0DsJ7jQwWacinD0jliz8k+qzCpanhd2wH+DEdj/xO2sFR fnYIME3hmXoB+7NByVUtheVjuQ2CWhcGFIK9tbuPC6DtXh1xxT0NJ7rspv Lgb0s6y/0tk+94ZP5RCoAtLZ7wirShy3/KJ4RE0y2SFZjIVjQ==" console(config-pubkey-key)#exit console(config-pubkey-chain)#exit console(config)#exit </pre>

# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

	<p>console#show crypto key pubkey-chain ssh username asd</p> <p>Username : asd</p> <p>ssh-dss</p> <p>AAAAB3NzaC1kc3MAAACBAJRwUAD3AuRACp1MOBeh1AgyZb18wf9Bt dip+t+1CbAqiqNEh4lBiew184DSKk0T6SnSSXuCN+bJnQPXJeiQt+OFnmjiYhn HcvI04Q5KnQhloZcEFgSsmQ7zJnReWtLvUQI0QvBIStanzedmQVGHvDrQ5X 2R729ToSH0ibBrnYtAAAAFQDNord7S9EJvUkKKxVBpWE6/skCmQAAAIB MjMO+BPP5KXzNWfZhqAhxBSOBvif/z6pzi9xWLIYy99A03zmRYCpcGIoLW iRHsR7NVpxFqwbqvez8KS0CDJ5aoKKLrpBlpg5ETkYEew/uTZ14lQQRBrzPw GBfxvTXKCWiI2j5KFa/WKLSnmWJX0/98qpxW/IMXoXsA9iK4pnMKwAAAI B4Jrt6jmoLybpzgOPOI0DsJ7jQwWacinD0jliz8k+qzCpanhd2wH+DEdj/xO2sFR fnYlME3hmXoB+7NByVUtheVjuQ2CWhcGFIK m9tbuPC6DtXh1xxT0NJ7rspv Lgb0s6y/0tk+94ZP5RCoAtLZ7wirShy3/KJ4RE0y2SFZjIVjQ==</p> <p>Fingerprint : d9:d1:21:ad:26:41:ba:43:b1:dc:5c:6c:b9:57:07:6c</p> <p>SSH RSA or DSA keys can be generated by using the ssh-keygen command on a Unix system or with other publicly available utilities.</p>
Broadcom NIC link always stays up within the m8024-k status even after disabling server port through device manager or turning off server altogether.	<p>Low- This is works as designed and is necessary for new features for 12G.</p> <p>The Broadcom NIC 57810S never reports to the internal switch that the link is down because it needs the link to be up so that internal communications can continue with iDRAC and for other various components even after disabling the link on the server side.</p>

## Release 4.2.0.4

### Layer 2 – 4.2.0.4

#### 802.1x Authentication

Description	User Impact
Windows Vista® Authentication - The Windows Vista® client could fail to authenticate properly when the option to cache user credentials is selected.	<p>Low</p> <p>Workaround:</p> <ol style="list-style-type: none"> <li>1. In <b>Control Panel → Network Connections</b>, right-click on the desired <b>Local Area Connection</b> and select <b>Properties</b>.</li> <li>2. In the <b>Properties</b> window, select the <b>Authentication</b> tab.</li> <li>3. Deselect the checkbox for <b>Cache user information for subsequent connections to this network</b>.</li> <li>4. Click <b>OK</b>.</li> </ol>
The maximum number of 802.1x clients per port is 4.	<p>Low – most deployments will have at most 2 802.1x clients per physical port.</p> <p>Note: If running Release 5.1.0.1 or later version of firmware, the maximum number is 24.</p>
The maximum number of configurable traffic classes is 7.	<p>Low as most deployments use a single traffic class. Some limited deployments may use up to 3 traffic classes.</p>

#### MAC Filtering

Description	User Impact
Maximum number of unicast static filtering entries	The maximum number of unicast MAC and source port filtering entries is 20.
Maximum number of multicast static filtering entries	<p>The maximum number of multicast MAC and source port filtering entries is 20.</p> <p>The maximum number of multicast MAC and destination port filtering entries is 256.</p>
Static multicast MAC address table entries do not show with show command	<p>Users must enable MAC filtering using the <b>mac addr-table multicast filtering</b> command to enable filtering. Static MAC multicast forwarding entries will then be shown.</p>

## LACP

Description	User Impact
LAGs Supported	Number of LAGs supported: 128 total LAGs of which up to 72 may be dynamic LAGs. Up to 144 ports can be assigned to dynamic LAGs. The PCM8024 supports 12 LAGs with up to 24 ports assigned to dynamic LAGs.

## IGMP Snooping

Description	User Impact
No command to identify external IGMP querier	There is no specific command to identify an external IGMP querier. Administrators can use the <b>show ip igmp snooping querier detail</b> command or the <b>show ip igmp snooping querier vlan</b> command to display information about snooping queriers.

## Multicast VLAN Registration

Description	User Impact
MVR is not supported on LAGs	Use of MVR is restricted to physical interfaces.

## Layer 3 – 4.2.0.4

### IP MTU

Description	User Impact
IP VLAN MTU Support	Operators may see jumbo packets discarded when operating in a routed IP environment. <i>Administrators are advised when operating in a L3 routing configuration with jumbo frames to adjust both the link MTU and the VLAN IP MTU.</i>

### IPv6 MTU

Description	User Impact
IPv6 Fragmentation Support	<p>The switch is not fragmenting the datagram and forwards even when the IP MTU of the forwarding interface is set to a lower value (than the datagram size).</p> <p>IPv6 frames are not allowed to be fragmented. IPv6 frames forwarded in silicon can be up to the lesser of 9216 octets or the link MTU. These frames are forwarded by the switching silicon with no effect. If a frame exceeds the link MTU for a port, it is discarded silently.</p> <p>If a packet is sent to the CPU or originated on the CPU and it exceeds the IPv6 MTU, then the packet still will not be fragmented. Instead, an ICMP error message is returned to the sender. The maximum IPv6 MTU is 1500 bytes. <i>Administrators are advised that when operating in an L2 switching configuration with jumbo frames, to only adjust the link MTU and let the system automatically adjust the IPv4/ IPv6 MTU based on the link MTU.</i></p>

## VRRP

Description	User Impact
The maximum number of VRRP instances is 50.	Users can scale VRRP higher than previously.



# PowerConnect 8024/8024F/M8024/M8024-k/ M6220/M6348/7024/7048/7024P/7048P/7024F/7048R/7048R-RA Release Notes

## Management – 4.2.0.4

### CLI

Description	User Impact
radius-server mode commands do not have a "no" form.	Low - None of the commands in radius-server mode support a "no" form except for the <b>msgauth</b> command. To reset values to the default, delete the server entry and add it back.
The maximum command line length is 1536 characters.	Low - Entries greater than the maximum line length throw an error, e.g. using multiple interface range qualifiers.

### USB

Description	User Impact
Dir command can only address top-level directory on USB stick	Minimal – users can move files to top-level directory easily
Only FAT32 formatted devices are supported.	Minimal – FAT32 devices are the de-facto standard for flash devices
When multiple partitions are present on the flash drive, only the first partition is accessible.	Minimal – users will typically re-partition flash drives to maximize space.

### Web

Description	User Impact
Certain browser (IE) versions respond slowly when displaying large lists of information. In these cases, the “All” display selection may not appear (is disabled).	This behavior is a browser performance limitation. Users may select another supported browser to enable “all” display functionality. Alternatively, the user may utilize the page selector functions to display the appropriate page of information.
Certain browser (FireFox) versions automatically block popups after a certain number of displays within a session.	This behavior is a browser functionality issue. If popups are blocked, the web interface will display errors/information using alerts. Users can disable popup monitoring by browsing to about:config and set dom.popup_maximum to -1

### File Management

Description	User Impact
CLI Comment Character	The '!' indicates the beginning of a comment. All characters following the '!' will be treated as a comment (except when configuring a banner where the ! is accepted at the beginning of a line)

## Data Center – 4.2.0.4

### Interoperability

Description	User Impact
VLAN request/Notification counters are not incremented for priority tagged packets	Low – FIP sessions are established and are displayed in the show commands.  FIP snooping VLAN request or VLAN response counters do not increment when CNA sends priority tagged frames (i.e. VID 0). It is observed that certain CNAs sometimes sends FIP VLAN discovery frames as 802.1Q tagged frames with VID=0 and priority as FCoE priority. FSB snoops FIP packets which are classified to any of FCoE enabled VLANs. In this case, the default VLAN (1) and the configured FCoE VLAN. In general, VLAN request messages are exchanged

	<p>as untagged so gets associated with VLAN 1. In this case, the BROADCOM CNA sends priority tagged FIP frames (VID=0) which do not match the FSB snooping criteria because they do not get associated to any of the FCoE enabled VLANs hence FCoE VLAN Request/Notification counters are not incremented for priority tagged packets. These control frames are however forwarded to FCF by FSB in order to establish a successful session. FIP snooping bridge need to consider forwarding priority tagged FIP frames to FCF as well in order to interoperate with CNAs which could send priority tagged packets. The current FSB implementation does this already.</p>
Broadcom CNA only supports configuration of VLAN via VLAN Discovery process	<p>Low – Most users prefer automatic setup of CNAs</p> <p>The Broadcom CNA does not support manual configuration of VLAN. This means that customers who prefer to set up their FCoE network manually will not be able to do so if using BRCM CNAs.</p>
FIP snooping bridge does not forward the DCBX FIP tlv info from configuration source	<p>Low – No supported FCF supports this configuration option.</p> <p>While working with QLogic, it is found that CNA sends two TLVs concerning the FIP/FCoE traffic. It sends FIP TLV along with FCoE TLV with respective priorities - in this case same priority for both. Although, it is not a normal use case but can be used to have different treatment for control and data traffic. There can be a use case where host or FCF can choose to create different priorities for control (FIP) and FCoE data traffic.</p> <p>In cases, where FIP and FCoE use different priorities, it is expected that intermediate switches are configured to treat them accordingly. In cases where ports are configured in DCBX auto mode and configuration source carries two TLVs, one for FIP and other for FCoE with different priorities then it is expected that FSB/DCB should forward this information to downstream ports.</p> <p>The PowerConnect FSB implementation ignores the FIP TLV and does not forward this information to the peers. In such cases, Host will not know the special treatment or expected priority for FIP frames. Considering that slow protocol and this being a corner case situation, this can be a readme and documented in release notes.</p>
FIP Snooping Over Stack Results in eNode in Ethernet VLAN	<p>Low - When trying to accomplish FIP snooping over the stack, the eNode address is put in the wrong VLAN causing the connections to never occur. FCoE is not supported across the stacks so this is a non-issue.</p>

End of Release Notes